Claim Number: 880081

**Assessment Number: MW115954** 

**Version: MIWAY001/1** Printed: 8/24/2017 3:50 PM

#### Addresses

**Insured** 

Name: Mr Graham Wessel Sternberg

ID Number: 5601135133080

Address:

205 Southrand Road

Hazeldene - Germiston - Gtg

Post Code: 1401

Home Tel: 0118271080 Business Tel: 0118734332

Mobile Tel: 0833147409

Email Address: sternberg@mweb.co.za

Name: Miway Insurance (Alexandrea Abraham)

Address: Post Code:

Business Tel: 0119900855

Assessor

Name: Bhekani Ngcobo SP37106968

Address:

48 Sterling Road Kosmosdal Centurion Post Code:

Business Tel: 011 990 0514

Email Address: bhekaniN@miway.co.za

Repairer

Name: Bredren Auto Body SP25471202

ID Number: 25471202

Address: 70 Watt Street

Meadowdale - Germiston - Gtg

Post Code:

Business Tel: 0116229170

Email Address: admin@bredren.co.za

# **Summary Information**

Claim

Printed by: Keith Muller Authorisation Status:

Interim Work Provider: MiWay - Non Warranty

Policy Number: 25/7508

Other Reference: DVB:(PA) GERMISTON

Insured Amount: R0.00 Est repair cost: R0.00 Nο

Repairer Type:

Able to Authorise Repairs: Repairs Authorised: TBA Third Party: No Date of Accident: 8/21/2017

Repair Start Date: Repair End Date:

Estimated Repair Time: 10.0

Actual Repair Time: Parts Ordered: Parts Ordered Date: Hire Car Start Date: Hire Car End Date:

Under Warranty: No

Warranty Expiry:

#### **Vehicle Details**

**Vehicle** 

Manufacturer: TOYOTA Model/Sub Model: Etios/XS Model Sheet Number: **YET 15** Engine Number: **TBA** Registration Number: BX64SZGP

VIN Number: MBJB29BT300041780

Registration Month: January Registration Year: 2012

**Model Specs** 

FROM 07/2012 AIR CONDITIONING CENTRAL LOCKING **OUTER MIRROR PAINTED** SUN VISOR MIRROR ANTI-THEFT ALARM EQU 1496CCM 66KW

5-SPEED GEARBOX

**Full Report** 

Claim Number: 880081

**Assessment Number: MW115954** 

**Version: MIWAY001/1 Printed: 8/24/2017 3:50 PM** 

Odometer: Not Known POWER STRG ELECTRIC Odometer Reading Type: Unknown ANTI LOCK BRAKES Colour: Silver TYRES 175/65 R 14..R Paint Code: MET WHEEL 5 J X 14 VIN search performed: No PRODUCTION INDIA

4 DOOR

GRILLE IN VEH COLOUR 2 COAT METALLIC PRE PAINT OFF VEHIC WATER BASED PAINT

#### **Vehicle Condition**

**Vehicle Status** 

Pre-Accident Condition: Fair Severity of Impact:

Steering: Satisfactory Vehicle Status on Inspection:

Brakes Pedal Travel: Satisfactory Date of Inspection: 8/23/2017


Place of Inspection:

Pre-Accident Damage: NONE NOTED

Tyres Condition: Fair

Tread Depth LHF: Tread Depth RHF: Tread Depth RHR: Tread Depth RHR:

Damage Areas:



Direction of Impact:

**Full Report** 

Claim Number: 880081

**Assessment Number: MW115954** 

**User Status:** Printed: 8/24/2017 3:50 PM **Version: MIWAY001/1** 

Cost	Summary	
------	---------	--

Total Deductions		0		
Repair Cost Excl VAT Total Deduction:		0 0		
After Deduction -	Grand Total Exc VAT		0	
	VAT 14 %		0	
	Repair Cost Incl VAT		0	
	Deduction for Excess		TBA	
	Waste Collection Total		R0.00	

# **Repair Information**

**PARTS** 

G.No.	Description	Part Number	Bet.	Supplier Name	Price
281	FRONT BUMPER	52119 0U902			0
317	L/F BUMPER BRACKET	52536 0D050			R251.28
410	RADIATOR GRILLE	53111 0D904			0
561	LEFT HEADLAMP CPL	81170 0D422			0
741	L/FRT FENDER	53812 0D060			0
841	L/FRT FENDERLINER	53876 0D140			0
I: Iden U: Use	t Part d OEM Parts	Sub Total			

A: Alternative Parts O: Other Parts S: Salvage Parts F: Final costing

C: Contract Supplier

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Total Parts** 

#### **AUDA PARTS**

G.No. De	scription	Supplier Part Number	Supplier Name	Supplier Price

0

**Full Report** 

Price Valid: 8/1/2017

Claim Number: 880081

**Assessment Number: MW115954** 

**Version: MIWAY001/1 Printed: 8/24/2017 3:50 PM** 

LABOUR	Time Basis 10 WU = 1 HR. Price/CL 1 = R265.00/HR Price/CL 2 = R265.00/HR Price/CL 3 = R265.00/HR Price/CL 5 = R265.00/HR			R265.00/HR R265.00/HR
Repair / Guide Nu	mber Repair Details	CL	WU	Cost Price
810151A	ADJUST HEADLAMP	1	3.0	R79.50
531011)	REPLACE L/FRT FENDER	1	7.0	R185.50
,	(BUMPER AND HEADLAMP REMOVED	D)		1120100
	INCLUDES:R + R L/FRT FENDERLIN			
	AND			
	R + R NECESSARY ATTACHMENTS			
520011	RENEW FRONT BUMPER	1	7.0	R185.50
	INCLUDES: $R + R$ FRONT BUMPER,			
	RADIATOR			
	GRILLE AND NECESSARY ATTACHED			
	PARTS			
810051)	R + R LEFT HEADLAMP	1	2.0	R53.00
	(BUMPER REMOVED)			
	DOES NOT INCLUDE: ADJUST			
0.474	HEADLAMP		<b>=</b> 0.4	2422 22
0471	REPAIR BONNET	1	5.0*	R132.50
PAINT W		Time Basis 10 W	U = 1 HR. Price =	-
Guide Nu	mber Description - 2 COAT METALLIC - PRE PAINT OFF VEHIC - WATER BASED PAINT	:	WU	Cost Price
741	L/FRT FENDER NEW PART PAINTING		9.0	
281	FRONT BUMPER NEW PART PAINT K		13.0	
410	RADIATOR GRILLE NEW PART PAIN	=	4.0	
471	BONNET REPAIR PAINTING <50%		13.0	
		00 Price/HR	20.0	Cost Price
	TIME(PAINT) Preparation Main Work Plastic		39.0 5.0	
	Preparation Main Work Plastic  Preparation Main Work Metal		25.0	
	Piepaiation Main Work Metal		23.0	
	Total Work Units (10WU/HR)		69.0	
	Total Paintwork Labour		6.9 HRS.	0
	. Otal i allitiroin Laboui		313 11131	3

**Full Report** 

Claim Number: 880081 Full Report
Assessment Number: MW115954 User Status:

Version: MIWAY001/1 Printed: 8/24/2017 3:50 PM

MATERIAL COST - PAINT  New Part Painting  New Part Painting - Plastic K1R  Material-Constant Main Work Metal  Repair Painting  Material-Const Main Work Plastic		Cost Price R471.46 0 R335.66 R528.90 R63.14
Total Excluding Pearlescent Uplift Pearlescent Uplift @ 0.0%		0 R0.00
Total Paint Material Cost		0
Final Calculation		8/24/2017
Parts	0	
Total Parts		0
Labour Time Basis 10 WU = 1 HR Total CL 1 24 WU X R265.00/HR  Total Labour	R636.00	R636.00
Paint Work  Labour Costs  Material Costs  Total Paint  Repair Costs Excludes VAT  VAT @ 14 %	0 0	0 0 0
Repair Costs Includes VAT		0
Deductions % Settlement Pre VAT (10.00 %) Total Deductions	0	0
Grand Total Excludes VAT (After Deduction) VAT @ 14 %		0
Grand Total Includes VAT (After Deduction)		0 TBA

Claim Number: 880081

**Assessment Number: MW115954** 

**Version: MIWAY001/1** Printed: 8/24/2017 3:50 PM

### **Active Box Codes**

2	14.00	Fixed Allowance - VAT Percentage
28	1.00	Sundry Parts - % of Labour Total
51	100.00	Paint Materials - AZT/Schwacke Painting
88	10.00	Deductions / Excess - Early Settlement excl. VAT as %

# **In-Active Box Codes**

93	0	Sundry Parts - Set as Upper Liimt

#### **Assessment Notes**

Special Instructions: . Incident Desc:I was coming down road, went to get medicine for my husband. I was at work and went to the Pharmacy, Primrose? Ackermans Pharmacy.

Guy ran across parking car and there was a parking and empty space and a parking so I thought I better take first parking or I would knock him. With that I think I had gone too far swung hit back right back corner side of Peugeot. Security guard came and said lady is in the pharmacy, I?m going to get medicine? if you can find the lady and we can meet outside and that?s what happened.

We exchanged information, I reported it this morning.

No Injuries.

My car bumper and left part panel will have to be replaced. Her car is not damaged, just a scratch.

Sum Insured: 91400. Car Make: TOYOTA. Car Model: ETIOS 1.5 Xs. Car Year: 2012

**Sum Insured Type: RETAIL** 

**Policy Type: Personal Insurance** 

Salvage Estimate: R40,533

Life Status: 1 New Licence Disc Expiry: 31/MAY/18

Vin No: MBJB29BT300041780 Engine No: 2NRV059632

**Full Report**