

AS15-3 PinOut



1	2	3	4	5	6
Motor A	GND	12V Out	5V	RS232 TX	RS232 RX
12V In	GND	Motor B	WAS	Str Switch	Wrk Switch
12	11	10	9	8	7