

# SERVICE REPORT



SRV2-TEST short - Projector not powering on in Training Room 2

RAA

Job: SKS-90001

Date: 23/09/2026

|            |                                     |          |                                             |
|------------|-------------------------------------|----------|---------------------------------------------|
| CLIENT     | RAA                                 | CONTACT  | Sarah Nguyen<br>sarah.nguyen@example.com.au |
| SITE       | 1 King William St, Adelaide SA 5000 | ROOM     | Ground · Training Room 2                    |
| EQUIPMENT  | Epson EB-L630U                      | CONTRACT | Ad-hoc service                              |
| TECHNICIAN | Mark Stow                           | ATTENDED | 23 Sept 2026<br>Ref PO-1001                 |

## Issue reported

The projector in Training Room 2 would not power on from the wall panel.

## Work carried out

Found the power board under the lectern switched off. Switched it back on, powered the projector up from the panel and confirmed the image and audio were working.

### Advice for the client

- Label the lectern power board so it isn't switched off by cleaners.

#### TECHNICIAN

Mark Stow

SKS Technologies

23 Sept 2026

#### CLIENT ACKNOWLEDGEMENT

Name

Date

