## **BOTS 'N' DOGS CHARGING PROCEDURES**

Lithium Polymer

DON'T leave LiPo batteries charging overnight.

are interchangeable between BC6 and BC6-DX. Feel free to swap as needed to use BC6-DX presets. Adaptors from the charge balance leads (3 or 4 pin white/black plug on the battery) to the LiPo chargers

If the voltage across all cells is close to or under the discharged voltage level, the battery might be lucas.delagarza@ll.mit.edu if this happens. damaged. DON'T charge, discharge, or use damaged LiPo batteries. Email Lucas at

	-		-			
	800	1300	2200	3700	(mA*hrs)	Capacity
None	[3]	[2]	[1]	[0]	preset	BC6-DX
2	ω	w	ω	ω	(S)	Cells
<0.4	<1.0	<2.0	<3.0	<3.0	current (A)	Max charge
6.8	10.2	10.2	10.2	10.2	3	Discharged voltage
8.4	12.6	12.6	12.6	12.6	3	Charged voltage

- ب BC6 or BC6DX charger. Feel free to swap charge balancing lead adaptors between the two Connect output leads (red plug) and charge balancing leads (3 or 4 pin white or black plug) to
- Select "Balance" (charge).
  Scroll to correct charge pr
- Scroll to correct charge preset (BC6DX) or set battery parameters manually (BC6)
- Hold "enter" to start. Either charger should beep once charging begins and ends.
- Disconnect both sets of leads once charging is complete.

## 12V Lead-Acid

in parallel to the exposed terminals inside the rover. Charge onboard the rovers from the f 1. V source charger. External batteries may be connected with clips

EEEpc batteries

Charge from normal wall wart.