



A3

.param R_s=50 R_ell=450 L=1u C_a=25n C_b= $\{1/((2\pi f_s)^2 L)\}$ f_s=5e6 S_v=4e-18

A4

.param V_DC = 5 sigma_V=0.05 sigma_R1 = 0.02 sigma_R2=0.01 a= $\{2\pi \cdot 1e6\}$