Cutting Data Recommendations

Material				415	425	435
				Feed mm/rev.		
				0.4-0.6-0.8	0.4-0.6-0.8	0.6-0.8-1.2
CMC No.	Туре	k _{s0.4} N/mm²	Hardness HB	Cutting Speed m/min.		
	Non Alloyed Steel					
01.1	C=0.15%	1900	90-200	365-310-320	315-265-205	225-200-160 195-170-140
01.2	C=0.35%	2100	125-225	315-265-230 300-250-220	275-230-175 255-215-165	185-160-130
01.3	C=0.70%	2000 2300	150-250 180-275	270-230-195	230-195-150	165-145-120
01.4	High Carbon Steel Hardened &	2300	100-275	270-200-100	200 100 100	
01.5	Tempered	2500	250-450	230-190-165	195-165-125	140-125-100
	Low Alloy Steel	2000	200 100			
02.1	Non-Hardened	2100	150-260	270-230-200	200-165-130	135-115-95
02.2	Hardened	2750	220-450	155-120-115	110- 95- 75	75- 65-55
	High Alloy Steel				475 450 445	110- 95-75
03.11	Annealed	2500	150-250	235-195-170	175-150-115 75- 65- 50	60- 50-40
03.21	Hardened	3750	250-350	120-	/5- 65- 50	00- 30-40
	Steel Castings	1000	-225	230-200-	165-140-115	120-110-90
06.1	Non-Alloyed	1800 2200	150-250	150-130-	105- 90- 75	80- 65-60
06-2/3	Low & High Alloyed	2200	150-250	100 100		

Coromant Insert Programme

T-MAX P	415	425	435
SNMM 12 04 04-71 SNMM 12 04 08-71 SNMM 12 04 12-71 SNMM 15 06 04-71 SNMM 15 06 08-71 SNMM 15 06 12-71 SNMM 15 06 16-71 SNMM 19 06 16-71			
CNMM 12 04 04-71 CNMM 12 04 08-71 CNMM 12 04 12-71 CNMM 16 06 04-71 CNMM 16 06 08-71 CNMM 16 06 12-71 CNMM 16 06 16-71 CNMM 19 06 12-71			

CNMM T-MAX P	415	425	435
TNMM 11 03 02-71 TNMM 11 03 04-71 TNMM 16 04 04-71 TNMM 16 04 12-71 TNMM 22 04 04-71 TNMM 22 04 08-71 TNMM 22 04 08-71 TNMM 22 04 12-71 TNMM 22 04 12-71 TNMM 27 06 12-71			

TNMM T-MAX P	415	425	435
SNMM 15 06 24-31 SNMM 19 06 16-31 SNMM 19 06 24-31 SNMM 25 07 24-31 SNMM 25 07 32-31 SNMM 25 09 24-31 SNMM 25 09 32-31 CNMM 19 06 16-62 CNMM 19 06 24-62 CNMM 25 09 24-62 CNMM 25 09 32-62			