

## Robert Williams <williams.a.robert@gmail.com>

## **Drawings Required for Quote**

6 messages

Robert Williams < williams.a.robert@gmail.com >

To: ml@bluechipgroup.com.au

27 February 2018 at 15:10

Hi John,

I just phoned in regards to seeking a quote. I would like to know what drawings files are required or would a 3-D model suffice.

Also if you could give me a general lead time to work on.

Regards,

Robert

Mitch <ml@bluechipgroup.com.au>

27 February 2018 at 15:13

To: Robert Williams <williams.a.robert@gmail.com> Cc: John Crockett <john@bluechipgroup.com.au>

Hi Robert,

If you have a PFD we can quote off that or most types of 3D models like a .step is fine.

Regards,

Mitchel Liddell Manager Bluechip CNC Machining 10 Egmont Road Henderson WA 6166 (08) 9437 6070 0430 331 139 ml@bluechipgroup.com.au www.bluechipgroup.com.au

From: Robert Williams

Sent: Tuesday, February 27, 2018 3:10 PM

To: ml@bluechipgroup.com.au

Subject: Drawings Required for Quote

[Quoted text hidden]

Robert Williams < williams.a.robert@gmail.com> To: Mitch <ml@bluechipgroup.com.au>

8 May 2018 at 10:58

Hi Mitchel,

I have some machining I need a price on. If I could get separate price on each job as we are still not sure if we are getting it machined or manufacturing in house.

The first job is the following pdf drawings and step file I need 4 of each part all manufactured from Aluminium 6061

The rest of the files will follow

Cheers,

| 2018  | Gmail - Drawings Required for Quote |                     |
|---|-------------------------------------|---------------------|
| Robert  |                                     |                     |
| [Quoted text hidden]  |                                     |                     |
| 6 attachments   |                                     |                     |
| BearingHousing_Base.pdf   |                                     |                     |
| BearingHousing_Base.stp   |                                     |                     |
| BearingHousing_JackPlate.pdf 240K   |                                     |                     |
| ☐ BearingHousing_JackPlate.stp<br>41K   |                                     |                     |
| ☐ BearingHousing_Plate.stp<br>27K   |                                     |                     |
| BearingHousing_Plate.pdf 198K   |                                     |                     |
| Robert Williams <williams.a.robert@gmail<br>o: Mitch <ml@bluechipgroup.com.au></ml@bluechipgroup.com.au></williams.a.robert@gmail<br> | .com>                               | 8 May 2018 at 11:03 |
| The next job I need 4 of the cheek plate 4 of the cheek plate mirror Manufactured from Aluminium 6061                                 |                                     |                     |
| On 27 February 2018 at 15:13, Mitch <ml< td=""><td>@bluechipgroup.com.au&gt; wrote:</td><td></td></ml<>                               | @bluechipgroup.com.au> wrote:       |                     |
| 3 attachments   |                                     |                     |
| CHEEKPLATE.pdf 99K  |                                     |                     |
| CheekPlate.stp<br>165K  |                                     |                     |
| CheekPlate_Mirror.stp<br>170K   |                                     |                     |
| Robert Williams <williams.a.robert@gmail<br>o: Mitch <ml@bluechipgroup.com.au></ml@bluechipgroup.com.au></williams.a.robert@gmail<br> | .com>                               | 8 May 2018 at 11:08 |
| I need 8 of the hub flange and 24 of the re   | ollers all made from Aluminium 6061 |                     |
| Cheers,<br>Robert   |                                     |                     |
| On 27 February 2018 at 15:13, Mitch <ml< td=""><td>@bluechipgroup.com.au&gt; wrote:</td><td></td></ml<>                               | @bluechipgroup.com.au> wrote:       |                     |
| 3 attachments   |                                     |                     |
| Hub flange.pdf<br>27K   |                                     |                     |
| Hub flange.stp  |                                     |                     |

□ roller 8-19-6 bearing.stp <sub>14K</sub>

ml@bluechipgroup.com.au <ml@bluechipgroup.com.au> To: Robert Williams <williams.a.robert@gmail.com>

10 May 2018 at 13:18

Good afternoon Robert,

Please find attached quote for machining as requested.

Regards,

Mitchel Liddell Manager Bluechip CNC Machining 10 Egmont Road Henderson WA 6166 (08) 9437 6070 0430 331 139 ml@bluechipgroup.com.au www.bluechipgroup.com.au

From: Robert Williams

Sent: Tuesday, May 08, 2018 11:08 AM

To: Mitch

Subject: Re: Drawings Required for Quote

[Quoted text hidden]

