

Task 3: ADC

3_ADC.ino

```
1 // Potentiometer is connected to GPIO 34 (Analog ADC1_CH6)
2 const int potPin = 34;
3
4 // variable for storing the potentiometer value
5 int potValue = 0;
6
7 void setup() {
8     Serial.begin(115200);
9     delay(1000);
10 }
11
12 void loop() {
13     // Reading potentiometer value
14     potValue = analogRead(potPin);
15     Serial.print("potValue: ");
16     Serial.println(potValue);
17     delay(50);
18 }
19
```