

English | 中文版

Introduction	Contest Schedule	Contest Structure	Contest Recap	Contact Information
Online Tes	st			
The examina	tion countdo	own:00 : 34 : 2	29	
(Please dor	n't refresh the	e browser!)		
Your Name:	Dhairya Shah			
1. Multiple Ch	oice Question	ns (choose one	that applies)
1. If a custome	er uses a DOP-	B07E415 Series	HMI and wou	uld like to replace it with a new DOP-100 of the same dimensions for mounting
which of the fo	ollowing mode	ls is suitable?		
O DOP-107CV	,			
O DOP-110WS	5			
ODOP-107EV				
O DOP-107W	V			
2. Which of the	e following scr	ipt languages d	loes the Supe	ervisory Control and Data Acquisition (SCADA) software adopt?
VBScript				
O The C Progr	amming Langı	uage		
O C++				
O An assembl	y language			
3. How many I	ines can a hun	nan-machine in	terface show	in a line chart of historical data?
○ 128				
○ 30				
1 6				
O 60				
4. How many h	noming modes	does the PLC-	Based Motion	n Controller DVP15MC11T support?
○10				
○ 20				
O 24				
3 5				
5. What does	"1" stand for	in the Buffer M	1ode?	
Wait				
○Interrupt				

O Blend with low velocity
O Blend with high velocity
6. Which of the following AC Motor Drive Series communicates via CANopen and Modbus-RTU communication protocols?
● MS300
○ MH300
○ ME300
7. Which of the following is correct about the overload capacity for the AC Motor Drives MH300 and MS300 Series?
○ 150% 60s,200% 10s
○ 150% 60s, 200% 30s
● 150% 60s, 200% 3s
○ 120% 60S, 160% 3S
8. Which of the following AC Motor Drives comes with an LCD panel?
○ c200
○ ME300
○ MS300
● MH300
9. Which of the following model names is a Delta pulse type motion control card?
O PCI-L221-B1D0
© PCI-DMC-B01
O PCI-M324-F1D0
○ PCI-3232
10. Which of the following interfaces is not built-in on the MP1-A12D-1503DG Series PC-based panel motion controller?
O RS232
○ RS485
● HDMI
○ EtherNET
11. What is the maximum number of Delta CNC controllers' serial I/O terminals?
○ 64in/64 out
○ 128in/128out
256in/256out
○ 96in/96out
12. Which description of the NC-EIO-R3216 High-speed Serial I/O for Delta CNC Controller is correct?
Relay type; 16 points output
O Relay type; 32 points input

Optical coupler type; 16 points output
Optical coupler type; 16 points input
13. What is the protective height of the Area Sensor AS-BA010?
○ 800mm
400mm
○ 320mm
○ 160mm
14. What is the repeatability of the Laser Displacement Sensor LD-040N-C2B?
2μm
○ 5µm
○ 15µm
○ 0.1mm
15. How many extended axes can the Robot Controller DCS support in addition to the 4 axes of the SCARA Robot DRS Series?
01
O ₂
O ₄
● 6
2. Multiple Selection Questions (select all that apply)
16. Which of the following patterns does Delta's DIAView SCADA System present?
✓ 2D / 3D pie charts
☑ Bar charts
✓ Line charts for real-time data
✓ Line charts for historical data
17. Which of the following control modes does the AC Motor Drive MH300 Series support?
✓ VF
✓ SVC
✓ FOC
✓ TQC
18. What are Delta's major motor drives under 7.5 kW?
✓ MS300
✓ ME300
✓ CH2000
✓ C2000
19. What are the methods for Delta CNC controller to upload machining programs?
✓ CF card

- ✓ USB
- Internet
- □ RS232
- 20. Under what mode(s) can the Handheld Teaching Pendant control Delta's robots?
- ✓ T1 mode
- ✓ T2 mode
- ✓ AUTO mode
- ✓ All of the above

Submit

© Delta GreenTech (China) Co., Ltd. All Rights Reserved.