PC3860M1 to PC3860M2: Modifications

- 1. Add a 4K7 pull-up resistor from pin 1 of U20, 21, 22, 23, 24, 25, 26, 27 because the output of the comparators is open collector.
- 2. Removal of two D-type latches (U76 and U77) as these cause false triggers and connect event lines to where the outputs of the latches went.
- 3. Change U83 and U84 to 74LVC equivalents so they can be driven by 5V.
- 4. Swap over TX and Rx signals on the ESP32 module so that they can talk to the TEENSY modules.
- 5. Remove R67 through R74. These were feedback resistors designed to give some hysteresis to the event comparator but this can recharge the peak hold capacitor.
- 6. Change power socket to two pin version of the LED drive plugs.