






## **ZIO CONNECTORS**














## **TESTPOINTS**






LED

## TORQUE SENSOR CONNECTOR



The output Vref is a constant 2.5V output and represents the virtual zero point for direct +/- torque measurement.

## **PWM BRAKE CONTROLLER**



Sheet: /Connectors/ File: connectors.kicad\_sch

 Title: STB

 Size: A4
 Date:
 Rev:

 KICad E.D.A. kicad (6.0.2-0)
 Id: 2/4

