Claim Management Panel

Supplier: **AVO Carbon France (NMAP551841)**

Type: **I - Information**

Problem description: **double DMC on brush card**

Claim reference: **NMAP/551841/2/2024/1666**

Settings

C2/C3 REMINDER PANEL

(QR) D2-D3 Defualt Due Date :	**2/9/2024**	10:19:41 AM (your local time)	D2-D3 Revised Due Date:	(QR) D2-D3 Actual Date:	**3/13/2024**	3:05:40 PM (your local time)	(QR) D2-D
D4 Default Due Date :	**2/13/2024**	10:19:41 AM (your local time)	D4 Revised Due Date :	D4 Actual Date :	**3/20/2024**	7:49:10 AM (your local time)	D
D5-D6 Default Due Date:	**2/22/2024**	10:19:41 AM (your local time)	D5-D6 Revised Due Date:	D5-D6 Actual Date:	**4/1/2024**	9:05:38 AM (your local time)	D5-D
D7-D8 Default Due Date:	**2/22/2024**	10:19:41 AM (your local time)	D7-D8 Revised Due Date C2/C3:	D7-D8 Actual Date:	**4/4/2024**	7:31:03 AM (your local time)	D7-D



NOTIFICATIONS SENT

0 Result(s)

NIDEC APPROVALS & REFUSALS HISTORY

Steps approved

Step	Date of validation	User name
D8	4/4/2024	Marwen Haggui
D1	2/8/2024	Dominik Dudek
D4 Validation	3/20/2024	Dominik Dudek
D2	3/20/2024	Marwen Haggui
D2-D3 Validation	3/19/2024	Dominik Dudek
D3	3/20/2024	Marwen Haggui
D4	3/20/2024	Marwen Haggui
D5	4/1/2024	Marwen Haggui
D5-D6 Validation	4/3/2024	Dominik Dudek
D6	4/1/2024	Marwen Haggui
D7	4/4/2024	Marwen Haggui
D7-D8 Validation	4/4/2024	Dominik Dudek
8D closed	4/8/2024	Dorota Siekaniec
8D Closing	4/8/2024	Dorota Siekaniec
Creation	2/8/2024	Dominik Dudek

15 Result(s)

Steps rejected

0 Result(s)

Forum

Filter

Keywords:

0 Result(s)

Quick Response (D1-D3)

ALERTS

-Component without PPAP

Plant issued a claim:	NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.	Supplier:	**AVO Carbon France (NMAP551841)**	Date of Claim:	**2/8/2024**
Customer Contact:	**Dudek Dominik**	SAP Vendor Code:	**551841**	Date of QR:	**2/9/2024**
Claim reference:	**NMAP/551841/2/2024/1666**	Author:	**DUDEK Dominik**	Update of QR:	**2/9/2024**
Status:	**Closed**	Type:	**I - Information**		
		CLAIM PPM:	0.00		

D1-D3 evaluation score: 22

D1. Description of the problem

1.A WHAT IS THE PROBLEM ? USE 5W+2H TO DESCRIBE WHAT IS THE CURRENT SITUATION.

Problem description:	**double DMC on brush card**	What happened?:	**double DMC on brush card**
Part Number & Description:	Brush mounting plate assy (503-772-99-99)	Why is it a problem?:	**double DMC on brush card**
Traceability of nok parts:	**ASN180383229**	When did it happen? :	**2/6/2024** 12:00:00 AM (your local time)
Recurrence:	**No reccurent defect**	Who detected it?:	**operator**
Defect S/R:	**No**	Where was it detected? :	**CM4 line**
		How was it detected?:	**visually**
		How many parts ?:	**1.00**

nok part picture / sketch:

ok part picture / sketch:

Other files::

1.B SUPPLIER PROBLEM SOLVING TEAM

Supplier Team

Add an existing contact:

Name		Contact	Email	Phone	Cell Phone	Fax	Position	Profile	Status
Haggui Marwen		• marwen.haggui@avocarbon.com	marwen.haggui@avocarbon.com	+21656057189	+21656057189		Customer Quality	Supplier	Active

NidecTeam

Contact	Email	Profile
DUDEK Dominik	dominik.dudek@nidec-ma.com	{profile} Local Quality (Local SQE) (Full) (Claim)

1.C TOOL TO USE (DEFINED BY NIDEC)

Ishikawa: ☑ FTA: ☑ 5 Whys : ☑ LLC: ☑ Audit: ☐ Other: ☐

1.D PROBLEM DESCRIPTION FROM SUPPLIER / FIRST ANALYSE OF PROBLEM / POTENTIAL ROOT CAUSES

Problem description from Supplier: **double DMC on brush card**

Samples of nok parts required at supplier location: ☑ Express shipping supplier account: **regular truck**

D2. Risk on similar products and processes

Can this defect happen on similar parts?: Comments (compulsory if yes): **ALL CM4 reference**

Other family product: ☑ Component:
Brush mounting plate assy (503-772-99-99)
Brush mounting plate assy (503-773-99-99)
Brush mounting plate assy (503-774-99-99)
Brush mounting plate assy (503-775-99-99)
Brush mounting plate assy (503-852-99-99)
Brush mounting plate assy (503-989-99-99)
Brush mounting plate assy (503-991-99-99)

Other machine: ☐

Other tooling: ☐

Other Nidec plants: ☐

Other: ☐

D3. Containment

WHAT ARE THE ACTIONS TO DETECT ALL NON-CONFORMING PARTS IN THE PROCESS FLOW?

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Delivery note and batch #	Responsible
Parts at Nidec plant	110.00	0.00	1.00			
Parts at Nidec logistics platform	0.00	0.00	0.00			
Parts at Nidecs customer (C1 claim)	0.00	0.00	0.00			

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Responsible	Delivery note and batch #
Parts in transport	2,940.00	2,940.00	0.00	2/10/2024	Supplier	first batch week w06
Parts at supplier / supplier platform	0.00	0.00	0.00			
Parts at sub-supplier	0.00	0.00	0.00			
Other Nidec plant/s	0.00	0.00	0.00			

4 Result(s)

How are the ok parts identified?: **100% regarding double DMC on brush card**

First contained shipment information: **first batch secured delevered Week 06**

How are the ok paletts identified?: **Orange NIDEC identification**

How are the ok parts identified? ::

WHAT ARE THE IMMEDIATE ACTIONS TO PREVENT PRODUCTION/DELIVERY OF NOK PARTS?

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
Express delivery to Nidec to avoid production stop				
Nidec suspect stocks to be sent to supplier				

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
QRQC meeting	Required	Supplier	2/9/2024	2/9/2024

1 Result(s)

D4-D8

ALERTS

-Component without PPAP

Plant issued a claim:	NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.	Supplier:	**AVO Carbon France (NMAP551841)**	Creation Date:	**2/8/2024**
Customer Contact:	**Dudek Dominik**	SAP Vendor Code:	**551841**	Date of QR:	**2/9/2024**
Claim reference:	**NMAP/551841/2/2024/1666**	Created by:	**DUDEK Dominik**	Update of QR:	**2/9/2024**
Status:	**Closed**	Type:	**I - Information**	Date of D4-D8:	**3/20/2024**
		CLAIM PPM:	0.00		
D4-D8 evaluation score:	75			Update of D4-D8:	

D 4. Root cause of occurrence

Work out the root causes using first Ishikawa, then FTA and finally 5 why's (Tools to use chosen by Nidec).

ROOT CAUSE OF OCCURRENCE

standard not exist :
There is no specific standard for operation re-testing.

HOW WAS THE DEFECT REPRODUCED ?

the setter mixed between the printer device and the reader device

Attachment:

D 5. Root casue of non detection

ROOT CAUSE OF NON DETECTION :

the setter must disactivate the printer device and keep the reader device activated.

Attachments:

D 6. Countermeasure to non detection and occurrence

6.A ACTIONS FOR OCCURENCE

Action	Responsible	Date Plan	Date Clos.	Attachments Please click 'Save' to activate attachment fielc
Standard of re-test parts operation	hamza	3/5/2024	3/5/2024	
Training session for Quality agent and supervison and setter reading the new standard	training departement	3/5/2024	3/5/2024	

2 Result(s)

6.B ACTIONS FOR NON-DETECTION

Action	Responsible	Date Plan.	Date Clos.	Attachments Please click 'Save' to activate
Specific instruction of vision tester for operation re-test parts (mentioned the printer device must be disactivate and the reader must be activate)	marwan haggui	3/6/2024	3/6/2024	instruction relecture update

Training session of final opeartor for defect double DMC	training departement	3/6/2024	3/6/2024	

2 Result(s)

D 7. Effectiveness of action plan

7A ACTIONS TO CHECK EFFECTIVENESS ACTIONS FOR OCCURENCE

Action	Responsible	Date Plan.	Date Clos.	Attachments Please click 'Save' to activate attachment field
The first batch was secured and delivered Pallet Number : 037 batch number 240307	haggui marwan	4/1/2024	4/1/2024	

1 Result(s)

7B ACTIONS TO CHECK EFFECTIVENESS ACTIONS FOR NON-DETECTION

Action	Responsible	Date Plan.	Date Clos.	Attachments Please click 'Save' to activate attachment field
Station audit on the electrical station during the re-test operation	haggui marwan	4/1/2024	4/1/2024	EOL test audit station.pdf

1 Result(s)

D 8. Action(s) to prevent recurrence

8.1 DO FOLLOWING DOCUMENTS REQUIRE AN UPDATE ?

Name of the document	Responsible	Date Plan	Date Clos.	Attachments
PFMEA				
Control Plan				
Work instruction	haggui marwan	3/6/2024	3/6/2024	instruction_relecture_updated (1).pdf
Control instruction				
Procedure	hamza	3/5/2024	3/5/2024	
Control gage				
Maintenance instruction				
Lesson Learned Card				
Other	training departement	3/6/2024	3/6/2024	
Other	training departement	3/5/2024	3/5/2024	
Other	haggui marwan	4/1/2024	4/1/2024	EOL_test_audit_station (1).pdf

8.2 GENERALIZATION OF COUNTERMEASURES TO SIMILAR LINES/ PRODUCTS

8.3 AUDIT DONE BY SUPPLIER (IF REQUIRED)

8D Audit required?:

Date of audit done by supplier:

Supplier Audit Results:

Supplier Audit Comment:

8.4 VALIDATION OF 8D CLOSURE FROM SUPPLIER MANAGEMENT

Name: **haggui marwan**

Supplier Management Position: **Quality engineer**

Date of validation of 8D closure from supplier management: **4/4/2024**

Closure of 8D from Nidec

Chargeback:

Efficiency of 8D proven:

Nok stocks at zero:

8D eval value (%): **100.00**

Date of closure:

Supplier 8D Report Evaluation Sheet

EVALUATION

D#	Discipline	Unsatisfactory/Not OK	Acceptable	Requirements fulfilled
D1B	Supplier problem solving team	☐ Minimum standard not reached	☐ - Champion named - Cross functional team - Champion contact data available	☑ - Names and all functions of the functional team are available
D1D	Problem description from supplier / first analysis of the problem / potential root cause	☐ Minimum standard not reached	☐ - Clear and complete description of potential root cause - Express shipping account avaliable	☑ - Relevant attachments (e.g. pi possible root cause provided
D2	Risk on similar products and processes	☐ Minimum standard not reached	☐ - Risk analysis for simmliar products/lines performed and adequate information provided	☑ - Information about risk at oth numbers/family provided
D3	Containment	☐ Minimum standard not reached	☐ - Overview of actions in all material postions (e.g. in transit) available - Effectivity confirmed	☑ - Proof of containment effectiv relevant documentation availa
D4	Root cause of occurrence	☐ Minimum standard not reached	☐ - Root cause identified - Quality tools marked (Ishikawa, FTA, 5 Why's) used for occurence - Appropriate methods applied	☑ - Proof for actions to reproduc (e.g. pictures, records from pro provided
D5	Root cause of non detection	☐ Minimum standard not reached	☐ - Root cause identified - Quality tools marked (Ishikawa, FTA, 5 Why's) used for non-detection - Appropriate methods applied	☑ - Proof for actions to reproduc (e.g. pictures) provided
D6a	Actions for occurence	☐ Minimum standard not reached	☐ - Complete list of corrective actions per identified cause with verification - Timline for permanent actions	☑ - Announced deadlines for clos respected
D6b	Actions for non-detection	☐ Minimum standard not reached	☐ - Complete list of corrective actions per identified cause with verification - Timline for permanent actions	☑ - Announced deadlines for closi respected
D7a	Actions to check effectiveness actions for occurence	☐ Minimum standard not reached	☐ - Complete list of permanent corrective actions with details - Verification of actions (statistics)	☑ - Containment actions success after introduction of permane action
D7b	Actions to check effectiveness actions for non-detection	☐ Minimum standard not reached	☐ - Complete list of permanent corrective actions with details - Verification of actions (statistics)	☑ - Containment actions success after introduction of permane action
D8.1	Do following documents require an update ?	☐ Minimum standard not reached	☐ - Documented lessons learned - Relevant documents updated (FMEA, Control Plan, etc.)	☑ - Analysis of generalization of countermeasures to similar lin performed
D8.4	Validation of 8D closure from supplier management	☐ Minimum standard not reached	☐ - All dates in logical order	☑ - 8D is cross-checked and appr champion/management

Report

- Minimum standard not reached
- All content is understandable
- No abbreviations and terms w definition used

EVALUATION RESULT

Evaluation result: 100

New tab

Ishikawa Diagram

Date of Ishikawa: **3/19/2024** Update of Ishikawa:



Nidec Comments

Factor Tree Analysis

Date of FTA: **3/19/2024** Update of FTA:

PROBLEM DESCRIPTION

Problem description: **double DMC on brush card**

OCCURENCE

Factors	Control Point	Standard	OK parts	NOK parts	Std Meet?	Std OK?	Action to reproduce the defect	Date	Direct Link?	Def. rep
1/re-test parts on production line	the parts will be passed on electrical test and vision test to be controlled	the reinjected parts t be re-tested again must be passed on both electrical test and vision test	OK parts passed Ok	NOK parts detected and puted in jail	No	No	no specifique standard of re-test parts on the production line the NOK parts passed again on the elecrical test and the vison tester and marked again due to the not disactivation of printer device		Yes	No

1 Result(s)

NON DETECTION

Factor	Control Point	Standard	OK Parts	NOK Parts	Std Meet?	Std OK?	Action to reproduce the defect	Date	Direct Link?	Def. rep
2/vision tester	Master parts checklist PC5.2-M1 Ind. 6	- Correct reference / No wire in the internal circle of the housing / Spring presence / No wire out of the	OK parts passed the vision machine	NOK parts passed detected on the vision machine	No	No	specifique standart no exist : the setter switch of setting of both device , he must disactivate the printer device and still activate the reader		Yes	No

		outside circle of the housing									
3/operator training levelB	opeartor level	polyvalence level for operator should be level B	polyvalence level for operator should be level B	polyvalence level for operator should be level B	Yes	Yes	No action to reproduce the defect		No		No

2 Result(s)

Nidec Comment

5 Whys's

Date of 5 why's: **3/20/2024** Update of 5 Why's:

PROBLEM DESCRIPTION

Problem description: **double DMC on brush card**

OCCURENCE

Relevant factors from FTA	1st WHY?	1st Check	2nd WHY?	2nd Check	3rd WHY?	3rd Check	4th WHY?	4th Check	5th
1/re-test parts on production line	parts with double marking passed in opeartion of re-test parts		there is no specific standard of re-testing parts in production line		risk of doubel marking was not considerate				

1 Result(s)

NON DETECTION

Relevant factors from FTA	1st WHY?	1st Check	2nd Check	2nd WHY?	3rd WHY?	3rd Check	4th WHY?	4th Check	5th
2/vision tester	in re-test operation, the DMC printer is still activated.			the setter mixed between the printer device and the reader device	there is no specific standard of disactivation printer during the re-test opearation				

1 Result(s)

Nidec Comment

Lesson Learned Card

LLC Type

Date of LLC:

Logistics: ☐ Management: ☐

Product: ☐ Detection: ☐

Occurence: ☐ Process: ☐

1. What was the problem?

What happened?

double DMC on brush card

Who detected it?

operator

Where was it detected?

CM4 line

2. What is the cause?

standard not exist :
There is no specific standard for operation re-testing.

How was it detected?

visually

Why is it a problem?

double DMC on brush card

When did it happen?

2/6/2024 12:00:00 AM (your local time)

How many parts ?

1.00

3. Description of the applied modification

BEFORE	AFTER
no Standard of re-test parts operation No Specific instruction of vision tester for operation re-test parts (mentioned the printer device must be disactivate and the reader must be activate)	Apply (create) Standard of re-test parts operation create Specific instruction of vision tester for operation re-test parts (mentioned the printer device must be disactivate and the reader must be activate) changement mode.pdf

4. What we learned?

ERADICATION

What is the countermeasure that was put in place to avoid recurrence ?

For occurence
*Standard of re-test parts operation
*/Training session for Quality agent and supervison and setter reading the new standard
For non-detection
*/Specific instruction of vision tester for operation re-test parts (mentioned the printer device must be disactivate and the reader must be activate)
*/Training session of final opeartor for defect double DMC

CHECKING

What is the method (who, what, how) for the countermeasures?

Who : AVO
What
*/For occurence : check the apply of standar of re-test opeartion during each opeartion
*/For non detection : check the apply of new instruction of vison tester during the re-test opeartion

SIGNALING

What is the countermeasure supposed to do or make or h detecting a non conformity ?

In case of detection of NOK parts with double DMC on brush card in the production line : alert and block all stock for sorting
+ Alert and block the parts in transit

5. What has been modified?

a. Proces is modified according to Before/ After sheet:	☐	g. Visual aids are posted:	☑
b. All documents have been updated and has been validated with the operators:	☑	h. Operators and other functions are trained:	☑
c. Procedures and work instructions:	☑	i. Proof of training is avalaible (records,5 ' meeting):	☑
d. Control Plan and PFMEA:	☐	j. Operators can correctly describe what they must do:	☑
e. Maintenance instructions:	☐	k. Other:	☐
f. Records (start-up checklists, reaction sheets, preventive maintenance...):	☑		

EOL_test_audit_station (1).pdf

An evidance of modification: instruction_relecture_updated (1).pdf

6. Potential applicability

LLC Applicability Product: **Brush mounting plate assy**

LLC Applicability Line / process: **CM4**

LLC Applicability Plant: **AVO**

Sorting Approval

Approval of sorting / rework

This document must be sent to Nidec within 24 hour(s) after claim notification

Date of page: Update:

CLAIM ISSUER

Author: Dudek Dominik
Position: SQA Engineer
Phone: +48 12 297 27 86
Fax:
Email: dominik.dudek@nidec-ma.com

CLAIM RECEIVER

Name: Haggui Marwen
Position: Customer Quality
Phone: +21656057189
Fax:
Email: marwen.haggui@avocarbon.com

IMMEDIATE ACTIONS REQUIRED AT NIDEC

PROBLEM DESCRIPTION

double DMC on brush card

DESCRIPTION OF SORTING/REWORK

QUANTITY AND PART NUMBERS CONCERNED

Parts at Nidec plant: 110.00
Parts at Nidec logistics platfrom: 0.00
Parts at Nidec's customer (C1): 0.00
Parts in transport: 0.00
Part Number & Description: Brush mounting plate assy (503-772-99-99)
Suspected delivery notes and batches#: first batch week w06

SORTING COMPANY CHOSEN TO DO THE SORTING/REWORK

Company Name:
Company Address:
Company Website:
Phone:

COMMENTS FROM NIDEC

All costs for semi-finished goods and finished goods with nok components will be invoiced to the supplier. Nok components will be returned to the supplier.

UPLOAD SIGNED FILE

LIST OF SORTING APPROVAL FILES

0 Result(s)

New tab

8D Report Explanation

D1
Nidec opens and incident and issues an 8D to the Supplier
D2-D3
The Supplier undertakes to: • **Contain all defective Supplies which have the same defect from all stocks (finished and semi-finished) and in transportation and at all affected Nidec locations worldwide,** • **Upon request, send a team to carry out sorting and inspection operations at Nidec and Nidec's Customers locations,** • **Upon request, send a team at Nidec's site to address the issue, even if the responsibility of the Supplier has not been proven yet,** • **Replace defective batch (es),** • **Label non-defective batch(es) accordingly,**
D4-D5-D6
The Supplier undertakes to: • **Perform an exhaustive analysis to identify the root cause of the non-conformity with the defined methods,** • **Provide Nidec with an action plan to be validated by Nidec prior to any action being implemented.** • **Update the production CP accordingly to be validated by Nidec.**
D7-D8
The Supplier undertakes to: • **Check the efficiency of the actions implemented. Results have to be validated by Nidec.** • **Update all related documents.** • **Implement the actions to similar Supplies and processes (elimination of recurrences).** • **Issue a Lesson Learned Card.**
Supplier 8D Report Evaluation Sheet
8D Evaluation Sheet has to be presented with final version of 8D report. Evaluation sheet is a tool for assessing compliance of 8D content with Nidec requirements. There are with three levels of acceptance: • **0% - 79% - 8D does not meet minimum requirements and cannot be accepted** • **80% - 89% - 8D meets minimum requirements and can be accepted** • **90% - 100% - 8D evaluated with bonus points and can be accepted** **8D Evaluation Sheet has three levels of points:** • **Unsatisfactory/Not OK** • **Acceptable** • **Requirements fulfilled/Bonus**
Incidents closure
8D following C1 and C2 incidents will be closed after Nidec validation. **Nidec may perform an 8D audit to assess 8D application for C1 incidents. The standard template (Supplier 8D audit) to be used is provided with the RFQ package.**

New tab