Quality Alert

SQA Platform

N° of Alert:2024-mar-008	*Date 18/03/2024*	*update of Alert:*
Customer Plant: AVO/SCEET Fahs	Supplier: AVO GERMANY	
Customer Contact:bassem.benmallek@avocarbon.com	Editor: Belgacem Brika	

Description of the problem

1- Porblem Description :bush was manufactured with dimension 5,965 not conform in minimum
2- Why is it a problem: the height of this carbon brush is too small

Part number:	A60101942(1026047)	When did it happened:	16/03/2024
Part name:	Carbon brush	Who detected it	technician
Batch number:	278419	Where was it detected	at incomming inspection
Recuerrence defect:	yes	How was it detected	by measures
Demerit:		How many parts:	4pcs

Moyen de contrôle utisé par la Tunisie différent de celui utilisé à Poitiers

nok Part (Sketch - Picture)

5,908;5,898;5,928;5921,....

ok Part (Sketch - Picture)



Supplier Porblem Solving Team

Name	Position	Location	Telephone	E.mail
PETITDEMANGE Gwendoline	Customer quality	Quality		gwendoline.petitdemange@avocarbon.com
GIRARD Nathalie	Production quality	Quality		nathalie.girard@avocarbon.com
BILLY Jean-Baptiste	Maintenance manager	Maintenance		jean-baptiste.billy@avocarbon.com
CHARPENTIER Sébastien	Plant manager	Site		sebastien.charpentier@avocarbon.com

Containment

What are the actions to detect all non-conforming parts in the process flow ?

Location in the process flow:	N° to be sorted	N° Parts sorted	N° nok Parts	PPM	Date	Resp.
Parts at SAME plant:	62299 pcs					
Parts at SCEET Logistics Platform:						
Parts in Transport:						
Parts at Supplier Plateform:						
Parts at POITIERS plant :	0					

How are the ok parts identified ?! NA

How are the ok paletts identified ? NA

First contained shipment information

8D report

1- Quick Response after 24 hours:	18/03/2024
2- 4D report after 5 days:	29/03/2024
3- 6D report after 10 days:	05/04/2024 - 26/08/2024
4- Closed 8D report 1 month:	