Lesson Learned Card

LLC Type

Date of LLC: **10/7/2024**

Logistics:	☐	Management:	☐
Product:	☐	Detection:	☑
Occurence:	☑	Process:	☐

1. What was the problem?

What happened?

short circiut between soldering pads

Who detected it?

quality technician

Where was it detected?

CM3

How was it detected?

by analysis

Why is it a problem?

rejected on EOL

When did it happen?

5/19/2024 11:00:00 PM (your local time)

How many parts ?

1.00

2. What is the cause?

1-During the validation of automatic sodlering PCBA , we need to make the operation of soldering of PCBA mannually , the opeartor slight movement to solder the second point without clean the iron --> a llitle tin Fell down between the two soldering points
2-Operator of rework not concentrate and aware about the procedure ''Retest all reworked parts''

3. Description of the applied modification

BEFORE	AFTER
1/Visual control 2/control instruction without picture of defect.	1/Impliment a new camera in station of control soldering PCBA. 2/update the control instruction with adding the claimed part photo for more clarification of the control points.

4. What we learned?

ERADICATION

What is the countermeasure that was put in place to avoid recurrence ?

Make the soldering according to the standard

CHECKING

What is the method (who, what, how) for the countermeasures?

Audit of the line each week

SIGNALING

What is the countermeasure supposed to do or make a non conformity ?

Block all Quantity.
check the camera parameters to ensure the conform of parts produced before detection of the defect.
Check the qualification of the operator.

5. What has been modified?

a. Proces is modified according to Before/ After sheet:	☐	g. Visual aids are posted:	☐
b. All documents have been updated and has been validated with the operators:	☑	h. Operators and other functions are trained:	☑
c. Procedures and work instructions:	☑	i. Proof of training is avalaible (records,5 ' meeting):	☑
d. Control Plan and PFMEA:	☐	j. Operators can correctly describe what they must do:	☐
e. Maintenance instructions:	☑	k. Other:	☐
f. Records (start-up checklists, reaction sheets, preventive maintenance...):	☐		

An evidance of modification: procedure soudure etain.pdf, Fiche de poste.pdf, formation des operateurs.pdf

6. Potential applicability

LLC Applicability Product: **All products**

LLC Applicability Line / process: **CM**

LLC Applicability Plant: **SCEET**

Sorting Approval

Approval of sorting / rework

This document must be sent to Nidec within 24 hour(s) after claim notification

Date of page: Update:

CLAIM ISSUER

Author: **Dudek Dominik**

Position: **SQA Engineer**

Phone: **+48 12 297 27 86**

Fax:

Email: **dominik.dudek@nidec-ma.com**

CLAIM RECEIVER

Name: **Haggui Marwen**

Position: **Customer Quality**

Phone: **+21656057189**

Fax:

Email: **marwen.haggui@avocarbon.com**

IMMEDIATE ACTIONS REQUIRED AT NIDEC

PROBLEM DESCRIPTION

short circiut between soldering pads

DESCRIPTION OF SORTING/REWORK

QUANTITY AND PART NUMBERS CONCERNED

Parts at Nidec plant: **0.00**

Parts at Nidec logistics platfrom: **0.00**

Parts at Nidec's customer (C1): **0.00**

Parts in transport: **0.00**

Part Number & Description: **Brush Mounting Plate Assy (503-779-99-99)**

Suspected delivery notes and batches#: first the Pallet Number N° 175

SORTING COMPANY CHOSEN TO DO THE SORTING/REWORK

Company Name:

Company Address:

Company Website:

Phone:

COMMENTS FROM NIDEC

All costs for semi-finished goods and finished goods with nok components will be invoiced to the supplier. Nok components will be returned to the supplier.

UPLOAD SIGNED FILE

LIST OF SORTING APPROVAL FILES