Claim Management Panel

Supplier: **AVO Carbon France (NMAP551841)**

Type: **C2 : Production claim**

Problem description: **lack of spring**

Claim reference: **NMAP/551841/2/2024/1675**

Settings

C2/C3 REMINDER PANEL

(QR) D2-D3 Defualt Due Date :	**2/28/2024**	1:12:03 PM (your local time)	D2-D3 Revised Due Date:	(QR) D2-D3 Actual Date:	**3/15/2024**	7:31:40 AM (your local time)	(QR) D2-D
D4 Default Due Date :	**3/1/2024**	1:12:03 PM (your local time)	D4 Revised Due Date :	D4 Actual Date :	**4/1/2024**	12:09:15 PM (your local time)	D
D5-D6 Default Due Date:	**3/12/2024**	12:12:03 PM (your local time)	D5-D6 Revised Due Date:	D5-D6 Actual Date:	**4/24/2024**	1:59:04 PM (your local time)	D5-D
D7-D8 Default Due Date:	**3/12/2024**	12:12:03 PM (your local time)	D7-D8 Revised Due Date C2/C3:	D7-D8 Actual Date:	**4/28/2024**	9:50:28 AM (your local time)	D7-D



NOTIFICATIONS SENT

0 Result(s)

NIDEC APPROVALS & REFUSALS HISTORY

Steps approved

Step	Date of validation	User name
D8	4/28/2024	Marwen Haggui
D1	2/27/2024	Dominik Dudek
D4 Validation	4/5/2024	Dominik Dudek
D2	4/1/2024	Marwen Haggui
D2-D3 Validation	3/15/2024	Dominik Dudek
D3	4/1/2024	Marwen Haggui
D4	4/1/2024	Marwen Haggui
D5	4/24/2024	Marwen Haggui
D5-D6 Validation	4/25/2024	Dominik Dudek
D6	4/24/2024	Marwen Haggui
D7	4/28/2024	Marwen Haggui
D7-D8 Validation	4/30/2024	Dominik Dudek
8D closed	5/7/2024	Dorota Siekaniec
8D Closing	5/7/2024	Dorota Siekaniec
Creation	2/27/2024	Dominik Dudek

15 Result(s)

Steps rejected

Step	Date of refusal	User name	Reason for rejection
D2-D3 Validation	3/4/2024	Dominik Dudek	"First contained shipment information:Shippement of week" ??? please enter wright shipment date and attache special label
D4 Validation	3/22/2024	Dominik Dudek	All factors from Ishikawa must be transfer to FTA.

2 Result(s)

Forum

Filter

Keywords:

0 Result(s)

Quick Response (D1-D3)

ALERTS

-Component without PPAP

Plant issued a claim: NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.
Supplier: **AVO Carbon France (NMAP551841)**
Date of Claim: **2/27/2024**

Customer Contact: **Dudek Dominik**
SAP Vendor Code: **551841**
Date of QR: **2/28/2024**

Claim reference: **NMAP/551841/2/2024/1675**
Author: **DUDEK Dominik**
Update of QR: **2/28/2024**

Status: **Closed**
Type: **C2 : Production claim**

CLAIM PPM: 0.00

D1-D3 evaluation score: 22

D1. Description of the problem

1.A WHAT IS THE PROBLEM ? USE 5W+2H TO DESCRIBE WHAT IS THE CURRENT SITUATION.

Problem description: **lack of spring**
What happened?: **lasck of spring**

Part Number & Description: **Brush mounting plate assy (503-773-99-99)**
Why is it a problem?: **lack of spring**

Traceability of nok parts: **231121**
When did it happen? : **2/24/2024** 12:00:00 AM (your local time)

Recurrence: **Recurrent defect**
Who detected it?: **operator**

Defect S/R: **No**
Where was it detected? : **CM4**

How was it detected?: **rejected on EOL**

How many parts ?: **1.00**

nok part picture / sketch:

ok part picture / sketch:

Other files::

1.B SUPPLIER PROBLEM SOLVING TEAM

Supplier Team

Add an existing contact:

Name		Contact	Email	Phone	Cell Phone	Fax	Position	Profile	Status
Haggui Marwen		• marwen.haggui@avocarbon.com	marwen.haggui@avocarbon.com	+21656057189	+21656057189		Customer Quality	Supplier	Active

NidecTeam

Contact	Email	Profile
DUDEK Dominik	dominik.dudek@nidec-ma.com	{profile} Local Quality (Local SQE) (Full) (Claim)

1.C TOOL TO USE (DEFINED BY NIDEC)

Ishikawa: ☑ FTA: ☑ 5 Whys : ☑ LLC: ☑ Audit: ☐ Other: ☐

1.D PROBLEM DESCRIPTION FROM SUPPLIER / FIRST ANALYSE OF PROBLEM / POTENTIAL ROOT CAUSES

Problem description from Supplier: **lack of spring**

Samples of nok parts required at supplier location: ☑ Express shipping supplier account: **regular truck**

D2. Risk on similar products and processes

Can this defect happen on similar parts?: Comments (compulsory if yes): **ALl reference CM4**

Other family product: ☐

Other machine: ☐

Other tooling: ☐

Other Nidec plants: ☐

Other: ☑

D3. Containment

WHAT ARE THE ACTIONS TO DETECT ALL NON-CONFORMING PARTS IN THE PROCESS FLOW?

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Delivery note and batch #	Responsible
Parts at Nidec plant	3,214.00	0.00	1.00			
Parts at Nidec logistics platform	0.00	0.00	0.00			
Parts at Nidecs customer (C1 claim)	0.00	0.00	0.00			

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Responsible	Delivery note and batch #
Parts in transport	18,513.00	18,513.00	0.00	2/29/2024		delevery for week 09
Parts at supplier / supplier platform	0.00	0.00	0.00			
Parts at sub-supplier	0.00	0.00	0.00			
Other Nidec plant/s	0.00	0.00	0.00			

4 Result(s)

How are the ok parts identified?: **100% secured regarding lack of spring**

First contained shipment information: **Shippement of week**

How are the ok paletts identified?: **100% secured regarding lack of spring**

How are the ok parts identified? ::

WHAT ARE THE IMMEDIATE ACTIONS TO PREVENT PRODUCTION/DELIVERY OF NOK PARTS?

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
Express delivery to Nidec to avoid production stop				
Nidec suspect stocks to be sent to supplier				

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
display quality alert	Not required	Supplier	2/28/2024	2/28/2024
QRQC meeting with all the team	Not required	Supplier	2/28/2024	2/28/2024

2 Result(s)

D4-D8

ALERTS

-Component without PPAP

Plant issued a claim:	NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.	Supplier:	**AVO Carbon France (NMAP551841)**	Creation Date:	**2/27/2024**
Customer Contact:	**Dudek Dominik**	SAP Vendor Code:	**551841**	Date of QR:	**2/28/2024**
Claim reference:	**NMAP/551841/2/2024/1675**	Created by:	**DUDEK Dominik**	Update of QR:	**2/28/2024**
Status:	**Closed**	Type:	**C2 : Production claim**	Date of D4-D8:	**3/6/2024**
		CLAIM PPM:	0.00		
D4-D8 evaluation score:	75			Update of D4-D8:	

D 4. Root cause of occurrence

Work out the root causes using first Ishikawa, then FTA and finally 5 why's (Tools to use chosen by Nidec).

ROOT CAUSE OF OCCURRENCE

the NOK parts was produced in the same periode of first
claim of lack spring NMAP/551841/10/2023/1559
and the correctives action are implimented in place
according to the action plan
the root cause is that the Flow of production rework
parts is not efficient and the location of the station
Rework

HOW WAS THE DEFECT REPRODUCED ?

Parts reworked Ok and not yet reworked (rework not
finish) are mixed with production good parts

Attachment:

D 5. Root casue of non detection

ROOT CAUSE OF NON DETECTION :

all the parts produced reworked are mixed with the
normal production

Attachments:

D 6. Countermeasure to non detection and occurrence

6.A ACTIONS FOR OCCURENCE

Action	Responsible	Date Plan	Date Clos.	Attachments Please click 'Save' to activate attachment field
integrate the rewokr jail (the same jail of tin rework)	Bilel bouzidi	11/13/2023	11/13/2023	
separate the rework station and put it outside the production line	Hamza Jbelli	11/13/2023	11/13/2023	Layout___Flow_chart_line.pdf

2 Result(s)

6.B ACTIONS FOR NON-DETECTION

Action	Responsible	Date Plan.	Date Clos.	Attachments Please click 'Save' to activate a

pass 10 parts with lack of spring on EOL tester on station : */ Station of test spring effort */Station of camera	haggui marwan	2/29/2024	2/29/2024	

1 Result(s)

D 7. Effectiveness of action plan

7A ACTIONS TO CHECK EFFECTIVENESS ACTIONS FOR OCCURENCE

Action	Responsible	Date Plan.	Date Clos.	Attachments Please click 'Save' to activate attachment field
layer audit in Rework station	haggui marwan	4/17/2024	4/17/2024	layer audit in rework station.pdf

1 Result(s)

7B ACTIONS TO CHECK EFFECTIVENESS ACTIONS FOR NON-DETECTION

Action	Responsible	Date Plan.	Date Clos.	Attachments Please click 'Save' to activate attachment field
layer audit in Rework station	haggui marwan	4/17/2024	4/17/2024	layer audit in rework station.pdf

1 Result(s)

D 8. Action(s) to prevent recurrence

8.1 DO FOLLOWING DOCUMENTS REQUIRE AN UPDATE ?

Name of the document	Responsible	Date Plan	Date Clos.	Attachments
PFMEA				
Control Plan				
Work instruction	Bilel bouzidi	11/13/2023	11/13/2023	
Control instruction				
Procedure	Hamza Jbelli	11/13/2023	11/13/2023	Layout___Flow_chart_line (1).pdf
Control gage				
Maintenance instruction				
Lesson Learned Card				
Other	haggui marwan	4/17/2024	4/17/2024	layer audit in rework station.pdf
Other				
Other				

8.2 GENERALIZATION OF COUNTERMEASURES TO SIMILAR LINES/ PRODUCTS

8.3 AUDIT DONE BY SUPPLIER (IF REQUIRED)

8D Audit required?:

Date of audit done by supplier:

Supplier Audit Results:

Supplier Audit Comment:

8.4 VALIDATION OF 8D CLOSURE FROM SUPPLIER MANAGEMENT

Name:

Supplier Management Position:

Date of validation of 8D closure from supplier management:

Closure of 8D from Nidec

Chargeback:

Efficiency of 8D proven:

Nok stocks at zero:

8D eval value (%): 100.00

Date of closure:

Supplier 8D Report Evaluation Sheet

EVALUATION

D#	Discipline	Unsatisfactory/Not OK	Acceptable	Requirements fulfilled
D1B	Supplier problem solving team	☐ Minimum standard not reached	☐ - Champion named - Cross functional team - Champion contact data available	☑ - Names and all functions of the functional team are available
D1D	Problem description from supplier / first analysis of the problem / potential root cause	☐ Minimum standard not reached	☐ - Clear and complete description of potential root cause - Express shipping account avaliable	☑ - Relevant attachments (e.g. pi possible root cause provided
D2	Risk on similar products and processes	☐ Minimum standard not reached	☐ - Risk analysis for simmliar products/lines performed and adequate information provided	☑ - Information about risk at oth numbers/family provided
D3	Containment	☐ Minimum standard not reached	☐ - Overview of actions in all material postions (e.g. in transit) available - Effectivity confirmed	☑ - Proof of containment effectiv relevant documentation availa
D4	Root cause of occurrence	☐ Minimum standard not reached	☐ - Root cause identified - Quality tools marked (Ishikawa, FTA, 5 Why's) used for occurence - Appropriate methods applied	☑ - Proof for actions to reproduc (e.g. pictures, records from pro provided
D5	Root cause of non detection	☐ Minimum standard not reached	☐ - Root cause identified - Quality tools marked (Ishikawa, FTA, 5 Why's) used for non-detection - Appropriate methods applied	☑ - Proof for actions to reproduc (e.g. pictures) provided
D6a	Actions for occurence	☐ Minimum standard not reached	☐ - Complete list of corrective actions per identified cause with verification - Timline for permanent actions	☑ - Announced deadlines for clos respected
D6b	Actions for non-detection	☐ Minimum standard not reached	☐ - Complete list of corrective actions per identified cause with verification - Timline for permanent actions	☑ - Announced deadlines for closi respected
D7a	Actions to check effectiveness actions for occurence	☐ Minimum standard not reached	☐ - Complete list of permanent corrective actions with details - Verification of actions (statistics)	☑ - Containment actions success after introduction of permane action
D7b	Actions to check effectiveness actions for non-detection	☐ Minimum standard not reached	☐ - Complete list of permanent corrective actions with details - Verification of actions (statistics)	☑ - Containment actions success after introduction of permane action
D8.1	Do following documents require an update ?	☐ Minimum standard not reached	☐ - Documented lessons learned - Relevant documents updated (FMEA, Control Plan, etc.)	☑ - Analysis of generalization of countermeasures to similar lin performed
D8.4	Validation of 8D closure from supplier management	☐ Minimum standard not reached	☐ - All dates in logical order	☑ - 8D is cross-checked and appr champion/management
Report		☐ Minimum standard not reached	☐ - All content is understandable	☑ - No abbreviations and terms v definition used

EVALUATION RESULT

Evaluation result: 100

New tab

Ishikawa Diagram

Date of Ishikawa: **3/18/2024** Update of Ishikawa:



Nidec Comments

Factor Tree Analysis

Date of FTA: **3/18/2024** Update of FTA:

PROBLEM DESCRIPTION

Problem description: **lack of spring**

OCCURENCE

Factors	Control Point	Standard	OK parts	NOK parts	Std Meet?	Std OK?	Action to reproduce the defect	Date	Direct Link?	Def. rep
1/rework production flow	control the flow of parts reworked	rework the parts according the reowrk instruction with respect the flow mentionned in instruction PS12.1-M4 ind. 2	flow respected	flow not respected	No	No	The flow of production in line allows for the rework of parts not well positionned spring to be passed to the customer.		Yes	**No**
2/spring crimping station	control the good crimping of the spring	acording the work instruction PS12.1-M2 ind. 4	Ok parts with good grimping spring	NOK parts with good grimping spring	Yes	Yes	Action not reproduce the defect.		No	**No**

2 Result(s)

NON DETECTION

Factor	Control Point	Standard	OK Parts	NOK Parts	Std Meet?	Std OK?	Action to reproduce the defect	Date	Direct Link?	Def. rep
2/ELecrical test	Master samples checklist + Master samples validation checklist	Missing spring, Inverted brush, No short circuit between GND-Contact1, No short circuit between Contact3-GND,	Ok part passed good in the electrical test	NOK part detected by the electrical test (lack of spring)	Yes	Yes	the electrical test detecet the NOK parts and passed as NOK --> the parts was puted		No	**No**

		Electrical continuity in circuit 1, Electrical continuity in circuit 3, Short circuit between forks, Resistor test : absence and value, Hall IC functioning, Capacitor Test : Absence and value, Gauge check for pins, Mixed PCB : Varistor functioning and capacitance value & Height 1.3									
4.training level B	Training level	Operator should be at level B	operator at level B	operator at level B	Yes	Yes	defect not reproduced		No		**No**

2 Result(s)

Nidec Comment

5 Whys's

Date of 5 why's: **3/18/2024** Update of 5 Why's:

PROBLEM DESCRIPTION

Problem description: **lack of spring**

OCCURENCE

Relevant factors from FTA	1st WHY?	1st Check	2nd WHY?	2nd Check	3rd WHY?	3rd Check	4th WHY?	4th Check	5th
1/rework production flow	risk not considerate	>	the flow of the production of reworked parts was integrated with the normal production	>	the flow of reworked parts is not locked	>	failure not taken into account during PFMEA analysis	X	

1 Result(s)

NON DETECTION

Relevant factors from FTA	1st WHY?	1st Check	2nd Check	2nd WHY?	3rd WHY?	3rd Check	4th WHY?	4th Check	5th WHY?	5th Check

Nidec Comment

Lesson Learned Card

LLC Type

Date of LLC:

Logistics:	☐	Management:	☐
Product:	☐	Detection:	☑
Occurence:	☑	Process:	☐

1. What was the problem?

What happened?

lasck of spring

Who detected it?

operator

Where was it detected?

CM4

How was it detected?

rejected on EOL

Why is it a problem?

lack of spring

When did it happen?

2/24/2024 12:00:00 AM (your local time)

How many parts ?

1.00

2. What is the cause?

the NOK parts was produced in the same periode of first claim of lack spring NMAP/551841/10/2023/1559
and the correctives action are implimented in place according to the action plan
the root cause is that the Flow of production rework parts is not efficient and the location of the station Rework

3. Description of the applied modification

BEFORE	AFTER
No integrate the rewokr jail **No separation he rework station and put it outside the production line**	**integrate the rewokr jail** **separate the rework station and put it outside the production line**

4. What we learned?

ERADICATION

What is the countermeasure that was put in place to avoid recurrence ?

***For occurence**
-implimentation specific jail for the rework station
-separation rewrok station and production line and put it outside the production line
***For non detection**
-paasing parts on electrical test and vision test with lack spring and see the results

CHECKING

What is the method (who, what, how) for the countermeasures?

Who : AVO
What :
***/For occurence : - verification the rework opeartion done only in the rework station outside the production line**
***/For non detection :**
-check the detection of lack spring by the electrcial test and vision test

SIGNALING

What is the countermeasure supposed to do or make or h detecting a non conformity ?

In case of detection of NOK parts with lack of spring in the production line : alert and block all stock for sorting + Alert and block the parts in transit

5. What has been modified?

a. Proces is modified according to Before/ After sheet:	☐	g. Visual aids are posted:	☑
b. All documents have been updated and has been validated with the operators:	☐	h. Operators and other functions are trained:	☑
c. Procedures and work instructions:	☑	i. Proof of training is avalaible (records,5 ' meeting):	☑
d. Control Plan and PFMEA:	☐	j. Operators can correctly describe what they must do:	☐
e. Maintenance instructions:	☐	k. Other:	☐
f. Records (start-up checklists, reaction sheets, preventive maintenance...):	☐		

An evidance of modification:
- Layout___Flow_chart_line (1).pdf
- layer audit in rework station.pdf

6. Potential applicability

LLC Applicability Product:	**Brush mounting plate assy**
LLC Applicability Line / process:	**CM4**
LLC Applicability Plant:	**AVO**

Sorting Approval

Approval of sorting / rework

This document must be sent to Nidec within 24 hour(s) after claim notification

Date of page: Update:

CLAIM ISSUER

Author: Dudek Dominik
Position: SQA Engineer
Phone: +48 12 297 27 86
Fax:
Email: dominik.dudek@nidec-ma.com

CLAIM RECEIVER

Name: Haggui Marwen
Position: Customer Quality
Phone: +21656057189
Fax:
Email: marwen.haggui@avocarbon.com

IMMEDIATE ACTIONS REQUIRED AT NIDEC

PROBLEM DESCRIPTION

lack of spring

DESCRIPTION OF SORTING/REWORK

QUANTITY AND PART NUMBERS CONCERNED

Parts at Nidec plant: 3,214.00
Parts at Nidec logistics platfrom: 0.00
Parts at Nidec's customer (C1): 0.00
Parts in transport: 0.00
Part Number & Description: Brush mounting plate assy (503-773-99-99)

delevery for week 09

Suspected delivery notes and batches#:

SORTING COMPANY CHOSEN TO DO THE SORTING/REWORK

Company Name:
Company Address:
Company Website:
Phone:

COMMENTS FROM NIDEC

All costs for semi-finished goods and finished goods with nok components will be invoiced to the supplier. Nok components will be returned to the supplier.

UPLOAD SIGNED FILE

LIST OF SORTING APPROVAL FILES

0 Result(s)

New tab

8D Report Explanation

D1
Nidec opens and incident and issues an 8D to the Supplier
D2-D3
The Supplier undertakes to: • **Contain all defective Supplies which have the same defect from all stocks (finished and semi-finished) and in transportation and at all affected Nidec locations worldwide,** • **Upon request, send a team to carry out sorting and inspection operations at Nidec and Nidec's Customers locations,** • **Upon request, send a team at Nidec's site to address the issue, even if the responsibility of the Supplier has not been proven yet,** • **Replace defective batch (es),** • **Label non-defective batch(es) accordingly,**
D4-D5-D6
The Supplier undertakes to: • **Perform an exhaustive analysis to identify the root cause of the non-conformity with the defined methods,** • **Provide Nidec with an action plan to be validated by Nidec prior to any action being implemented.** • **Update the production CP accordingly to be validated by Nidec.**
D7-D8
The Supplier undertakes to: • **Check the efficiency of the actions implemented. Results have to be validated by Nidec.** • **Update all related documents.** • **Implement the actions to similar Supplies and processes (elimination of recurrences).** • **Issue a Lesson Learned Card.**
Supplier 8D Report Evaluation Sheet
8D Evaluation Sheet has to be presented with final version of 8D report. Evaluation sheet is a tool for assessing compliance of 8D content with Nidec requirements. There are with three levels of acceptance: • **0% - 79% - 8D does not meet minimum requirements and cannot be accepted** • **80% - 89% - 8D meets minimum requirements and can be accepted** • **90% - 100% - 8D evaluated with bonus points and can be accepted** **8D Evaluation Sheet has three levels of points:** • **Unsatisfactory/Not OK** • **Acceptable** • **Requirements fulfilled/Bonus**
Incidents closure
8D following C1 and C2 incidents will be closed after Nidec validation. **Nidec may perform an 8D audit to assess 8D application for C1 incidents. The standard template (Supplier 8D audit) to be used is provided with the RFQ package.**

New tab