Claim Management Panel

Supplier: **AVO Carbon France (NMAS609128)**

Type: **C2 : Production claim**

Problem description: **Trimmed Sheet Not Punched**

Claim reference: **NMAS/609128/3/2024/1696**

Settings

C2/C3 REMINDER PANEL

(QR) D2-D3 Defualt Due Date :	**3/18/2024**	8:58:55 AM (your local time)	D2-D3 Revised Due Date:	(QR) D2-D3 Actual Date:	**3/18/2024**	7:42:18 AM (your local time)	(QR) D2-D
D4 Default Due Date :	**3/20/2024**	8:58:55 AM (your local time)	D4 Revised Due Date :	D4 Actual Date :	**4/15/2024**	9:19:13 AM (your local time)	D
D5-D6 Default Due Date:	**3/29/2024**	8:58:55 AM (your local time)	D5-D6 Revised Due Date:	D5-D6 Actual Date:	**4/16/2024**	12:06:05 PM (your local time)	D5-D
D7-D8 Default Due Date:	**3/29/2024**	8:58:55 AM (your local time)	D7-D8 Revised Due Date C2/C3:	D7-D8 Actual Date:	**4/22/2024**	2:22:56 PM (your local time)	D7-D



NOTIFICATIONS SENT

0 Result(s)

NIDEC APPROVALS & REFUSALS HISTORY

Steps approved

Step	Date of validation	User name
D8	4/22/2024	Marwen Haggui
D1	3/15/2024	Alfons Lledo
D4 Validation	4/16/2024	Alfons Lledo
D2	4/15/2024	Marwen Haggui
D2	4/15/2024	Karim MNASRI
D2-D3 Validation	3/18/2024	Alfons Lledo
D3	4/15/2024	Marwen Haggui
D4	4/15/2024	Marwen Haggui
D5-D6 Validation	4/16/2024	Alfons Lledo
D6	4/16/2024	Alfons Lledo
D7	4/22/2024	Marwen Haggui
D7-D8 Validation	4/29/2024	Alfons Lledo
8D closed	4/30/2024	FRANCISCO MOYA
8D Closing	4/30/2024	FRANCISCO MOYA
Creation	3/15/2024	Alfons Lledo

15 Result(s)

Steps rejected

Step	Date of refusal	User name	Reason for rejection
D7-D8 Validation	4/22/2024	FRANCISCO MOYA	Please update , LLC and D.8: Control Plan and PFMEA have to be updated according actions implemented.
8D Closing	4/29/2024	Alfons Lledo	Closure of 8D from Nidec not filled in

2 Result(s)

Forum

Filter

Keywords:

0 Result(s)

Quick Response (D1-D3)

ALERTS

-Component without PPAP

Plant issued a claim: NIDEC MOTORS & ACTUATORS (SPAIN) S.A.U
Supplier: **AVO Carbon France (NMAS609128)**
Date of Claim: **3/15/2024**
Customer Contact: **Lledo Alfons**
SAP Vendor Code: **609128**
Date of QR: **3/18/2024**
Claim reference: **NMAS/609128/3/2024/1696**
Author: **LLEDO Alfons**
Update of QR:
Status: **Closed**
Type: **C2 : Production claim**
CLAIM PPM: 0.00
D1-D3 evaluation score: 22

D1. Description of the problem

1.A WHAT IS THE PROBLEM ? USE 5W+2H TO DESCRIBE WHAT IS THE CURRENT SITUATION.

Problem description: **Trimmed Sheet Not Punched**
What happened?: **Trimmed Sheet Not Punched**
Part Number & Description: **BRUSH CARD HOLDER 11TA (A18116507G)**
Why is it a problem?: **Fuse Choke Losses its Functionallity**
Traceability of nok parts: **231013**
When did it happen? : **3/13/2024** 11:00:00 PM (your local time)
Recurrence: **No reccurent defect**
Who detected it?: **11TA Assembly Line Operator**
Defect S/R: **Yes (S/security)**
Where was it detected? : **11TA Assembly Line**
How was it detected?: **Visually**
How many parts ?: **4.00**

nok part picture / sketch:

ok part picture / sketch:

Other files::

1.B SUPPLIER PROBLEM SOLVING TEAM

Supplier Team

Add an existing contact:

Name		Contact	Email	Phone	Cell Phone	Fax	Position	Profile	Status
Haggui Marwen		• marwen.haggui@avocarbon.com	marwen.haggui@avocarbon.com	+21656057189	+21656057189		Customer Quality	Supplier	Active
MNASRI Karim		• karim.mnasri@avocarbon.com	karim.mnasri@avocarbon.com	+21656834809			Plant Quality Manager	Supplier	Active

NidecTeam

Contact	Email	Profile

LLEDO Alfons	Alfons.Lledo@nidec-ma.com	{profile} Local Quality (Local SQE) (Full) (Claim)
MACÍAS Juan Antonio	juan-antonio.macias@nidec-ma.com	{profile} Contributor (Claim)
MOYA FRANCISCO	francisco.moya@nidec-ma.com	{profile} Contributor (Claim) Local Quality (Local SQE) (Full) (Claim)

1.C TOOL TO USE (DEFINED BY NIDEC)

Ishikawa: ☑ FTA: ☑ 5 Whys : ☑ LLC: ☑ Audit: ☑ Other: ☐

1.D PROBLEM DESCRIPTION FROM SUPPLIER / FIRST ANALYSE OF PROBLEM / POTENTIAL ROOT CAUSES

Problem description from Supplier: **Trimmed Sheet Not Punched**

Samples of nok parts required at supplier location: ☑ Express shipping supplier account: **regular truck**

D2. Risk on similar products and processes

Can this defect happen on similar parts?: Comments (compulsory if yes): **(A18116507G)**

Other family product: ☐

Other machine: ☐

Other tooling: ☐

Other Nidec plants: ☐

Other: ☑

D3. Containment

WHAT ARE THE ACTIONS TO DETECT ALL NON-CONFORMING PARTS IN THE PROCESS FLOW?

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Delivery note and batch #	Responsible
Parts at Nidec plant	4,376.00	0.00	4.00	3/15/2024		Supplier
Parts at Nidec logistics platform	0.00	0.00	0.00			
Parts at Nidecs customer (C1 claim)	0.00	0.00	0.00			

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Responsible	Delivery note and batch #
Parts in transport	7,224.00	7,224.00	0.00	3/18/2024	Supplier	
Parts at supplier / supplier platform	0.00	0.00	0.00			
Parts at sub-supplier	0.00	0.00	0.00			
Other Nidec plant/s	0.00	0.00	0.00			

4 Result(s)

How are the ok parts identified?: **100% secured regarding Trimmed Sheet Not Punched**

First contained shipment information: **first batch secured deleverd week 11**

How are the ok paletts identified?: **NIDEC Orange identification**

How are the ok parts identified? ::

WHAT ARE THE IMMEDIATE ACTIONS TO PREVENT PRODUCTION/DELIVERY OF NOK PARTS?

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
Express delivery to Nidec to avoid production stop				

Nidec suspect stocks to be sent to supplier				

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
QRQC meeting	Not required	Supplier	3/15/2024	3/15/2024
Quality alert	Not required	Supplier	3/15/2024	3/15/2024

2 Result(s)

D4-D8

ALERTS

-Component without PPAP

Plant issued a claim: NIDEC MOTORS & ACTUATORS (SPAIN) S.A.U
Supplier: **AVO Carbon France (NMAS609128)**
Creation Date: **3/15/2024**

Customer Contact: **Lledo Alfons**
SAP Vendor Code: **609128**
Date of QR: **3/18/2024**

Claim reference: **NMAS/609128/3/2024/1696**
Created by: **LLEDO Alfons**
Update of QR:

Status: **Closed**
Type: **C2 : Production claim**
Date of D4-D8: **3/25/2024**

CLAIM PPM: 0.00

D4-D8 evaluation score: 75
Update of D4-D8:

D 4. Root cause of occurrence

Work out the root causes using first Ishikawa, then FTA and finally 5 why's (Tools to use chosen by Nidec).

ROOT CAUSE OF OCCURRENCE

standard is not enough :
the frequency of cleaning the debreding station is not well defined , that's mean cleaning each shift is not enought to eliminate the burr and the risk of punshed point not done

HOW WAS THE DEFECT REPRODUCED ?

During the debriding operation, the fixture is not clean (there are some metallic burrs ticked inside the fixture).
The operator put OVP and started the cycle of debriding. -> after the accumulation of burrs, the defect was created.

Attachment:

D 5. Root casue of non detection

ROOT CAUSE OF NON DETECTION :

Standard is not efficient.
In the method of control in the debriding station, the operator takes part each production of parts and controls it visually regarding the punched point.

Attachments:

D 6. Countermeasure to non detection and occurrence

6.A ACTIONS FOR OCCURENCE