Claim Management Panel

Supplier: **AVO Carbon France (NMAP551841)**

Type: **C2 : Production claim**

Problem description: **choke wire not welded**

Claim reference: **NMAP/551841/7/2024/1798**

Settings

C2/C3 REMINDER PANEL

(QR) D2-D3 Defualt Due Date :	**7/10/2024**	9:11:43 AM (your local time)	D2-D3 Revised Due Date:	(QR) D2-D3 Actual Date:	**7/10/2024**	2:04:11 PM (your local time)	(QR) D2-D3
D4 Default Due Date :	**7/12/2024**	9:11:43 AM (your local time)	D4 Revised Due Date :	D4 Actual Date :	**9/4/2024**	11:56:57 AM (your local time)	D4
D5-D6 Default Due Date:	**7/23/2024**	9:11:43 AM (your local time)	D5-D6 Revised Due Date:	D5-D6 Actual Date:	**10/9/2024**	9:05:49 AM (your local time)	D5-D6
D7-D8 Default Due Date:	**7/23/2024**	9:11:43 AM (your local time)	D7-D8 Revised Due Date C2/C3:	D7-D8 Actual Date:	**10/9/2024**	2:02:45 PM (your local time)	D7-D8



NOTIFICATIONS SENT

0 Result(s)

NIDEC APPROVALS & REFUSALS HISTORY

Steps approved

Step	Date of validation	User name
D8	10/9/2024	Marwen Haggui
D1	7/9/2024	Dominik Dudek
D4 Validation	9/4/2024	Dominik Dudek
D2	9/4/2024	Marwen Haggui
D2-D3 Validation	7/10/2024	Dominik Dudek
D3	9/4/2024	Marwen Haggui
D4	9/4/2024	Marwen Haggui
D5	10/9/2024	Marwen Haggui
D5-D6 Validation	10/9/2024	Dominik Dudek
D6	10/9/2024	Marwen Haggui
D7	10/9/2024	Marwen Haggui
D7-D8 Validation	10/10/2024	Dominik Dudek
8D closed	10/11/2024	Dorota Siekaniec
8D Closing	10/11/2024	Dorota Siekaniec
Creation	7/9/2024	Dominik Dudek

15 Result(s)

Steps rejected

Step	Date of refusal	User name	Reason for rejection
D4 Validation	8/23/2024	Dominik Dudek	Please do necesery corection. Details in email.
D5-D6 Validation	9/9/2024	Dominik Dudek	In D6.A (action for occurrence) lack of information regards frequency to check value of current.

2 Result(s)

Forum

Filter

Keywords:

0 Result(s)

Quick Response (D1-D3)

ALERTS

-Component without PPAP

Plant issued a claim: NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.
Supplier: **AVO Carbon France (NMAP551841)**
Date of Claim: **7/9/2024**

Customer Contact: **Dudek Dominik**
SAP Vendor Code: **551841**
Date of QR: **7/10/2024**

Claim reference: **NMAP/551841/7/2024/1798**
Author: **DUDEK Dominik**
Update of QR: **7/10/2024**

Status: **Closed**
Type: **C2 : Production claim**

CLAIM PPM: 0.00

D1-D3 evaluation score: 22

D1. Description of the problem

1.A WHAT IS THE PROBLEM ? USE 5W+2H TO DESCRIBE WHAT IS THE CURRENT SITUATION.

Problem description: **choke wire not welded**
What happened?: **choke wire not welded**

Part Number & Description: **Brush mounting plate assy (503-773-99-99)**
Why is it a problem?: **motor was rejected on EOL**

Traceability of nok parts: **DMC 5037732415341212, ASN 180393916**
When did it happen? : **7/7/2024** 11:00:00 PM (your local time)

Recurrence: **Recurrent defect**
Who detected it?: **operator**

Defect S/R: **No**
Where was it detected? : **CM4**

How was it detected?: **During defect analysis**

How many parts ?: **1.00**

nok part picture / sketch:

ok part picture / sketch:

Other files::

1.B SUPPLIER PROBLEM SOLVING TEAM

Supplier Team

Add ar

Name		Contact	Email	Phone	Cell Phone	Fax	Position	Pr
Bechikh Wissal		• wissal.bechikh@avocarbon.com	wissal.bechikh@avocarbon.com	+216 58598711			Customer Quality	Su
Ben Mallek Bassem			bassem.benmallek@avocarbon.com	00216 58588811			Project quality engineer	{pr
Ghribi Mohamed Aymen		• mohamedaymen.ghribi@avocarbon.com	mohamedaymen.ghribi@avocarbon.com	0021658352210			Quality	Su
Haggui Marwen		• marwen.haggui@avocarbon.com	marwen.haggui@avocarbon.com	+21656057189	+21656057189		Customer Quality	Su

NidecTeam

Contact	Email	Profile
DUDEK Dominik	dominik.dudek@nidec-ma.com	{profile} Local Quality (Local SQE) (Full) (Claim)

1.C TOOL TO USE (DEFINED BY NIDEC)

Ishikawa: ☑ FTA: ☑ 5 Whys : ☑ LLC: ☑ Audit: ☐ Other: ☐

1.D PROBLEM DESCRIPTION FROM SUPPLIER / FIRST ANALYSE OF PROBLEM / POTENTIAL ROOT CAUSES

Problem description from Supplier: **bad welding between thermal switch leg and choke leg**

Samples of nok parts required at supplier location: ☑ Express shipping supplier account: **Regular express**

D2. Risk on similar products and processes

Can this defect happen on similar parts?: Comments (compulsory if yes): **503-773-99-99**

Other family product: ☐

Other machine: ☐

Other tooling: ☐

Other Nidec plants: ☐

Other: ☐

D3. Containment

WHAT ARE THE ACTIONS TO DETECT ALL NON-CONFORMING PARTS IN THE PROCESS FLOW?

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Delivery note and batch #	Responsible
Parts at Nidec plant	1,442.00	0.00	1.00			
Parts at Nidec logistics platform	0.00	0.00	0.00			
Parts at Nidecs customer (C1 claim)	0.00	0.00	0.00			

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Responsible	Delivery note and batch #
Parts in transport	39,519.00	0.00	0.00	7/10/2024	Supplier	In NUNNER
Parts at supplier / supplier platform	5,000.00	5,000.00	0.00	7/10/2024	Supplier	AVO
Parts at sub-supplier	0.00	0.00	0.00			
Other Nidec plant/s	0.00	0.00	0.00			

4 Result(s)

How are the ok parts identified?: **100% secured regarding bad welding thermal switch and chock wire**

First contained shipment information: **Delevery for week W29**

How are the ok paletts identified?: **100% secured regarding bad welding thermal switch and chock wire**

How are the ok parts identified? ::

WHAT ARE THE IMMEDIATE ACTIONS TO PREVENT PRODUCTION/DELIVERY OF NOK PARTS?

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
Express delivery to Nidec to avoid production stop				
Nidec suspect stocks to be sent to supplier				

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
QRQC meeting with team	Required	Supplier	7/9/2024	7/9/2024
Quality alert in production line			7/9/2024	7/9/2024
start selection to secure the product in AVO side	Required		7/9/2024	7/9/2024

3 Result(s)

D4-D8

ALERTS

-Component without PPAP

Plant issued a claim:	NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.	Supplier:	**AVO Carbon France (NMAP551841)**	Creation Date:	**7/9/2024**
Customer Contact:	**Dudek Dominik**	SAP Vendor Code:	**551841**	Date of QR:	**7/10/2024**
Claim reference:	**NMAP/551841/7/2024/1798**	Created by:	**DUDEK Dominik**	Update of QR:	**7/10/2024**
Status:	**Closed**	Type:	**C2 : Production claim**	Date of D4-D8:	**8/21/2024**
		CLAIM PPM:	0.00		
D4-D8 evaluation score:	75			Update of D4-D8:	

D 4. Root cause of occurrence

Work out the root causes using first Ishikawa, then FTA and finally 5 why's (Tools to use chosen by Nidec).

ROOT CAUSE OF OCCURRENCE

the current was controlled but not efficient , the intervall were not well defined , the claimed parts were welded with lack current

HOW WAS THE DEFECT REPRODUCED ?

the current was controlled but not efficient , the intervall were not well defined , the claimed parts were welded with lack current

Link of video :
https://drive.google.com/file/d/10DSFzF2TA-E-7I2zZYrhWOiBnzlOWeGC/view?usp=sharing

Attachment:

Current conrole in welding station .mp4

D 5. Root casue of non detection

ROOT CAUSE OF NON DETECTION :

The control method, not enough to describe the defect

Attachments:

D 6. Countermeasure to non detection and occurrence

6.A ACTIONS FOR OCCURENCE

Action	Responsible	Date Plan	Date Clos.	Attachments Please click 'Save' to activate attachment fiel
Implement control current in welding station to avoid any welding operation with lack of power	hajer	7/19/2024	7/19/2024	PH 3.75 Soudure Self sur PTH.pdf