Claim Management Panel

Supplier: **AVO Carbon France (NMAP551841)**

Type: **I - Information**

Problem description: **double DMC on brush card**

Claim reference: **NMAP/551841/2/2024/1666**

Settings

C2/C3 REMINDER PANEL

(QR) D2-D3 Defualt Due Date :	**2/9/2024**	10:19:41 AM (your local time)	D2-D3 Revised Due Date:	(QR) D2-D3 Actual Date:	**3/13/2024**	3:05:40 PM (your local time)	(QR) D2-D
D4 Default Due Date :	**2/13/2024**	10:19:41 AM (your local time)	D4 Revised Due Date :	D4 Actual Date :	**3/20/2024**	7:49:10 AM (your local time)	D
D5-D6 Default Due Date:	**2/22/2024**	10:19:41 AM (your local time)	D5-D6 Revised Due Date:	D5-D6 Actual Date:	**4/1/2024**	9:05:38 AM (your local time)	D5-D
D7-D8 Default Due Date:	**2/22/2024**	10:19:41 AM (your local time)	D7-D8 Revised Due Date C2/C3:	D7-D8 Actual Date:	**4/4/2024**	7:31:03 AM (your local time)	D7-D



NOTIFICATIONS SENT

0 Result(s)

NIDEC APPROVALS & REFUSALS HISTORY

Steps approved

Step	Date of validation	User name
D8	4/4/2024	Marwen Haggui
D1	2/8/2024	Dominik Dudek
D4 Validation	3/20/2024	Dominik Dudek
D2	3/20/2024	Marwen Haggui
D2-D3 Validation	3/19/2024	Dominik Dudek
D3	3/20/2024	Marwen Haggui
D4	3/20/2024	Marwen Haggui
D5	4/1/2024	Marwen Haggui
D5-D6 Validation	4/3/2024	Dominik Dudek
D6	4/1/2024	Marwen Haggui
D7	4/4/2024	Marwen Haggui
D7-D8 Validation	4/4/2024	Dominik Dudek
8D closed	4/8/2024	Dorota Siekaniec
8D Closing	4/8/2024	Dorota Siekaniec
Creation	2/8/2024	Dominik Dudek

15 Result(s)

Steps rejected

0 Result(s)

Forum

Filter

Keywords:

0 Result(s)

Quick Response (D1-D3)

ALERTS

-Component without PPAP

Plant issued a claim:	NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.	Supplier:	**AVO Carbon France (NMAP551841)**	Date of Claim:	**2/8/2024**
Customer Contact:	**Dudek Dominik**	SAP Vendor Code:	**551841**	Date of QR:	**2/9/2024**
Claim reference:	**NMAP/551841/2/2024/1666**	Author:	**DUDEK Dominik**	Update of QR:	**2/9/2024**
Status:	**Closed**	Type:	**I - Information**		
		CLAIM PPM:	0.00		

D1-D3 evaluation score: 22

D1. Description of the problem

1.A WHAT IS THE PROBLEM ? USE 5W+2H TO DESCRIBE WHAT IS THE CURRENT SITUATION.

Problem description:	**double DMC on brush card**	What happened?:	**double DMC on brush card**
Part Number & Description:	Brush mounting plate assy (503-772-99-99)	Why is it a problem?:	**double DMC on brush card**
Traceability of nok parts:	**ASN180383229**	When did it happen? :	**2/6/2024** 12:00:00 AM (your local time)
Recurrence:	**No reccurent defect**	Who detected it?:	**operator**
Defect S/R:	**No**	Where was it detected? :	**CM4 line**
		How was it detected?:	**visually**
		How many parts ?:	**1.00**

nok part picture / sketch:

ok part picture / sketch:

Other files::

1.B SUPPLIER PROBLEM SOLVING TEAM

Supplier Team

Add an existing contact:

Name		Contact	Email	Phone	Cell Phone	Fax	Position	Profile	Status
Haggui Marwen		• marwen.haggui@avocarbon.com	marwen.haggui@avocarbon.com	+21656057189	+21656057189		Customer Quality	Supplier	Active

NidecTeam

Contact	Email	Profile
DUDEK Dominik	dominik.dudek@nidec-ma.com	{profile} Local Quality (Local SQE) (Full) (Claim)

1.C TOOL TO USE (DEFINED BY NIDEC)

Ishikawa: ☑ FTA: ☑ 5 Whys : ☑ LLC: ☑ Audit: ☐ Other: ☐

1.D PROBLEM DESCRIPTION FROM SUPPLIER / FIRST ANALYSE OF PROBLEM / POTENTIAL ROOT CAUSES

Problem description from Supplier: **double DMC on brush card**

Samples of nok parts required at supplier location: ☑ Express shipping supplier account: **regular truck**

D2. Risk on similar products and processes

Can this defect happen on similar parts?: Comments (compulsory if yes): **ALL CM4 reference**

Other family product: ☑ Component:
Brush mounting plate assy (503-772-99-99)
Brush mounting plate assy (503-773-99-99)
Brush mounting plate assy (503-774-99-99)
Brush mounting plate assy (503-775-99-99)
Brush mounting plate assy (503-852-99-99)
Brush mounting plate assy (503-989-99-99)
Brush mounting plate assy (503-991-99-99)

Other machine: ☐

Other tooling: ☐

Other Nidec plants: ☐

Other: ☐

D3. Containment

WHAT ARE THE ACTIONS TO DETECT ALL NON-CONFORMING PARTS IN THE PROCESS FLOW?

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Delivery note and batch #	Responsible
Parts at Nidec plant	110.00	0.00	1.00			
Parts at Nidec logistics platform	0.00	0.00	0.00			
Parts at Nidecs customer (C1 claim)	0.00	0.00	0.00			

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Responsible	Delivery note and batch #
Parts in transport	2,940.00	2,940.00	0.00	2/10/2024	Supplier	first batch week w06
Parts at supplier / supplier platform	0.00	0.00	0.00			
Parts at sub-supplier	0.00	0.00	0.00			
Other Nidec plant/s	0.00	0.00	0.00			

4 Result(s)

How are the ok parts identified?: **100% regarding double DMC on brush card**

First contained shipment information: **first batch secured delevered Week 06**

How are the ok paletts identified?: **Orange NIDEC identification**

How are the ok parts identified? ::

WHAT ARE THE IMMEDIATE ACTIONS TO PREVENT PRODUCTION/DELIVERY OF NOK PARTS?

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
Express delivery to Nidec to avoid production stop				
Nidec suspect stocks to be sent to supplier				

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
QRQC meeting	Required	Supplier	2/9/2024	2/9/2024

1 Result(s)

D4-D8

ALERTS

-Component without PPAP

Plant issued a claim:	NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.	Supplier:	**AVO Carbon France (NMAP551841)**	Creation Date:	**2/8/2024**
Customer Contact:	**Dudek Dominik**	SAP Vendor Code:	**551841**	Date of QR:	**2/9/2024**
Claim reference:	**NMAP/551841/2/2024/1666**	Created by:	**DUDEK Dominik**	Update of QR:	**2/9/2024**
Status:	**Closed**	Type:	**I - Information**	Date of D4-D8:	**3/20/2024**
		CLAIM PPM:	0.00		
D4-D8 evaluation score:	75			Update of D4-D8:	

D 4. Root cause of occurrence

Work out the root causes using first Ishikawa, then FTA and finally 5 why's (Tools to use chosen by Nidec).

ROOT CAUSE OF OCCURRENCE

standard not exist :
There is no specific standard for operation re-testing.

HOW WAS THE DEFECT REPRODUCED ?

the setter mixed between the printer device and the reader device

Attachment:

D 5. Root casue of non detection

ROOT CAUSE OF NON DETECTION :

the setter must disactivate the printer device and keep the reader device activated.

Attachments:

D 6. Countermeasure to non detection and occurrence

6.A ACTIONS FOR OCCURENCE

Action	Responsible	Date Plan	Date Clos.	Attachments Please click 'Save' to activate attachment fielc
Standard of re-test parts operation	hamza	3/5/2024	3/5/2024	
Training session for Quality agent and supervison and setter reading the new standard	training departement	3/5/2024	3/5/2024	

2 Result(s)

6.B ACTIONS FOR NON-DETECTION

Action	Responsible	Date Plan.	Date Clos.	Attachments Please click 'Save' to activate
Specific instruction of vision tester for operation re-test parts (mentioned the printer device must be disactivate and the reader must be activate)	marwan haggui	3/6/2024	3/6/2024	instruction relecture update