Claim Management Panel

Supplier: **AVO Carbon France (NMAP551841)**

Type: **C1 : Customer claim**

Problem description: **bent hall pins in connector**

Claim reference: **NMAP/551841/9/2024/1847**

Settings

C1 REMINDER PANEL

(QR) D2-D4 Defualt Due Date:	**11/29/2024**	8:17:00 AM (your local time)	(QR) D2-D4 Revised Due Date:		(QR) D2-D4 Actual Date:	**11/28/2024**	8:17:07 AM (your local time)	(QR) D2-D
D5-D6 Default Due Date:	**12/5/2024**	8:17:00 AM (your local time)	D5-D6 Revised Due Date:		D5-D6 Actual Date:	**11/28/2024**	8:17:14 AM (your local time)	D5-D
D7-D8 Default Due Date:	**12/12/2024**	8:17:00 AM (your local time)	D7-D8 Revised Due Date:		D7-D8 Actual Date:	**11/28/2024**	11:03:03 AM (your local time)	D7-D



NOTIFICATIONS SENT

0 Result(s)

NIDEC APPROVALS & REFUSALS HISTORY

Steps approved

Step	Date of validation	User name
Creation	11/28/2024	Krzysztof Chłapek
D1	11/28/2024	Krzysztof Chłapek
D4	11/28/2024	Krzysztof Chłapek
D2-D4 Validation	11/28/2024	Krzysztof Chłapek
D6	11/28/2024	Krzysztof Chłapek
D5-D6 Validation	11/28/2024	Krzysztof Chłapek
D7	11/28/2024	Anis Othmani
D8	11/28/2024	Anis Othmani
D7-D8 Validation	11/28/2024	Dominik Dudek
8D Closing	11/28/2024	Dorota Siekaniec
8D closed	11/28/2024	Dorota Siekaniec

11 Result(s)

Steps rejected

Step	Date of refusal	User name	Reason for rejection
D5-D6 Validation	10/22/2024	Dominik Dudek	1. please update presentation about details regarding to new design of pins (why new design is better and how to prevent defects from occurri significant diferent between shapes of pins. 2. please also describe how the new gauge for check bended pins works (short presentation requa upload the picture showing camera in control preparation station in larger size (current photo is very small)
D5-D6 Validation	10/25/2024	Dominik Dudek	Unfortunately provide updated presentation still are not cleared and contained not enough details which explain why AVO changed pins desig design will prevent future occurrence. Also lack this clarification in 5 Why's. Why old design could cause the bend hall IC? How new design of pi Why's and presentation must be update. Also, we need more details regarding to new gauge for check hall IC position and so on. Attached pdf how exactly this gauge works. presentation must be update.
D5-D6 Validation	11/12/2024	Dominik Dudek	rejected on supplier request
D5-D6 Validation	11/19/2024	Dominik Dudek	In the D6 "presentation of change the shape of electrica...." - date must be corected
D7-D8 Validation	11/22/2024	Dominik Dudek	There is a lack of PFMEA and CP evidence in point D8.

D7-D8 Validation	11/26/2024	Dominik Dudek	Evidence in D8 (FMEA and Control Plan) should be updated regarding to corrective action

6 Result(s)

Forum

Filter

Keywords:

0 Result(s)

Quick Response (D1-D3)

ALERTS

-Component without PPAP

Plant issued a claim: NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.
Supplier: **AVO Carbon France (NMAP551841)**
Date of Claim: **9/10/2024**

Customer Contact: **Dudek Dominik**
SAP Vendor Code: **551841**
Date of QR: **9/11/2024**

Claim reference: **NMAP/551841/9/2024/1847**
Author: **DUDEK Dominik**
Update of QR: **9/10/2024**

Status: **Closed**
Type: **C1 : Customer claim**

CLAIM PPM: 0.00

D1-D3 evaluation score: 22

D1. Description of the problem

1.A WHAT IS THE PROBLEM ? USE 5W+2H TO DESCRIBE WHAT IS THE CURRENT SITUATION.

Problem description: **bent hall pins in connector**
What happened?: **bent hall pins in connector**

Part Number & Description: **Brush Mounting Plate Assy (503-779-99-99)**
Why is it a problem?: **no possibility to insert the plug**

Traceability of nok parts: **DMC 5037792416321971**
When did it happen? : **9/5/2024** 11:00:00 PM (your local time)

Recurrence: **No reccurent defect**
Who detected it?: **operator**

Defect S/R: **No**
Where was it detected? : **on production line**

How was it detected?: **during production**

How many parts ?: **1.00**

nok part picture / sketch:

ok part picture / sketch:

Other files::

1.B SUPPLIER PROBLEM SOLVING TEAM

Supplier Team

Add ar

Name		Contact	Email	Phone	Cell Phone	Fax	Position	Pr
Ben Mallek Bassem			bassem.benmallek@avocarbon.com	00216 58588811			Project quality engineer	{pr
Ghribi Mohamed Aymen		• mohamedaymen.ghribi@avocarbon.com	mohamedaymen.ghribi@avocarbon.com	0021658352210			Quality	Su
Haggui Marwen		• marwen.haggui@avocarbon.com	marwen.haggui@avocarbon.com	+21656057189	+21656057189		Customer Quality	Su
Othmani Anis		• anis.othmani@avocarbon.com	anis.othmani@avocarbon.com	216	+21658588818		Quality Manager	Su

NidecTeam

Contact	Email	Profile
DUDEK Dominik	dominik.dudek@nidec-ma.com	{profile} Local Quality (Local SQE) (Full) (Claim)
MOSTOWIK Marek	marek.mostowik@nidec-ma.com	{profile} Contributor (Claim)

1.C TOOL TO USE (DEFINED BY NIDEC)

Ishikawa: ☑ FTA: ☑ 5 Whys : ☑ LLC: ☑ Audit: ☐ Other: ☐

1.D PROBLEM DESCRIPTION FROM SUPPLIER / FIRST ANALYSE OF PROBLEM / POTENTIAL ROOT CAUSES

Problem description from Supplier: **bent hall pins in connector**

Samples of nok parts required at supplier location: ☑ Express shipping supplier account: **regular truck**

D2. Risk on similar products and processes

Can this defect happen on similar parts?: Comments (compulsory if yes): **(503-779-99-99)**

Other family product: ☐

Other machine: ☐

Other tooling: ☐

Other Nidec plants: ☐

Other: ☐

D3. Containment

WHAT ARE THE ACTIONS TO DETECT ALL NON-CONFORMING PARTS IN THE PROCESS FLOW?

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Delivery note and batch #	Responsible
Parts at Nidec plant	44,215.00	0.00	1.00			
Parts at Nidec logistics platform	0.00	0.00	0.00			
Parts at Nidecs customer (C1 claim)	0.00	0.00	0.00			

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Responsible	Delivery note and batch #
Parts in transport	0.00	0.00	0.00			
Parts at supplier / supplier platform	3,498.00	3,498.00	0.00	9/18/2024	Supplier	Delevery week 37
Parts at sub-supplier	0.00	0.00	0.00			
Other Nidec plant/s	0.00	0.00	0.00			

4 Result(s)

How are the ok parts identified?: **'100 Sorted regarding issue bent hall pins in connector**

First contained shipment information: **delevery Week 37**

How are the ok paletts identified?: **orange NIDEC identification**

How are the ok parts identified? :: Copie_de_Securing_identification.pdf

WHAT ARE THE IMMEDIATE ACTIONS TO PREVENT PRODUCTION/DELIVERY OF NOK PARTS?

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
Express delivery to Nidec to avoid production stop				
Nidec suspect stocks to be sent to supplier				

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
Display quality alert	Not required	Supplier	9/11/2024	9/11/2024
QRQC meeting in production line	Not required	Supplier	9/11/2024	9/11/2024
start selection in aVO	Not required	Supplier	9/11/2024	9/13/2024
start selection in NIDCE	Not required	Supplier	9/12/2024	9/20/2024

4 Result(s)

D4-D8

ALERTS

-Component without PPAP

Plant issued a claim: NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.
Supplier: **AVO Carbon France (NMAP551841)**
Creation Date: **9/10/2024**
Customer Contact: **Dudek Dominik**
SAP Vendor Code: **551841**
Date of QR: **9/11/2024**
Claim reference: **NMAP/551841/9/2024/1847**
Created by: **DUDEK Dominik**
Update of QR: **9/10/2024**
Status: **Closed**
Type: **C1 : Customer claim**
Date of D4-D8: **10/4/2024**
CLAIM PPM: 0.00
D4-D8 evaluation score: 75
Update of D4-D8: **11/26/2024**

D 4. Root cause of occurrence

Work out the root causes using first Ishikawa, then FTA and finally 5 why's (Tools to use chosen by Nidec).

ROOT CAUSE OF OCCURRENCE

the shape of pin of test on last station on electrical test have impact on the deformation of contact plat (HAll IC pin)

HOW WAS THE DEFECT REPRODUCED ?

After deep analysis and trails, our engineer team detect that the shape of the Pin of test in our electrical test has impact of the small deformation on the contact plat

Attachment:
Electrical pin of test.pptx

D 5. Root casue of non detection

ROOT CAUSE OF NON DETECTION :

Standard is not efficient
the small deviation on the Hall IC pin is not detectable

Attachments:

D 6. Countermeasure to non detection and occurrence

6.A ACTIONS FOR OCCURENCE

Action	Responsible	Date Plan	Date Clos.	Attachments Please click 'Save' to activate attachment field