Claim Management Panel

Supplier: **AVO Carbon France (NMAS609128)**

Type: **C2 : Production claim**

Problem description: **Fuse Choke Leg Height NOK**

Claim reference: **NMAS/609128/2/2024/1673**

Settings

C2/C3 REMINDER PANEL

(QR) D2-D3 Defualt Due Date :	**2/23/2024**	5:49:13 PM (your local time)	D2-D3 Revised Due Date:	(QR) D2-D3 Actual Date:	**2/26/2024**	10:57:35 AM (your local time)	(QR) D2-D
D4 Default Due Date :	**2/27/2024**	5:49:13 PM (your local time)	D4 Revised Due Date :	D4 Actual Date :	**2/29/2024**	3:53:37 PM (your local time)	D
D5-D6 Default Due Date:	**3/7/2024**	5:49:13 PM (your local time)	D5-D6 Revised Due Date:	D5-D6 Actual Date:	**3/7/2024**	11:15:41 AM (your local time)	D5-D
D7-D8 Default Due Date:	**3/7/2024**	5:49:13 PM (your local time)	D7-D8 Revised Due Date C2/C3:	D7-D8 Actual Date:	**4/1/2024**	1:59:32 PM (your local time)	D7-D



NOTIFICATIONS SENT

0 Result(s)

NIDEC APPROVALS & REFUSALS HISTORY

Steps approved

Step	Date of validation	User name
D8	4/1/2024	Marwen Haggui
8D Closing	4/2/2024	FRANCISCO MOYA
8D report approval after 8D Audit	4/2/2024	FRANCISCO MOYA
D1	2/22/2024	Alfons Lledo
D4 Validation	2/29/2024	Alfons Lledo
D2	2/29/2024	Marwen Haggui
D2	2/29/2024	Karim MNASRI
D2-D3 Validation	2/26/2024	Alfons Lledo
D3	2/29/2024	Marwen Haggui
D4	2/29/2024	Marwen Haggui
D5-D6 Validation	3/7/2024	Alfons Lledo
D6	3/7/2024	Alfons Lledo
D7	4/1/2024	Marwen Haggui
D7-D8 Validation	4/2/2024	Alfons Lledo
8D closed	4/2/2024	FRANCISCO MOYA

« ‹ 1 2 › 16 Result(s)

Steps rejected

Step	Date of refusal	User name	Reason for rejection
D4 Validation	2/29/2024	Alfons Lledo	Modify D4
8D Closing	3/25/2024	Alfons Lledo	Fill in 8.3

D7-D8 Validation	3/26/2024	FRANCISCO MOYA	Update point 8.3 with Audit

3 Result(s)

Forum

Filter

Keywords:

0 Result(s)

Quick Response (D1-D3)

ALERTS

-Component without PPAP

Plant issued a claim: NIDEC MOTORS & ACTUATORS (SPAIN) S.A.U
Supplier: **AVO Carbon France (NMAS609128)**
Date of Claim: **2/22/2024**
Customer Contact: **Lledo Alfons**
SAP Vendor Code: **609128**
Date of QR: **2/23/2024**
Claim reference: **NMAS/609128/2/2024/1673**
Author: **LLEDO Alfons**
Update of QR:
Status: **Closed**
Type: **C2 : Production claim**
CLAIM PPM: 0.00
D1-D3 evaluation score: 22

D1. Description of the problem

1.A WHAT IS THE PROBLEM ? USE 5W+2H TO DESCRIBE WHAT IS THE CURRENT SITUATION.

Problem description: **Fuse Choke Leg Height NOK**
What happened?: **Fuse Choke Leg Height measured at 10.19 - drawing spec 5.6min to 8max SPPC**
Part Number & Description: **BRUSH CARD HOLDER 11TA (A14116701A)**
Why is it a problem?: **Shortcircuit risk with the Motor Rear Cover**
Traceability of nok parts: **23041203**
When did it happen? : **2/20/2024** 12:00:00 AM (your local time)
Recurrence: **No reccurent defect**
Who detected it?: **11TA Line Operator**
Defect S/R: **Yes (S/security)**
Where was it detected? : **Assembly Line Electrical Test Station**
How was it detected?: **Shorticuit at Electrical Test**
How many parts ?: **14.00**

nok part picture / sketch:

ok part picture / sketch:

Other files::



1.B SUPPLIER PROBLEM SOLVING TEAM

Supplier Team

Add an existing contact:

Name		Contact	Email	Phone	Cell Phone	Fax	Position	Profile	Status
Haggui Marwen	✉	• marwen.haggui@avocarbon.com	marwen.haggui@avocarbon.com	+21656057189	+21656057189		Customer Quality	Supplier	Active
MNASRI Karim	✉	• karim.mnasri@avocarbon.com	karim.mnasri@avocarbon.com	+21656834809			Plant Quality Manager	Supplier	Active

NidecTeam

Contact	Email	Profile
LLEDO Alfons	Alfons.Lledo@nidec-ma.com	{profile} Local Quality (Local SQE) (Full) (Claim)
MACÍAS Juan Antonio	juan-antonio.macias@nidec-ma.com	{profile} Local Quality (Local SQE) (Full) (Claim)
MOYA FRANCISCO	francisco.moya@nidec-ma.com	{profile} Local Quality (Local SQE) (Full) (Claim)

1.C TOOL TO USE (DEFINED BY NIDEC)

Ishikawa: ☑ FTA: ☑ 5 Whys : ☑ LLC: ☑ Audit: ☑ Other: ☐

1.D PROBLEM DESCRIPTION FROM SUPPLIER / FIRST ANALYSE OF PROBLEM / POTENTIAL ROOT CAUSES

Problem description from Supplier: **Fuse Choke Leg Height NOK**

Samples of nok parts required at supplier location: ☑ Express shipping supplier account: **regular truck**

D2. Risk on similar products and processes

Can this defect happen on similar parts?: Comments (compulsory if yes): **(A14116701A)**

Other family product: ☐

Other machine: ☐

Other tooling: ☐

Other Nidec plants: ☐

Other: ☐

D3. Containment

WHAT ARE THE ACTIONS TO DETECT ALL NON-CONFORMING PARTS IN THE PROCESS FLOW?

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Delivery note and batch #	Responsible
Parts at Nidec plant	1,136.00	0.00	14.00		23041203	Nidec
Parts at Nidec logistics platform	0.00	0.00	0.00			
Parts at Nidecs customer (C1 claim)	0.00	0.00	0.00			

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Responsible	Delivery note and batch #
Parts in transport	0.00	0.00	0.00			
Parts at supplier / supplier platform	6,000.00	6,000.00	0.00	2/29/2024	Supplier	Delivery for Week 09
Parts at sub-supplier	0.00	0.00	0.00			
Other Nidec plant/s	0.00	0.00	0.00			

4 Result(s)

How are the ok parts identified?: **100% secured regarding NOK fuse choke height**

First contained shipment information: **first delevery for week 09**

How are the ok paletts identified?: **Orange NIDEC identification**

How are the ok parts identified? :: Identification of securing palette.docx

WHAT ARE THE IMMEDIATE ACTIONS TO PREVENT PRODUCTION/DELIVERY OF NOK PARTS?

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
Express delivery to Nidec to avoid production stop	Not required	Nidec	2/20/2024	

Nidec suspect stocks to be sent to supplier	Required	Nidec	2/20/2024	

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
QRQC meeting	Required	Supplier	2/23/2024	2/23/2024

1 Result(s)

D4-D8

ALERTS

-Component without PPAP

Plant issued a claim: NIDEC MOTORS & ACTUATORS (SPAIN) S.A.U
Supplier: **AVO Carbon France (NMAS609128)**
Creation Date: **2/22/2024**

Customer Contact: **Lledo Alfons**
SAP Vendor Code: **609128**
Date of QR: **2/23/2024**

Claim reference: **NMAS/609128/2/2024/1673**
Created by: **LLEDO Alfons**
Update of QR:

Status: **Closed**
Type: **C2 : Production claim**
Date of D4-D8: **2/29/2024**

CLAIM PPM: 0.00

D4-D8 evaluation score: 75
Update of D4-D8: **3/6/2024**

D 4. Root cause of occurrence

Work out the root causes using first Ishikawa, then FTA and finally 5 why's (Tools to use chosen by Nidec).

ROOT CAUSE OF OCCURRENCE

lack of standard : there is no standard of rework operation
Our Production team receive this palettes to checked and change the spring NOK and passed again in Electrical test.
After the rework, the pallet was still waiting for the availability of the electrical test, and due to the miscommunication between the production team and warehouse, the agent of the warehouse entered the pallet to be delivered

HOW WAS THE DEFECT REPRODUCED ?

passe the parts after rework with no control in electrical test

Attachment:

D 5. Root casue of non detection

ROOT CAUSE OF NON DETECTION :

lack of standard : parts are not re-controled and passed to electrical test
No risk analysis done

Attachments:

D 6. Countermeasure to non detection and occurrence

6.A ACTIONS FOR OCCURENCE