



The tray cavity sides that block easy insertion of the rod choke with base will be removed, allowing the parts to be packed with the coil legs oriented toward the bottom, similar to the packaging position in the new trays, as shown below.



The photo from the bottom side also show that the coil legs remain safe in this configuration :

