

Date	16.04.26	Improvement	Improvement Date	30.04.26
Line	Secondary Process		Process Name	Grinding
Issues	Output collection bin not properly closed and controlled leading to mixing of unground and finished parts		Responsibility	P.Suresh
Before			After	
				
Details: Output collection bin was not properly closed / controlled.			Details: Provide proper closing mechanism will be provided for output bins.	