Claim Management Panel

Supplier: **AVO Carbon France (NMAS609128)**

Type: **C2 : Production claim**

Problem description: **Lack Of Capacitor**

Claim reference: **NMAS/609128/8/2024/1822**

Settings

C2/C3 REMINDER PANEL

(QR) D2-D3 Defualt Due Date :	**8/12/2024**	1:16:36 PM (your local time)	D2-D3 Revised Due Date:	(QR) D2-D3 Actual Date:	**8/9/2024**	3:44:08 PM (your local time)	(QR) D2-
D4 Default Due Date :	**8/14/2024**	1:16:36 PM (your local time)	D4 Revised Due Date :	D4 Actual Date :	**10/16/2024**	11:30:17 AM (your local time)	I
D5-D6 Default Due Date:	**8/23/2024**	1:16:36 PM (your local time)	D5-D6 Revised Due Date:	D5-D6 Actual Date:	**10/18/2024**	10:02:39 AM (your local time)	D5-
D7-D8 Default Due Date:	**8/23/2024**	1:16:36 PM (your local time)	D7-D8 Revised Due Date C2/C3:	D7-D8 Actual Date:	**11/14/2024**	10:00:42 AM (your local time)	D7-I



NOTIFICATIONS SENT

0 Result(s)

NIDEC APPROVALS & REFUSALS HISTORY

Steps approved

Step	Date of validation	User name
D8	11/14/2024	Marwen Haggui
D1	8/9/2024	Alfons Lledo
D4 Validation	10/16/2024	Alfons Lledo
D2	10/16/2024	Anis Othmani
D2	10/16/2024	Marwen Haggui
D2-D3 Validation	8/9/2024	Alfons Lledo
D3	10/16/2024	Marwen Haggui
D4	10/16/2024	Marwen Haggui
D5	10/18/2024	Marwen Haggui
D5-D6 Validation	10/22/2024	Alfons Lledo
D6	10/18/2024	Marwen Haggui
D7	11/14/2024	Marwen Haggui
D7-D8 Validation	11/14/2024	Alfons Lledo
8D closed	11/14/2024	Alfons Lledo
8D Closing	11/14/2024	Alfons Lledo

« ‹ 1 2 › 16 Result(s)

Steps rejected

Step	Date of refusal	User name	Reason for rejection
D4 Validation	10/16/2024	Alfons Lledo	Update
D7-D8 Validation	11/12/2024	Alfons Lledo	Update acc mail sent 12-11-2024

2 Result(s)

Forum

Filter

Keywords:

0 Result(s)

Quick Response (D1-D3)

ALERTS

-Component without PPAP

Plant issued a claim: NIDEC MOTORS & ACTUATORS (SPAIN) S.A.U
Supplier: **AVO Carbon France (NMAS609128)**
Date of Claim: **8/9/2024**
Customer Contact: **Lledo Alfons**
SAP Vendor Code: **609128**
Date of QR: **8/12/2024**
Claim reference: **NMAS/609128/8/2024/1822**
Author: **LLEDO Alfons**
Update of QR:
Status: **Closed**
Type: **C2 : Production claim**
CLAIM PPM: 0.00
D1-D3 evaluation score: 22

D1. Description of the problem

1.A WHAT IS THE PROBLEM ? USE 5W+2H TO DESCRIBE WHAT IS THE CURRENT SITUATION.

Problem description: **Lack Of Capacitor**
What happened?: **NOK Motors due to lack of capacitor**
Part Number & Description: **BRUSH CARD HOLDER 11TA (A18116507G)**
Why is it a problem?: **Motor malfunction**
Traceability of nok parts: **2402191-01**
When did it happen? : **8/7/2024** 11:00:00 PM (your local time)
Recurrence: **No reccurent defect**
Who detected it?: **11TA Assembly Operator**
Defect S/R: **Yes (S/security)**
Where was it detected? : **Assembly Line Electrical Test**
How was it detected?: **Electrical Test Stops**
How many parts ?: **7.00**

nok part picture / sketch:

ok part picture / sketch:

Other files::

1.B SUPPLIER PROBLEM SOLVING TEAM

Supplier Team

Add an existing contact:

Name		Contact	Email	Phone	Cell Phone	Fax	Position	Profile	Status
Haggui Marwen		• marwen.haggui@avocarbon.com	marwen.haggui@avocarbon.com	+21656057189	+21656057189		Customer Quality	Supplier	Active
Othmani Anis		• anis.othmani@avocarbon.com	anis.othmani@avocarbon.com	216	+21658588818		Quality Manager	Supplier	Active

NidecTeam

Contact	Email	Profile

LLEDO Alfons	Alfons.Lledo@nidec-ma.com	{profile} Local Quality (Local SQE) (Full) (Claim)
MACÍAS Juan Antonio	juan-antonio.macias@nidec-ma.com	{profile} Contributor (Claim)
MOYA FRANCISCO	francisco.moya@nidec-ma.com	{profile} Contributor (Claim)

1.C TOOL TO USE (DEFINED BY NIDEC)

Ishikawa: ☑ FTA: ☑ 5 Whys : ☑ LLC: ☑ Audit: ☑ Other: ☐

1.D PROBLEM DESCRIPTION FROM SUPPLIER / FIRST ANALYSE OF PROBLEM / POTENTIAL ROOT CAUSES

Problem description from Supplier: **Lack Of Capacitor**

Samples of nok parts required at supplier location: ☐ Express shipping supplier account: **regular truck**

D2. Risk on similar products and processes

Can this defect happen on similar parts?: Comments (compulsory if yes): **A18116507G**

Other family product: ☐

Other machine: ☐

Other tooling: ☐

Other Nidec plants: ☐

Other: ☐

D3. Containment

WHAT ARE THE ACTIONS TO DETECT ALL NON-CONFORMING PARTS IN THE PROCESS FLOW?

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Delivery note and batch #	Responsible
Parts at Nidec plant	0.00	0.00	7.00			
Parts at Nidec logistics platform	0.00	0.00	0.00			
Parts at Nidecs customer (C1 claim)	0.00	0.00	0.00			

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Responsible	Delivery note and batch #
Parts in transport	0.00	0.00	0.00			
Parts at supplier / supplier platform	0.00	0.00	0.00			
Parts at sub-supplier	252.00	252.00	0.00	8/9/2024		will be deleved week 33
Other Nidec plant/s	0.00	0.00	0.00			

4 Result(s)

How are the ok parts identified?: **100% secured regarding lack of capacitor**

First contained shipment information: **first delevered secured will be delevered Week 33**

How are the ok paletts identified?: **Orange NIDEC identification**

How are the ok parts identified? ::

WHAT ARE THE IMMEDIATE ACTIONS TO PREVENT PRODUCTION/DELIVERY OF NOK PARTS?

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
Express delivery to Nidec to avoid production stop	Not required	Nidec	8/9/2024	
Nidec suspect stocks to be sent to supplier	Not required	Nidec	8/9/2024	

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
display quality alert	Not required	Supplier	8/9/2024	8/9/2024
QRQC meeting with all team	Not required	Supplier	8/9/2024	8/9/2024
reproduction of the defect and passed in AVO electrical test	Not required	Supplier	8/9/2024	8/9/2024

3 Result(s)

D4-D8

ALERTS

-Component without PPAP

Plant issued a claim: NIDEC MOTORS & ACTUATORS (SPAIN) S.A.U
Supplier: **AVO Carbon France (NMAS609128)**
Creation Date: **8/9/2024**
Customer Contact: **Lledo Alfons**
SAP Vendor Code: **609128**
Date of QR: **8/12/2024**
Claim reference: **NMAS/609128/8/2024/1822**
Created by: **LLEDO Alfons**
Update of QR:
Status: **Closed**
Type: **C2 : Production claim**
Date of D4-D8: **8/9/2024**
CLAIM PPM: 0.00
D4-D8 evaluation score: 75
Update of D4-D8:

D 4. Root cause of occurrence

Work out the root causes using first Ishikawa, then FTA and finally 5 why's (Tools to use chosen by Nidec).

ROOT CAUSE OF OCCURRENCE

Insufficient standard:

There is no pressure stability inside the welding machine

HOW WAS THE DEFECT REPRODUCED ?

Parts was welded with pressure (= 6.4 Bar) over than the maximum (= 5.5 Bar)
Parts were With strong welding

Attachment:

D 5. Root casue of non detection

ROOT CAUSE OF NON DETECTION :

insuffisant standard :

in the current standart there is no indication to avoid the manipulation of components.

Attachments:

D 6. Countermeasure to non detection and occurrence

6.A ACTIONS FOR OCCURENCE

Action	Responsible	Date Plan	Date Clos.	Attachments Please click 'Save' to activate attachment field