8D report

Customer plant:	Mahle Sempeter	**Supplier:**	AVO Carbon Germany	**Date of claim:**	30.07.2025
Customer contact:	Saza Babic	**AVO contact:**	Joachim Gehl		
Customer reference:	200123592	**AVO reference:**	250701 - 1026515		

QUICK RESPONSE (D1-D3)

This document must be issued within 24 hours after claim notification

D 1. Description of the problem

1.a What is the problem? Use 5W+2H to describe what is the current situation.

Problem description	2 wires are not welded together	What happened	2 wires are not welded together
		Why is it a problem	?
Incident type	Customer claim		
Part number AVO	1026515	When did it happen	30.07.2025
Part number Customer	16770253	Who detected it	Incoming inspection
Batch number	286972	Where was it detected	Incoming inspection
Recurrence	Non-recurrent	How was it detected	visually
Defect S/R	No	How many bad parts	?unknown
Standard process used	Yes		
When was the part produced?	Pressing machine => not relevant - welding machine in POI Grinding machine => not relevant, because no grinding error		

nOK part picture/ sketch



OK part picture/ sketch



1.b Problem solving team

Name	Position	Location	E-mail
Joachim Gehl	Quality Management	AVO Germany	joachim.gehl@avocarbon.com
Gunther Luschtinetz	Quality Management	AVO Germany	gunther.luschtinetz@avocarbon.com
Martin Röhr	Production	AVO Germany	
Mustafa Yorulmaz	Production	AVO Germany	
Khaled amri	Logistic	AVO Germany	

1.c Tools to use

Yes	Ishikawa		5why's		LLC		Audit		Other	

1.d First analyse of problem / potential root causes

Potential root cause(s):

If you use our expressnumber, please use only economic express.

Samples of nok parts required in plant for analyse: Yes

Express shipping number account: FedEx 186141300

D 2. Risk on similar products and processes

Can this defect happen on similar parts?

Other family product	No
Other line	No
Other tools/work station	No
Other	No

Comments (compulsory, if yes)

this is the only brush type where the 2 wires are welded together.

D 3. Containment

Sorting criterias (add additional sheets if needed)

Location in the supply chain	N° of involved parts	N° parts sorted	N° nok parts	Ppm	Date	Responsible
Parts at customer	---	---	---	---	---	Saza Babic
Parts in transport	---	---	---	---	---	---
Parts at AVO Germany stock	0	0	0	0	05.07.2025	Joachim Gehl
Parts at AVO production	---	---	---	---	---	---

First contained shipment information

Immediate actions to prevent production and delivery of nok parts ?

Containment actions	Responsible	Date planned	Date closed
Register the complaint + Quality alert	Joachim Gehl	05.08.2025	05.08.2025
Check the production-, quality- and maintenance data	Joachim Gehl	05.08.2025	05.08.2025
Information of all department leader during shop floor meeting QRQC	Joachim Gehl	05.08.2025	05.08.2025
Information to AVO France	Joachim Gehl	05.08.2025	05.08.2025