Claim Management Panel

Supplier: **AVO Carbon France (NMAP551841)**

Type: **C2 : Production claim**

Problem description: **lack of spring**

Claim reference: **NMAP/551841/2/2024/1675**

Settings

C2/C3 REMINDER PANEL

(QR) D2-D3 Defualt Due Date :	**2/28/2024**	1:12:03 PM (your local time)	D2-D3 Revised Due Date:	(QR) D2-D3 Actual Date:	**3/15/2024**	7:31:40 AM (your local time)	(QR) D2-D
D4 Default Due Date :	**3/1/2024**	1:12:03 PM (your local time)	D4 Revised Due Date :	D4 Actual Date :	**4/1/2024**	12:09:15 PM (your local time)	D
D5-D6 Default Due Date:	**3/12/2024**	12:12:03 PM (your local time)	D5-D6 Revised Due Date:	D5-D6 Actual Date:	**4/24/2024**	1:59:04 PM (your local time)	D5-D
D7-D8 Default Due Date:	**3/12/2024**	12:12:03 PM (your local time)	D7-D8 Revised Due Date C2/C3:	D7-D8 Actual Date:	**4/28/2024**	9:50:28 AM (your local time)	D7-D



NOTIFICATIONS SENT

0 Result(s)

NIDEC APPROVALS & REFUSALS HISTORY

Steps approved

Step	Date of validation	User name
D8	4/28/2024	Marwen Haggui
D1	2/27/2024	Dominik Dudek
D4 Validation	4/5/2024	Dominik Dudek
D2	4/1/2024	Marwen Haggui
D2-D3 Validation	3/15/2024	Dominik Dudek
D3	4/1/2024	Marwen Haggui
D4	4/1/2024	Marwen Haggui
D5	4/24/2024	Marwen Haggui
D5-D6 Validation	4/25/2024	Dominik Dudek
D6	4/24/2024	Marwen Haggui
D7	4/28/2024	Marwen Haggui
D7-D8 Validation	4/30/2024	Dominik Dudek
8D closed	5/7/2024	Dorota Siekaniec
8D Closing	5/7/2024	Dorota Siekaniec
Creation	2/27/2024	Dominik Dudek

15 Result(s)

Steps rejected

Step	Date of refusal	User name	Reason for rejection
D2-D3 Validation	3/4/2024	Dominik Dudek	"First contained shipment information:Shippement of week" ??? please enter wright shipment date and attache special label
D4 Validation	3/22/2024	Dominik Dudek	All factors from Ishikawa must be transfer to FTA.

2 Result(s)

Forum

Filter

Keywords:

0 Result(s)

Quick Response (D1-D3)

ALERTS

-Component without PPAP

Plant issued a claim: NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.
Supplier: **AVO Carbon France (NMAP551841)**
Date of Claim: **2/27/2024**

Customer Contact: **Dudek Dominik**
SAP Vendor Code: **551841**
Date of QR: **2/28/2024**

Claim reference: **NMAP/551841/2/2024/1675**
Author: **DUDEK Dominik**
Update of QR: **2/28/2024**

Status: **Closed**
Type: **C2 : Production claim**

CLAIM PPM: 0.00

D1-D3 evaluation score: 22

D1. Description of the problem

1.A WHAT IS THE PROBLEM ? USE 5W+2H TO DESCRIBE WHAT IS THE CURRENT SITUATION.

Problem description: **lack of spring**
What happened?: **lasck of spring**

Part Number & Description: **Brush mounting plate assy (503-773-99-99)**
Why is it a problem?: **lack of spring**

Traceability of nok parts: **231121**
When did it happen? : **2/24/2024** 12:00:00 AM (your local time)

Recurrence: **Recurrent defect**
Who detected it?: **operator**

Defect S/R: **No**
Where was it detected? : **CM4**

How was it detected?: **rejected on EOL**

How many parts ?: **1.00**

nok part picture / sketch:

ok part picture / sketch:

Other files::

1.B SUPPLIER PROBLEM SOLVING TEAM

Supplier Team

Add an existing contact:

Name		Contact	Email	Phone	Cell Phone	Fax	Position	Profile	Status
Haggui Marwen		• marwen.haggui@avocarbon.com	marwen.haggui@avocarbon.com	+21656057189	+21656057189		Customer Quality	Supplier	Active

NidecTeam

Contact	Email	Profile
DUDEK Dominik	dominik.dudek@nidec-ma.com	{profile} Local Quality (Local SQE) (Full) (Claim)

1.C TOOL TO USE (DEFINED BY NIDEC)

Ishikawa: ☑ FTA: ☑ 5 Whys : ☑ LLC: ☑ Audit: ☐ Other: ☐

1.D PROBLEM DESCRIPTION FROM SUPPLIER / FIRST ANALYSE OF PROBLEM / POTENTIAL ROOT CAUSES

Problem description from Supplier: **lack of spring**

Samples of nok parts required at supplier location: ☑ Express shipping supplier account: **regular truck**

D2. Risk on similar products and processes

Can this defect happen on similar parts?: Comments (compulsory if yes): **ALl reference CM4**

Other family product: ☐

Other machine: ☐

Other tooling: ☐

Other Nidec plants: ☐

Other: ☑

D3. Containment

WHAT ARE THE ACTIONS TO DETECT ALL NON-CONFORMING PARTS IN THE PROCESS FLOW?

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Delivery note and batch #	Responsible
Parts at Nidec plant	3,214.00	0.00	1.00			
Parts at Nidec logistics platform	0.00	0.00	0.00			
Parts at Nidecs customer (C1 claim)	0.00	0.00	0.00			

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Responsible	Delivery note and batch #
Parts in transport	18,513.00	18,513.00	0.00	2/29/2024		delevery for week 09
Parts at supplier / supplier platform	0.00	0.00	0.00			
Parts at sub-supplier	0.00	0.00	0.00			
Other Nidec plant/s	0.00	0.00	0.00			

4 Result(s)

How are the ok parts identified?: **100% secured regarding lack of spring**

First contained shipment information: **Shippement of week**

How are the ok paletts identified?: **100% secured regarding lack of spring**

How are the ok parts identified? ::

WHAT ARE THE IMMEDIATE ACTIONS TO PREVENT PRODUCTION/DELIVERY OF NOK PARTS?

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
Express delivery to Nidec to avoid production stop				
Nidec suspect stocks to be sent to supplier				

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
display quality alert	Not required	Supplier	2/28/2024	2/28/2024
QRQC meeting with all the team	Not required	Supplier	2/28/2024	2/28/2024

2 Result(s)

D4-D8

ALERTS

-Component without PPAP

Plant issued a claim:	NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.	Supplier:	**AVO Carbon France (NMAP551841)**	Creation Date:	**2/27/2024**
Customer Contact:	**Dudek Dominik**	SAP Vendor Code:	**551841**	Date of QR:	**2/28/2024**
Claim reference:	**NMAP/551841/2/2024/1675**	Created by:	**DUDEK Dominik**	Update of QR:	**2/28/2024**
Status:	**Closed**	Type:	**C2 : Production claim**	Date of D4-D8:	**3/6/2024**
		CLAIM PPM:	0.00		
D4-D8 evaluation score:	75			Update of D4-D8:	

D 4. Root cause of occurrence

Work out the root causes using first Ishikawa, then FTA and finally 5 why's (Tools to use chosen by Nidec).

ROOT CAUSE OF OCCURRENCE

the NOK parts was produced in the same periode of first
claim of lack spring NMAP/551841/10/2023/1559
and the correctives action are implimented in place
according to the action plan
the root cause is that the Flow of production rework
parts is not efficient and the location of the station
Rework

HOW WAS THE DEFECT REPRODUCED ?

Parts reworked Ok and not yet reworked (rework not
finish) are mixed with production good parts

Attachment:

D 5. Root casue of non detection

ROOT CAUSE OF NON DETECTION :

all the parts produced reworked are mixed with the
normal production

Attachments:

D 6. Countermeasure to non detection and occurrence

6.A ACTIONS FOR OCCURENCE

Action	Responsible	Date Plan	Date Clos.	Attachments Please click 'Save' to activate attachment field
integrate the rewokr jail (the same jail of tin rework)	Bilel bouzidi	11/13/2023	11/13/2023	
separate the rework station and put it outside the production line	Hamza Jbelli	11/13/2023	11/13/2023	Layout___Flow_chart_line.pdf

2 Result(s)

6.B ACTIONS FOR NON-DETECTION

Action	Responsible	Date Plan.	Date Clos.	Attachments Please click 'Save' to activate a