



mi.com

Service Record



WXIN2607070001928

Create Date: 2026-07-07 14:36:39
Service Center: Nr Rohtak Chowk Charkhi Dadri-Squo-M
Address: M/S Verma Enterprises , New Bus Stand Road, Near Rohtak Chowk, Rohila Tant House, Wali Gali Mi Care, Charkhi Dadri, Haryana-127306,HARYANA,127306

Served By: Surender
Service Center Code: XMIN5003
Phone Number: 9255958300
Contacts: Surender

Customer Information

Name: Akash lakhwan
Gender: male
User Type: End User
Contacts: 7206357472
Alternate: 7206357472
Email:
Address: ch dadri,HARYANA,127306

Products Information

Product Model: POCO M4 Pro 5G-IN-6GB+128GB-
IMEI (MEID): 861737062692285
SN: 39411/G2PK08683
Invoice Date:
Invoice Number:
Accessories: Mobile Phone、SIM Card Holder

Service Information

Service Type: OOW CID
Fault Description: Battery Damage/fragmentation/leakage,
Fault Description From Customer: Battery Damage/fragmentation/leakage
Inspection Remarks: 501 Replace Battery,521- Replace Battery cover Adhesive
Repair Method:
Parts Usage: 32020000UE4U(Adhesive-Battery Cover-Redmi Note11 5G);
460200008V1Y(Battery-BN5C-30%SOC);
Origin IMEI(MEID): 861737062692285
Origin SN: 39411/G2PK08683
New IMEI(MEID):
New SN:
Delivery Date:
Order Status: Pending For Inventory-OOW

Quality Information



861737062692285



Battery_appearance_damaged



Battery_Damage/fragmentation/leakage



0123456789

Service Charge

Service Charges:	350	CGST:	31.5(9%)	SGST:	31.5(9%)	Sub Total:	413
Parts Charges:							
Parts Name	Price	CGST Rate	SGST Rate	CGST	SGST	HS Code	
Adhesive-Battery Cover-Redmi Note11 5G	29	9%	9%	2.61	2.61	39199090	
Battery-BN5C-30%SOC	799	9%	9%	71.91	71.91	85076000	
Total:	Rs.1390.04						

Customer signature

Service Center signature