

Quick fix for sales sample rotation seats

iZi Turn and iZi Twist



Cap.:	Rev.: 01	Date: 2019-11-01	Pages.: 1 of 2	Name: Options to reduce scratches in sales samples 2019 11 01.docx
Done by: Erik van der veer	Sign:	Saved:		

The actions in this document are only intended for sales samples only

The rotation of the iZi Twist and iZi Turn seat can cause visible scratches on the plastic covers. This is unavoidable especially when dirt will get on the seat.

This is not a safety issue.


To avoid that seats used for demonstration will lose their mint condition appearance self-adhesive soft velcro might be applied. It is still important to keep the surfaces clean to avoid scratches.




Self adhesive soft velcro

Colour: black (white is used in this manual to make position better visible)

Scratch mark location 1



Scratch mark location 2



Quick fix for sales sample rotation seats

iZi Turn and iZi Twist



Cap.:	Rev.: 01	Date: 2019-11-01	Pages.: 2 of 2	Name: Options to reduce scratches in sales samples 2019 11 01.docx
Done by: Erik van der veer	Sign:	Saved:		

Scratch mark location 3

Only for iZi Turn: rotate in upright position



Upright: no contact bumpers with front brace



Reclined: contact bumpers with front brace