



BILL TO

Jordan Taylor
421 Maple Ridge Drive
Suite 204
Ashburn, VA 20147
(703) 555-0148
jordan.taylor@example.com

SERVICE LOCATION

421 Maple Ridge Drive, Suite 204, Ashburn, VA 20147
Upstairs cooling system diagnosis and approved repair.

ISSUE DATE	SERVICE DATE	FIELD RECORD	PAYMENT
Jul 20, 2026	Jul 20, 2026	Authorized And Completed	Unpaid

NATURE OF SERVICE REQUEST

Upstairs cooling system diagnosis and approved repair.

SERVICE DETAILS

Approved work **\$454.74**

DESCRIPTION	QTY	RATE	AMOUNT
Diagnostic visit and complete HVAC system evaluation	1	\$89.00	\$89.00
45/5 MFD dual-run capacitor replacement	1	\$245.00	\$245.00
System performance test and operating-temperature verification	1	\$95.00	\$95.00



SERVICE INVOICE

INV-004218
Jul 20, 2026


Job photo record

BEFORE PHOTO SKIPPED

Audited field decision recorded Jul 20, 2026, 10:05 AM. The technician continued without storing this checkpoint image.

AFTER PHOTO SKIPPED


Audited field decision recorded Jul 20, 2026, 12:15 PM. The technician continued without storing this checkpoint image.



JOB PHOTO

Supporting field evidence with a bounded caption that remains inside the reserved photo card area. Supporting field evidence with a bounded caption that remains inside the reserved photo card area. Supporting field evidence with a bounded...

Jul 20, 2026, 11:00 AM



JOB PHOTO

Supporting field evidence with a bounded caption that remains inside the reserved photo card area. Supporting field evidence with a bounded caption that remains inside the reserved photo card area. Supporting field evidence with a bounded...


Jul 20, 2026, 11:01 AM



SERVICE INVOICE

INV-004218
Jul 20, 2026


Job photos continued



JOB PHOTO

Supporting field evidence with a bounded caption that remains inside the reserved photo card area. Supporting field evidence with a bounded caption that remains inside the reserved photo card area. Supporting field evidence with a bounded...

Jul 20, 2026, 11:02 AM



JOB PHOTO

Supporting field evidence with a bounded caption that remains inside the reserved photo card area. Supporting field evidence with a bounded caption that remains inside the reserved photo card area. Supporting field evidence with a bounded...

Jul 20, 2026, 11:03 AM



SERVICE INVOICE

INV-004218
Jul 20, 2026

Invoice summary & approval

WORK SUMMARY & NOTES

Replaced the failed dual-run capacitor, verified compressor amperage, and tested a full cooling cycle.

Job cost	\$340.00
Service call	\$89.00
Subtotal	\$429.00
Tax (6.00%)	\$25.74
Total	\$454.74
Deposit / paid	\$0.00
BALANCE DUE	\$454.74

PAYMENT STATUS: UNPAID

Reference INV-004218 with payment. Cash, check, or electronic payment may be recorded separately. Card details are never collected on this document.

FIELD AUTHORIZATION RECORD

AUTHORIZATION OF REPAIR

Customer authorized the listed diagnosis, parts, labor, and good estimate before work began. Additional charges require renewed authorization.

Jordan Taylor

Customer | Jul 20, 2026, 10:12 AM

COMPLETION OF WORK

Customer acknowledged satisfactory completion of the listed work after service and final job evidence.

Jordan Taylor

Customer | Jul 20, 2026, 12:22 PM

Thank you for choosing Fast Track.

Questions? Call (703) 899-5615 or email info@fasttrackdmv.org.