



MASTERSCAN ENGINEERING

INSPECTION WITH INTEGRITY

+65 6261 4766 / +65 9451 6487 +65 6261 4768 sales@masterscan.com.sg
GST/Co. Reg. No.: 200506867D 29 Benoi Road, Pioneer Lot, Singapore 629922
www.masterscan.com.sg



REPORT NO : MSE/PEC/SRC/2025/MT/051

MSE/REF/NO : D2-25-7616

DATE OF TESTING : 17.10.2025

PAGE : 1 OF 2

MAGNETIC PARTICLE TEST REPORT

CLIENT : PEC PTE LTD
14, INTERNATIONAL BUSINESS PARK
SINGAPORE 609922

LOCATION : FIELD

PROJECT TITLE : 2025 RCC EVENT: PIPING REPAIR

JOB NO : 81111867

ITEM TESTED : WELDED JOINTS

TEST PROCEDURE : MSE/TP/MT/005 REV.8

ACCEPTANCE SPEC : ASME B31.3 - 2022 Ed ./Clause 344.3.2

TEST METHOD : VISIBLE WET CONTINUOUS METHOD

EQUIPMENT : CONTOUR PROBE, AC ELECTROMAGNETIC YOKE (Sr.No : 9262)

POLE SPACING : 3 INCHES TO 6 INCHES

CALIBRATION : FIELD INDICATION STRIP AND 10 LBS LIFTING BLOCK (MSE-LB-02)

SURFACE CONDITION : AS WELD AND CLEANED

MATERIAL : CARBON STEEL (NACE)

SURFACE TEMPERATURE : AMBIENT (25 to 35°C)

CONTRAST PAINT : MR72 WHITE PAINT (LOT NO :2401059)

MAGNETIC INK : MR76S BLACK INK (LOT NO : 2401048)

PARTICLE APPLICATION : Spraying

LIGHT METER SERIAL NO : 1613475 / 1613477

LIGHT/SOURCE INTENSITY : NATURAL LIGHT > 1080 Lux

SCOPE OF EXAMINATION : MAGNETIC PARTICLE TESTING WAS CARRIED OUT ON WELDED JOINTS.

AREA OF EXAMINATION : TESTED LOCATION PLEASE REFER TO THE ATTACHED DATA & DRAWING SHEETS.

FINDINGS : NO RELEVANT INDICATIONS WERE DETECTED AT THE TIME OF TESTING .
ITEM TESTED WERE FOUND COMPLIED TO SPECIFICATION.

RESULT : ACCEPTABLE

REPORTED BY : M.KAJENDRAN
NDT LEVEL II
DATE : 17.10.2025

SIGNATURE :

REVIEWED BY : SURENDRAKUMAR P.V
ASNT NDT Level III



FORM NO : MSE/NDT/MT/001 Rev.2

The report is issued under the following terms and conditions:

- (1) The report shall not be reproduced in part or in full unless approved in writing has been given by MASTERSCAN ENGINEERING.
- (2) The report shall not be used in any publicity material without the written consent of MASTERSCAN ENGINEERING.
- (3) MASTERSCAN ENGINEERING agrees to use reasonable diligence in the manner of performing the tests, inspections or services but no warrants are given and none may be implied directly or indirectly relating to MASTERSCAN ENGINEERING test results, services or facilities.
- (4) MASTERSCAN ENGINEERING shall under no circumstances be liable for collateral, special or consequential damage.
- (5) This is a test report and not a MASTERSCAN certificate of quality. The significance of the report is subject to the adequacy and representative character of the sample(s) and to the comprehensiveness of the tests, examinations or survey requested or made.
- (6) The test report is prepared based on the test(s) requested and on the specific items submitted / sampled to MASTERSCAN ENGINEERING for testing. MASTERSCAN ENGINEERING assumes no responsibility for variations in quality or other characteristics of product produced on supplied under conditions over which MASTERSCAN ENGINEERING has no control. MASTERSCAN ENGINEERING'S testing does not constitute a recommendation for, or endorsement of the product or material tested.
- (7) The results reported herein have been performed in accordance with the terms of accreditation under the Singapore Accreditation Council



MASTERSCAN ENGINEERING

INSPECTION WITH INTEGRITY

+65 6261 4766 / +65 9451 6487 +65 6261 4768 sales@masterscan.com.sg
GST/Co. Reg. No.: 200506867D 29 Benoi Road, Pioneer Lot, Singapore 629922
www.masterscan.com.sg



MAGNETIC PARTICLE TEST REPORT

REPORT NO :MSE/PEC/SRC/2025/MT/051

PAGE : 2 OF 2

S/N	JOINT NO	SIZE (INCH)	SCH	SHT NO	MATERIAL	WELDER NO.		WELDING PROCESS	WELD TYPE	Distance from Reference Point (mm)	Type of indication	RESULT	REMARKS
						ROOT	CAPPING						
DRAWING NO : 25-74-009						LINE No : RV-74002-1.5"-3PS1G						LINE CLASS : 3PS1G	
1	017	1.50	80	001	CS (NACE)	58812	58812	GTAW	-	-	-	ACCEPTABLE	81111867

Reported By :
M.KAJENDRAN
NDT LEVEL II



DATE : 17.10.2025

Reviewed by:
SURENDRAKUMAR P.V
ASNT NDT Level III



DATE : 18.10.2025

Witnessed By :

DATE :

Reviewed By :

DATE :

The report is issued under the following terms and conditions.

- (1) The report shall not be reproduced in part or in full unless approved in writing has been given by MASTERSCAN ENGINEERING.
- (2) The report shall not be used in any publicity material without the written consent of MASTERSCAN ENGINEERING.
- (3) MASTERSCAN ENGINEERING agrees to use reasonable diligence in the manner of performing the tests, inspections or services but no warrants are given and none may be implied directly or indirectly relating to MASTERSCAN ENGINEERING test results, services or facilities.
- (4) MASTERSCAN ENGINEERING shall under no circumstances be liable for collateral, special or consequential damage.
- (5) This is a test report and not a MASTERSCAN certificate of quality. The significance of the report is subject to the adequacy and representative character of the sample(s) and to the comprehensiveness of the tests, examinations or survey requested or made.
- (6) The test report is prepared based on the test(s) requested and on the specific items submitted / sampled to MASTERSCAN ENGINEERING for testing. MASTERSCAN ENGINEERING assumes no responsibility for variations in quality or other characteristics of product produced on supplied under conditions over which MASTERSCAN ENGINEERING has no control. MASTERSCAN ENGINEERING'S testing does not constitute a recommendation for, or endorsement of the product or material tested.
- (7) The results reported herein have been performed in accordance with the terms of accreditation under the Singapore Accreditation Council