CSE200: Computer Aided Engineering Drawing

Tahsin Tariq Banna

Lecturer,
Department of Computer Science and Engineering,
East West University

Common Onshape Documentation Links

- Features and Parts Lists
- Sketch Basics
  - Sketch Tools
  - Automatic Inferencing
  - Dimension Tool
- Feature Basics
  - Feature Tools
- Drawing

3D Part



Multiview Projection



(b)

Onshape



Sectional View





Task



(a)



(b)

Fig. 9.36

Task



Ø40
Ø16
16
23
20
40
70
23
Ø20
20
16
40
16
B
A

(a)



X1
Ø16
Ø40
TV
A
B
70
X
Y
23
23
20
Ø20
R20
LHSV
Y1
Sectional FV

(b)