open source open source hardware wyolum.com R12 R2 R1 To avoid damaging tracks, do not snap off. Use hacksaw to separate boards if required. \_ \_ R13 KlokTHREEjr github.com/wyolum/KlokTHREEjr 5V GND LDR4 LDR1 DAT\_IN CLK\_IN R15 CONNECT MOAR
LEDS HERE
DATICLK
P2 \_ \_ R14 KlokTHREEjr
github.com/wyolum/KlokTHREEjr

https://github.com	/wyolum/KlokTHREEjr	
www.wyolum.com	•	
Sheet: File: KlokTHREEjr.k	icad_pcb	
Title: KlokTHR	EEjr	
Size: A3	Date: 2018-01-08	Rev: rev 1
KiCad E.D.A. kicad	no-vcs-found-bf44d3961ubuntu16.04.1	ld: 1/1
	7	8

3