

VANTARA PETROCHEM - UNIT 3

COMPRESSOR INSPECTION REPORT

Report Number:	INS-2023-C102-001
Equipment Tag:	C-102
Equipment Type:	Reciprocating Compressor - H2 Recycle
Inspection Date:	2023-11-10
Inspector:	Rajesh Kumar (EMP-001) / Priya Sharma (EMP-002)
Inspection Type:	Annual Turnaround Inspection

INSPECTION FINDINGS

Cylinders:

- Cylinder 1: Bore within tolerance, minor scoring - polished
- Cylinder 2: Satisfactory condition
- Cylinder 3: Packing replaced (WO-2024-003 scope)

Valves:

- All suction and discharge valves replaced per planned scope
- Previous valves showed fatigue cracking (reference WO-2023-015)

Piston/Rods:

- Piston rod runout within limits
- Rider bands replaced on all pistons

Bearings/Crossheads:

- Main bearings within tolerance
- Crosshead pin bearings replaced

Foundation:

- All anchor bolts retorqued
- Foundation grout inspected - no cracks
- Reference: Previous vibration issue (INC-2023-011)

CERTIFICATION

Compressor C-102 restored to service following annual overhaul.
Next major inspection due: November 2024

Inspectors: Rajesh Kumar, Priya Sharma
Date: 2023-11-10