

VANTARA PETROCHEM - UNIT 3

DISTILLATION COLUMN INSPECTION REPORT

Report Number:	INS-2024-D601-001
Equipment Tag:	D-601
Equipment Type:	Atmospheric Distillation Tower
Inspection Date:	2024-03-18
Inspector:	Arvind Menon (EMP-005) / Rajesh Kumar (EMP-001)
Inspection Type:	Turnaround Internal Inspection

INSPECTION FINDINGS

Shell/Heads:

- UT thickness survey - all readings above minimum
- No external corrosion under insulation detected

Trays:

- Trays 1-17: Satisfactory condition
- Trays 18-22: Heavy fouling confirmed (ref: WO-2023-011 gamma scan)
- Cleaning completed, bubble caps inspected
- Trays 20, 21: 4 bubble caps replaced (damaged)
- Trays 23-42: Satisfactory

Downcomers:

- All downcomers clear
- Seal pans intact

Nozzles/Manways:

- All nozzle welds inspected - satisfactory
- Manway gaskets replaced

CERTIFICATION

D-601 restored to service following turnaround inspection.
Next internal inspection: March 2028 (4-year cycle per RBI)

Inspectors: Arvind Menon, Rajesh Kumar
Date: 2024-03-18
Reference Work Order: WO-2024-005