

VANTARA PETROCHEM - UNIT 3

VIBRATION ANALYSIS REPORT

Report Number:	INS-2024-P101A-VIB-001
Equipment Tag:	P-101A
Equipment Type:	Centrifugal Pump
Analysis Date:	2024-02-15
Analyst:	Priya Sharma (EMP-002)
Analysis Type:	Routine Vibration Monitoring

VIBRATION READINGS

Measurement Point	Velocity (mm/s)	Alarm Level	Status
Pump DE Horizontal	2.1	4.5	GOOD
Pump DE Vertical	1.8	4.5	GOOD
Pump DE Axial	1.2	3.5	GOOD
Pump NDE Horizontal	2.3	4.5	GOOD
Pump NDE Vertical	1.9	4.5	GOOD
Motor DE Horizontal	1.5	4.5	GOOD
Motor DE Vertical	1.3	4.5	GOOD
Motor NDE Horizontal	1.4	4.5	GOOD
Motor NDE Vertical	1.2	4.5	GOOD

ANALYSIS NOTES

All vibration levels within acceptable limits. No indication of bearing wear, misalignment, or imbalance. Pump operating normally following seal replacement in January 2024 (WO-2024-001). Running on approved VantaLube Premium 320 lubricant.

Continue routine monthly monitoring. No action required.