

### LABORATORY WORK SHEET

10 10

Name of the Student M.A.O.K.L. SAL CHARAN	
Class / Con / Trans	Tron Humber
Class CSM-L Semester IST  Course Code Am E DO2 Course Name Manufacturing  Name of the Course Female Man	23951 466 72
Name of the Course Faculty Mr. v. Mahidhan Reddy	Faculty ID TARE 10333-
Exercise Number: 10 Week Number 19	Date : 0.5 De Centiles 202

#### DAY TO DAY EVALUATION:

Marks	Am/	Algorithm / Procedure Source Code		Program Execution	V0:2-	
	Preparation	Performance in the Lab	Calculations and Graphs	Results and Error Analysis	Viva - Voce	Total
Max. Marks	4	4	4	4 4	4	20
Obtained	N	4 -	A	4	H	80

Signature of Faculty

### START WRITING FROM HERE:

Objective: Preparation of stepped pulley with pla material using the principle of 30 printing & colditive manufacturing techniques as per drawing.

Resources: manufacturing tools - 30 printa with attachments

materials regulated: 30 printing Machine. It is the construction of a 3-climensional object from a cap model of a oligital 30 model. It is an additive manufacturing process in which a physical object 15 created from a cligital design.

Equipment needed: Design software (CAT, A social work etc.)

Cura Sticing software Elegoo-plus 30 printer.

General principle of 3p-printing:

1. Modeling: It takes virtual blue prints from modeling software such as computer aided design (CAO) and stices them into digital Cross-Section for the machine to successively user as a guideline for printing.

I Printing: To perform a print, the machine reads the design from an STC or ogs tile and lays down successive design layers of material to build the model from a suite of own. Section.

3. Finishing: After finishing the support are removed to get the finished components.

# Procedure of 3D-printing:

A Person Creates

a 30 image of an

item using a CAD

software program.

informations sent to the printerThe prints forms the item deporting the material in layers starting from the layer on to a platform or laser some class light are used to harden the particular.

step-1: To create a 30 image of an item using a CAD or modelling. Software program and. Seve It as STL or OBL formal file.

Step-2: In this STL or OBL file is sticed using cura software with required parameters and paintfile is uploaded to 3D-printer for prioting or capied.

Pendeive.


# 2.A) Initial testing of the 3p - printer:

- I push the filament to the bottom of print head.
- I click purpose extrudent
- I click load them the temperature of nozzle will be automatically heated to 200°C.
- I After the nozzle is preheated to 200°C, click the teed to extrade the filament from the nozzle.
- Printing-
  - 2. B) After testing the printer:
- I gusuit the pendeive into USB deive port of the
- V click ten main menu select the material as

  PLA; on Selection of material respective temperature

  of both of them is raised to a prest temperature.
- I click on the main menu and select home.
- Then select the model folder and select the required model tolder and select the required model and confirm prodel.
- when the nozzer and heat reaches the present temperature or, y and z ares will return to zero, and starts printing.

step-3: After printing, the Support are elemented to get the finished component.



The PLA filament Coire from spool passes through feeding system and is liquified. In liquified chamber due to heat of the chamber and is extruded through nozzle tip a chamber and fine dia fibre of 0.2 mm diameter through nozzle tipas a tin and material is deposited on the base layer by layer and together because the layers are in the motten state on the nozzle tip more upward until the finished product is obtained.



### LABORATORY WORK SHEET

1.44	director trice con-	0.000			Roll Number					-				
					100	2	9	5	1	A	6	6	P	2
C	ourse Code :		Course Name :		- W	3	1.			1		1		
N	lame of the Co	ourse Faculty.						Fa	cult	y ID				
			Week t	dumber		1121127	.,	.D	ate		_##			
E	xercise Numb	per :	YYUUN I	tons-										
1	YAD OT YAD	EVALUATION	1.		17.2	0.00			Wast.		703		H	
	Marks	Am / Preparation	Algorithm / Procedure	Source Code				n Execution				liva -	Total	tal
			Performance in the Lab	Calculations and Graphs	Results and Error Analysis				Voce	9	1500			
	May Marke	or Marks 4 4	4			4				4		2	0	
	MITTER MITTER													

Signature of Faculty

#### START WRITING FROM HERE:

Obtained

### Pre Cautions:

- 1. Initial setting of level has to be done.
- 2. Do not expose the mater in a machine to direct Sunlight, creasive heat, open I naked flame, salty or corrosive gases, moisture or dust.

  3. Do not put the printer near devices that contain magnety or produce magnetic fields.
  - 4. 00 not connect to an Ac power outlet controlled by will switches or automatic times.

Result: The CATIA 3-demensional modeled till.

STI Is uploaded to the string software to cleate model print file to 3D printer to print 3D object.

Moley