







PARTS LIST								
ITEM	QTY	P	PART NUMBER			DESCRIPTION		
1	1	shaft	shaft					
2	ISO 41	ISO 4162 - M12 x 45			Hexagon flange bolts -			
					Small Ser	ries		
3	1	430047	43004700			MAE-DNM-SM/I-B3-4/PO		
					LIG-Stan	dard		
					Three-Ph	ase Mo	tors	
					SM/I, Mo	del B3,	4-polig,	
					approx. 1500 1/min.			
4	1	fan	fan					
5	2	SKF_S`	SKF_SY 35 TDW		AYP_001_HC_HH_HY-AY			
					L_001_H	P-Y-bea	aring	
					plummer	block (	units	
6	1	base 2	base 2					
7 24		ISO 41	ISO 4161 - M12			Hexagon nuts with		
						flange-coarse thread		
8	1	retainii	retaining ring					
9	2	key tap	key tapered pushing		to fix belt pulleys			
10	1	g500-H	g500-H1500_1		STEP AP214			
11	4	ISO 41	.62 - M12 x	52 - M12 x 70		Hexagon flange bolts -		
				Small Series				
Designed by	Checked by	Approved by		Date		_		
saif-aldain aqe	erno baka	erno baka	,		30/5/2023			
BME			Gearbox selection					
						Edition	Sheet	
				1	1			