Release Notes

ALP-5.0 API

VIALUX

ViALUX Messtechnik + Bildverarbeitung GmbH
Am Erlenwald 10
09128 Chemnitz
Deutschland

Telefon: +49 (0) 371 33 42 47 0
Fax: +49 (0) 371 33 42 47 10
Web: www.vialux.de
E-Mail: dlp@vialux.de

© 2004-2025 ViALUX GmbH. All rights reserved.

ALP-5.0 API Release Notes

Introduction

This document summarizes release 1 of the ALP-5.0 application programming interface (API). The following remarks are to indicate additional programming capabilities.

These release notes apply to ALP-5.0 components of the following versions:

- API (alp50.dll): 1.0.1.13
- API header file (alp.h): 28
- ALP API description (ALP-5.0 API description.pdf): 2025-02-27

ALP APIs are compatible to each other regarding their software interface. However, they are specialized to support individual hardware versions. The ALP hardware/software table summarizes the combinations for the five versions of ALP-4 and ALP-5 DLLs:

- **ALP-4.1** (alpD41.dll)
- **ALP-4.2** (alpV42.dll)
- **ALP-4.3** (alp4395.dll)
- **ALP-4.4** (alp44.dll)
- **ALP-5.0** (alp50.dll)

ALP hardware/software table:

DLP DMD Chip	DLP Controller FPGA	Supporting ALP-4 Software	ViALUX Product
DLP650L DLP7000 DLP9500	DLPC410	ALP-4.1 (as an option)	Discovery™4100 Development Kit
DLP7000		ALP-4.2	V-7000
DLP650L		ALP-4.3	V-650L
DLP7000			V-7001
DLP9500			V-9501
DLP6500	DLPC910		V-6501
DLP9000X			V-9001
DLP7000	DLPC410	ALP-4.4	V-7001+
DLP650L		ALP-5.0	V-650L02
DLP7000			V-7002
DLP9500			V-9502
DLP6500	DLPC910		V-6502
DLP9000X			V-9002



Summary of Contend

General Notes

Release 1 is the initial version of ALP-5.0.

It has the same, compatible set of features as release 23 of the ALP-4.3 / ALP-4.4 high-speed API. Please see the ALP-5.0 *high-speed* API description for details. Additional features and current limitations are described below.

Additional Features

A new Interface (PCIe) is now available. Using PCIe will require some additional setup steps before the device can be used. Refer to the ALP-5.0 Quick Start Guide and the “AlpDevAlloc” chapter of the ALP-5.0 API description for further details. The software interface, however, will stay unchanged in comparison with previous ALP versions.

Limitations

- The V-9002 only supports a DMD input clock rate of 480 MHz. Support of 400 MHz will be added in upcoming release updates.

Deployment

ALP-5.0 Release 1 is included in the ALP-5.0 available on the ViALUX website for download.