	Cpu speed: 3000 cy		skip O, Progra — NU UP DI PL ZR NA PE I	□ X
01A3:13B4 FF8E026 -t		D PTR [BP		SS:FFEC=015A
AX=0015 BX=0022 DS=000F ES=FFFF 01A3:13B8 5D -t		SP=FFEA IP=13B8	BP=FFEA SI=0009 DI=FI NV UP DI PL NZ NA PE I	
AX=0015 BX=0022 DS=000F ES=FFFF 01A3:13B9 EB21 -t		IP=13B9	BP=0000 SI=0009 DI=F NV UP DI PL NZ NA PE I	
DS=000F ES=FFFF 01A3:13DC ZE	SS=073F CS=01A3 CS:	IP=13DC	BP=0000 SI=0009 DI=F NU UP DI PL NZ NA PE I	NC
01A3:13DD 8926114 -t		111,SP		CS:4A11=FFEC
AX=0015 BX=0022 DS=000F ES=FFFF 01A3:13E1 ZE			BP=0000 SI=0009 DI=FI NV UP DI PL NZ NA PE I	
01A3:13E2 8C161D4	la M OV [4A	1D1,SS		CS:4A1D=073F
DOSBox 0.74-3,	Cpu speed: 3000 cy	cles, Frame:	skip 0, Progra —	□ X
AX=0015 BX=0022 DS=000F ES=FFFF 073F:0156 4A -t	CX=0070 DX=0001 SS=073F CS=073F DEC DX	SP=FFF2 IP=0156	BP=0000 SI=0009 DI=F NV UP EI PL NZ AC PE	
AX=0015 BX=0022 DS=000F ES=FFFF 073F:0157 75F4 -t	CX=0070 DX=0000 SS=073F CS=073F JNZ 014	IP=0157		
AX=0015 BX=0022 DS=000F ES=FFFF 073F:0159 CC			BP=0000 SI=0009 DI=F NV UP EI PL ZR NA PE	
-t				
	CX=0070 DX=0000		BP=0000 SI=0009 DI=F NV UP DI PL ZR NA PE	

BB DOSBox 0.74-3,	Cpu speed: 3000 cycles, Frame	eskip 0, Progra — 🗆 🗙
AX=000D BX=0015 DS=000F ES=FFFF 073F:014D 46 -t	CX=0070 DX=0001 SP=FFF2 SS=073F CS=073F IP=014D INC SI	
AX=000D BX=0015 DS=000F ES=FFFF 073F:014E 02C3 -t	CX=0070 DX=0001 SP=FFF2 SS=073F CS=073F IP=014E ADD AL,BL	
AX=0022 BX=0015 DS=000F ES=FFFF 073F:0150 8804 -t	CX=0070 DX=0001 SP=FFF2 SS=073F CS=073F IP=0150 MOV [SI],AL	
AX=0022 BX=0015 DS=000F ES=FFFF 073F:0152 8AC3 -t	CX=0070 DX=0001 SP=FFF2 SS=073F CS=073F IP=0152 MOV AL,BL	
AX=0015 BX=0015 DS=000F ES=FFFF 073F:0154 8A1C	CX=0070 DX=0001 SP=FFF2 SS=073F CS=073F IP=0154 MOV BL,[SI]	
_		
	Cpu speed: 3000 cycles, Frame	eskip 0, Progra — 🗆 🗙
	Cpu speed: 3000 cycles, Frame CX=0070 DX=0002 SP=FFF2 SS=073F CS=073F IP=0150 MOV [SI],AL	BP=0000 SI=0008 DI=FFFF
DOSBox 0.74-3, AX=0015 BX=000D DS=000F ES=FFFF 073F:0150 8804	CX=0070 DX=0002 SP=FFF2 SS=073F CS=073F IP=0150 MOU [SI],AL	BP=0000 SI=0008 DI=FFFF NV UP EI PL NZ AC PO NC DS:0008=60 BP=0000 SI=0008 DI=FFFF
DOSBox 0.74-3, AX=0015 BX=000D DS=000F ES=FFFF 073F:0150 8804 -t AX=0015 BX=000D DS=000F ES=FFFF 073F:0152 8AC3 -t	CX=0070 DX=0002 SP=FFF2 SS=073F CS=073F IP=0150 MOV [SII,AL] CX=0070 DX=0002 SP=FFF2 SS=073F CS=073F IP=0152 MOV AL,BL CX=0070 DX=0002 SP=FFF2	BP=0000 SI=0008 DI=FFFF NV UP EI PL NZ AC PO NC DS:0008=60 BP=0000 SI=0008 DI=FFFF
DOSBox 0.74-3, AX=0015 BX=000D DS=000F ES=FFFF 073F:0150 8804 -t AX=0015 BX=000D DS=000F ES=FFFF 073F:0152 8AC3 -t AX=000D BX=000D DS=000F ES=FFFF 073F:0154 8A1C -t	CX=0070 DX=0002 SP=FFF2 SS=073F CS=073F IP=0150 MOU ISII,AL CX=0070 DX=0002 SP=FFF2 SS=073F CS=073F IP=0152 MOU AL,BL CX=0070 DX=0002 SP=FFF2 SS=073F CS=073F IP=0154 MOU BL,ISII CX=0070 DX=0002 SP=FFF2	BP=0000 SI=0008 DI=FFFF NV UP EI PL NZ AC PO NC DS:0008=60 BP=0000 SI=0008 DI=FFFF NV UP EI PL NZ AC PO NC BP=0000 SI=0008 DI=FFFF NV UP EI PL NZ AC PO NC

DOSBox 0.74-3,	Cpu speed: 3000 cycles, Frame	eskip 0, Progra — 🗆 🗙
AX=0008 BX=0008 DS=000F ES=FFFF 073F:0154 8A1C -t	CX=0070 DX=0003 SP=FFFZ SS=073F CS=073F IP=0154 MOV BL,[SI]	
AX=0008 BX=000D DS=000F ES=FFFF 073F:0156 4A -t	CX=0070 DX=0003 SP=FFF2 SS=073F CS=073F IP=0156 DEC DX	
AX=0008 BX=000D DS=000F ES=FFFF 073F:0157 75F4 -t	CX=0070 DX=0002 SP=FFF2 SS=073F CS=073F IP=0157 JNZ 014D	
AX=0008 BX=000D DS=000F ES=FFFF 073F:014D 46 -t		BP=0000 SI=0007 DI=FFFF NV UP EI PL NZ NA PO NC
AX=0008 BX=000D DS=000F ES=FFFF 073F:014E 02C3	SS=073F CS=073F IP=014E ADD AL,BL	NV UP EI PL NZ NA PO NC
BB DOSBox 0.74-3,	Cpu speed: 3000 cycles, Frame	eskip 0, Progra — 🗆 🗙
AX=0005 BX=0008 DS=000F ES=FFFF 073F:0157 75F4 -t	CX=0070 DX=0003 SP=FFF2 SS=073F CS=073F IP=0157 JNZ 014D	
AX=0005 BX=0008 DS=000F ES=FFFF 073F:014D 46 -t	CX=0070 DX=0003 SP=FFFZ SS=073F CS=073F IP=014D INC SI	
AX=0005 BX=0008 DS=000F ES=FFFF 073F:014E 02C3 -t	CX=0070 DX=0003 SP=FFF2 SS=073F CS=073F IP=014E ADD AL,BL	BP=0000 SI=0007 DI=FFFF NV UP EI PL NZ NA PO NC
AX=000D BX=0008 DS=000F ES=FFFF 073F:0150 8804 -t	CX=0070 DX=0003 SP=FFFZ SS=073F CS=073F IP=0150 MOV [SI],AL	BP=0000 SI=0007 DI=FFFF NU UP EI PL NZ NA PO NC DS:0007=F0
AX=000D BX=0008 DS=000F ES=FFFF		BP=0000 SI=0007 DI=FFFF NV UP EI PL NZ NA PO NC

073F:0152 8AC3

MOV

AL,BL

DOSBox 0.74-3,	Cpu speed: 3000 cycles, Frame	skip 0, Progra — 🗆 🗙
AX=0002 BX=0001 DS=000F ES=FFFF 073F:0150 8804 -t	CX=0070 DX=0007 SP=FFF2 SS=073F CS=073F IP=0150 MOU [SI],AL	BP=0000 SI=0003 DI=FFFF NV UP EI PL NZ NA PO NC DS:0003=F0
AX=0002 BX=0001 DS=000F ES=FFFF 973F:0152 8AC3 -t		
AX=0001 BX=0001 DS=000F ES=FFFF 973F:0154 8A1C -t	CX=0070 DX=0007 SP=FFF2 SS=073F CS=073F IP=0154 MOV BL,[SI]	BP=0000 SI=0003 DI=FFFF NV UP EI PL NZ NA PO NC DS:0003=02
AX=0001 BX=0002 DS=000F ES=FFFF 973F:0156 4A -t	CX=0070 DX=0007 SP=FFF2 SS=073F CS=073F IP=0156 DEC DX	BP=0000 SI=0003 DI=FFFF NV UP EI PL NZ NA PO NC
AX=0001 BX=0002 DS=000F ES=FFFF 973F:0157 75F4	CX=0070 DX=0006 SP=FFF2 SS=073F CS=073F IP=0157 JNZ 014D	
B DOSBox 0.74-3,	Cpu speed: 3000 cycles, Frames	skip 0, Progra – 🗆 🗙
AX=0001 BX=0001 DS=000F ES=FFFF 073F:0154 8A1C -t	CX=0070 DX=0008 SP=FFF2 SS=073F CS=073F IP=0154 MOV BL,[SI]	
AX=0001 BX=0001 DS=000F ES=FFFF 073F:0156 4A -t	CX=0070 DX=0008 SP=FFF2 SS=073F CS=073F IP=0156 DEC DX	BP=0000 SI=0002 DI=FFFF NU UP EI PL NZ NA PO NC
AX=0001 BX=0001 DS=000F ES=FFFF 073F:0157 75F4 -t	CX=0070 DX=0007 SP=FFF2 SS=073F CS=073F IP=0157 JNZ 014D	
	CX=0070 DX=0007 SP=FFF2 SS=073F CS=073F IP=014D INC SI	BP=0000 SI=0002 DI=FFFF NV UP EI PL NZ NA PO NC
	CX=0070 DX=0007 SP=FFF2 SS=073F CS=073F IP=014E ADD AL,BL	

DOSBox 0.74-3,	Cpu speed: 3000 cycles, Frame	skip 0, Progra — 🗆 🗙
AX=0000 BX=0001 DS=000F ES=FFFF 073F:014B 881C -t		BP=0000 SI=0001 DI=FFFF NU UP EI PL NZ NA PO NC DS:0001=10
AX=0000 BX=0001 DS=000F ES=FFFF 073F:014D 46 -t		BP=0000 SI=0001 DI=FFFF NU UP EI PL NZ NA PO NC
AX=0000 BX=0001 DS=000F ES=FFFF 073F:014E 02C3 -t		BP=0000 SI=0002 DI=FFFF NU UP EI PL NZ NA PO NC
AX=0001 BX=0001 DS=000F ES=FFFF 073F:0150 8804 -t	CX=0070 DX=0008 SP=FFFZ SS=073F CS=073F IP=0150 MOV [SI],AL	BP=0000 SI=0002 DI=FFFF NU UP EI PL NZ NA PO NC DS:0002=00
AX=0001 BX=0001 DS=000F ES=FFFF 073F:0152 8AC3 T-		BP=0000 SI=0002 DI=FFFF NU UP EI PL NZ NA PO NC
BB DOSBox 0.74-3,	Cpu speed: 3000 cycles, Frame	skip 0, Progra — 🗆 🗙
AX=000F BX=0000 DS=000F ES=FFFF 073F:0141 BA0800 -t	CX=0070 DX=0000 SP=FFFZ SS=073F CS=073F IP=0141 MOV DX,0008	BP=0000 SI=0000 DI=FFFF NU UP EI PL NZ NA PO NC
AX=000F BX=0000 DS=000F ES=FFFF 073F:0144 B000 -t	CX=0070 DX=0008 SP=FFF2 SS=073F CS=073F IP=0144 MOV AL,00	BP=0000 SI=0000 DI=FFFF NU UP EI PL NZ NA PO NC
AX=0000 BX=0000 DS=000F ES=FFFF 073F:0146 B301 -t	CX=0070 DX=0008 SP=FFF2 SS=073F CS=073F IP=0146 MOV BL,01	BP=0000 SI=0000 DI=FFFF NV UP EI PL NZ NA PO NC
AX=0000 BX=0001 DS=000F ES=FFFF 073F:0148 8804 -t	CX=0070 DX=0008 SP=FFFZ SS=073F CS=073F IP=0148 MOV [SI],AL	BP=0000 SI=0000 DI=FFFF NV UP EI PL NZ NA PO NC DS:0000=60
AX=0000 BX=0001 DS=000F ES=FFFF		BP=0000 SI=0000 DI=FFFF NU UP EI PL NZ NA PO NC

073F:014A 46

INC

SI

₩ DOSBox 0.74-3,	Cpu speed: 3000 cycles, Frameskip 0, Progra — X
AX=0043 BX=0000 DS=073F ES=0000 D73F:011F 0000 -t	CX=0070 DX=0000 SP=FFF0 BP=0001 SI=0000 DI=FFFF SS=073F CS=073F IP=011F NV UP EI PL ZR NA PE NC ADD [BX+SI],AL DS:0000=CD
AX=0043 BX=0000 DS=073F ES=0000 D73F:0121 0201 -t	CX=0070 DX=0000 SP=FFF0 BP=0001 SI=0000 DI=FFFF SS=073F CS=073F IP=0121 NV UP EI PL NZ AC PO CY ADD AL,[BX+DI] DS:FFFF=00
AX=0043 BX=0000 DS=073F ES=0000 973F:0123 01FD -t	CX=0070 DX=0000 SP=FFF0 BP=0001 SI=0000 DI=FFFF SS=073F CS=073F IP=0123 NV UP EI PL NZ NA PO NC ADD BP,DI
AX=0043 BX=0000 DS=073F ES=0000 973F:0125 98 -t	CX=0070 DX=0000 SP=FFF0 BP=0000 SI=0000 DI=FFFF SS=073F CS=073F IP=0125 NV UP EI PL ZR AC PE CY CBW
AX=0043 BX=0000 DS=073F ES=0000 973F:0126 07	
BOSBox 0.74-3,	Cpu speed: 3000 cycles, Frameskip 0, Progra — 🗆 🗙
AX=0043 BX=0000 DS=073F ES=0000 073F:0117 4F -t	
AX=0043 BX=0000 DS=073F ES=0000 073F:0118 44 -t	
	CX=0070 DX=0000 SP=0000 BP=0000 SI=0000 DI=FFFF SS=073F CS=073F IP=0119 NV UP EI PL ZR AC PE NC INC BP
	CX=0070 DX=0000 SP=0000 BP=0001 SI=0000 DI=FFFF SS=073F CS=073F IP=011A NV UP EI PL NZ NA PO NC O AND [BX+SI+0007],BX DS:0007=ADFF
	CX=0070 DX=0000 SP=0000 BP=0001 SI=0000 DI=FFFF SS=073F CS=073F IP=011E NV UP EI PL ZR NA PE NC DB 60

BB DOSBox 0.74-3,	Cpu speed: 3000 cycles, Frame	eskip 0, Progra — 🗆 🗙
AX=0000 BX=0000 DS=073F ES=0000 073F:0111 44 -t		BP=0000 SI=0000 DI=0000 NV UP EI NG NZ NA PO NC
AX=0000 BX=0000 DS=073F ES=0000 073F:0112 41 -t		BP=0000 SI=0000 DI=0000 NV UP EI PL NZ NA PO NC
AX=0000 BX=0000 DS=073F ES=0000 073F:0113 54 -t		BP=0000 SI=0000 DI=0000 NV UP EI PL NZ NA PE NC
AX=0000 BX=0000 DS=073F ES=0000 073F:0114 41 -t		
AX=0000 BX=0000 DS=073F ES=0000 073F:0115 0443	SS=073F CS=073F IP=0115 ADD AL,43	NV UP EI PL NZ AC PO NC
Billion DOSBox 0.74-3,	Cpu speed: 3000 cycles, Frame	eskip 0, Progra — 🗆 🗙
AX=0000 BX=0000 DS=073F ES=073F 073F:0103 07 -t	CX=006E DX=0000 SP=00FD SS=073F CS=073F IP=0103 POP ES	
AX=0000 BX=0000 DS=073F ES=0000 073F:0104 66 -t		
AX=0000 BX=0000 DS=073F ES=0000 073F:010C 96 -t		BP=0000 SI=0000 DI=0000 NV UP EI NG NZ NA PO NC
AX=0000 BX=0000 DS=073F ES=0000 073F:010D 0C00 -t		BP=0000 SI=0000 DI=0000 NV UP EI NG NZ NA PO NC
AX=0000 BX=0000 DS=073F ES=0000 073F:010F 0004 -		BP=0000 SI=0000 DI=0000 NV UP EI PL ZR NA PE NC DS:0000=CD

AX=000D BX=0001 CX=0070 DX=0000 SP=4A03 BP=0000 SI=0009 DI=FFFF

NU UP EI PL ZR NA PE NC

DS=7106 ES=7106 SS=7106 CS=F000 IP=14A5

IRET

F000:14A5 CF