```
GlobalTime < T >
+ debugPrevTime
+ uartSpinPrevTime
+ controlLoopPrevTime
+ getGlobalTimeinTicks()
+ incrementOvf()
+ aetOvf()
+ getTCNT1()
+ GlobalTime()
+ convertTicksToTimeMs()
```

+ convertTimeMsToTicks()