

TVS
MOTOSHIELD
VEHICLE HEALTH REPORT**DEALER & VEHICLE INFO**

Dealer Name: NEO MOTORS
Dealer Code: 10814
Dealer Email: neotvs@gmail.com
Variant: TVS Ronin
VIN: MD637AN11R2D01275

DIAGNOSTIC REPORT**I.Engine Management System****Active**

Vehicle Data	Min	Max	Value	Status
1. Battery Voltage	10.5 V	14.5 V	13.8 V	✓
2. Engine Temperature	65 °C	110 °C	65.66 °C	✓
3. Throttle Position Sensor	0	100	0.0	✓
4. Intake Air Pressure Sensor	3 kpa	115 kpa	3.4 kpa	✓
5. Intake Air Temperature	-40 °C	130 °C	43.6 °C	✓
6. Engine Speed	1000 rpm	2500 rpm	1643.0 rpm	✓

Input/Output Control**Result**

1. MIL Lamp	Ok
2. Fuel Pump Relay	Ok
3. Actuate Starter Relay	Ok
4. Upstream Lambda Heater	Ok

II.Anti-lock Braking System**Active**

1. Start Wheel Speed Test


Ok

III.Instrument Cluster**Active****IV.Integrated Starter Cluster****Active**

SCAN THE QR CODE TO
JOIN THE TVS RONIN CuLT



OR DOWNLOAD THE
TVS CONNECT APP




TVS
MOTOSHIELD

VEHICLE HEALTH REPORT

PHYSICAL EVALUATION	RANGE	VALUE/STATUS
1. Drive chain slackness	18-23	22
2. Front tyre pressure	25-25	25
3. Rear tyre pressure	32-32	32
4. Dip stick oil level	-	Ok
5. Clutch play	8-13	Ok



1. Drive chain
slackness




2. Front tyre pressure



3. Rear tyre pressure



4. Dip stick oil level



5. Clutch play

REPORT SUMMARY

Vehicle Health Condition

Date: 2026-03-17



Passed



#TVSMCares

Disclaimer: This is not a legal document.

Note: All parameters recorded are at the time of inspection & subjected to change based on usage and maintenance.