03.29.00.Rev.18 Release Notes

Date: 2024-05-13

Release Content

This document provides the Release Notes for **03.29.00.Rev.18** firmware version. The current release includes the firmware and software package.

Package	Version	Release date
Firmware	FMB.Ver.03.29.00.Rev.18	2023-05-13
Software	Teltonika.Configurator_1.7.72_B.3.29_R.11	2023-12-13

Key Details

Items to review before updating your devices.

Item	Description
1	 Firmware recommended for specific models and their modifications: Fast & Easy Trackers: FMT100 Basic Trackers: FMB900, FMB910, FMB920, FMC920 (EG915U-EU, EG915U-LA), FMM920 Advanced Trackers: FMB110, FMB120, FMB122, FMB130, FMC130 (SLM320-LA, SLM320-E2, EC21-EC, EC21-AU), FMC13A, FMM130 (BG95-M3, BG96), FMM13A, FMB202, FMB204, FMB206, FMB230, FMC230 (SLM320-LA, SLM320-E2), FMM230 CAN Trackers: FMB140, FMB240 Professional Trackers: FMB125, FMC125 (SLM320-LA, SLM320-E2, EC21-EC), FMM125 (BG95-M3), FMB225, FMC225 (SLM320-LA, SLM320-E2)

TELTONIKA TELEMATICS UAB Saltoniskiu st. 9B-1, LT-08105 Vilnius, Lithuania











Tel. +370 5 212 7472 Fax. +370 5 276 1380



Firmware has downgrade protection for: FMC920, FMM920, FMC130 with MeiG SLM320, FMC125 with MeiG SLM320, FMC225, FMC13A, FMM13A. • FMC130 with MeiG SLM320, FMC125 with MeiG SLM320 and FMC225 2 devices with 03.29.00.Rev.18 version cannot be downgraded to any evaluation or base versions released before 03.28.06.Rev.00! • FMC920, FMM920, FMC13A and FMM13A devices with 03.29.00.Rev.18 version cannot be downgraded to any evaluation or base versions released before **03.29.00.Rev.00**!

Recommended firmware list for other devices models and their modifications can be found in: https://wiki.teltonika-gps.com/view/Firmware_versions

TELTONIKA TELEMATICS UAB Saltoniskiu st. 9B-1, LT-08105 Vilnius, Lithuania

Registration code 305578349











www.teltonika-gps.com info@teltonika.lt

03.29.00.Rev.18 Change List

Item	Changes	Change Type
1	Improved reconnection to new operator time if GPRS was unavailable with initial operator	Stability
2	Fixed pro-longed reconnection to new operator due to record tasks interrupting operator search	Stability
3	Fixed network session closing when current operator is added to blacklist	Stability
4	Improved module initialization time for devices with Quectel modems	Stability
5	Fixed Digital Output state restore after firmware update	Stability
6	RS232 interface stability improvements	Stability
7	GNSS status element state improvements	Stability
8	Time synchronization improvements	Stability
9	Manufacture testing improvements	Stability

TELTONIKA TELEMATICS UAB Saltoniskiu st. 9B-1, LT-08105 Vilnius, Lithuania











C Tel. +370 5 212 7472 Fax. +370 5 276 1380 www.teltonika-gps.com info@teltonika.lt

03.29.00.Rev.14 Change List

Item	Changes	Change Type
1	Manufacture testing improvements	Stability

TELTONIKA TELEMATICS UAB Saltoniskiu st. 9B-1, LT-08105 Vilnius, Lithuania









03.29.00.Rev.13 Change List

Item	Changes	Change Type
1	TELTONIKA EYE Beacon and EYE Sensor easy configuration functionalities added	New feature
2	TELTONIKA EYE Beacon Lost & Found and Proximity Event functionalities added	New feature
3	SECO functionality added	New feature
4	Back-Up Tracker functionality added	New feature
5	GNSS jamming functionality added	New feature
6	Low Power Mode functionality added	New feature
7	MQTT support for <u>AWS IoT Shadow/Custom</u> and <u>Azure</u> <u>IoT</u> added	New feature
8	RS485 Buffered functionality added	New feature
9	RS232 Delimiter mode functionality added	New feature
10	1-Wire interface control in sleep modes functionality added	New feature
11	BT/BLE interface control in sleep modes functionality added	New feature
12	NBL-2 Bluetooth RFID reader support added	New feature
13	SMS/GPRS command <u>"lvcanhorn"</u> support added	New feature
14	Added support for FMC13A and FMM13A	New feature
15	Added support for <u>FMC00A</u> and <u>FMM00A</u>	New feature
16	Added support for <u>FMC920</u> and <u>FMM920</u>	New feature
17	Added support for <u>FMC003</u> and <u>FMM003</u>	New feature
18	Added support for small OBD devices FMB003 and FMB020	New feature
19	Added support for FMC1XY/FMC2XY devices with MeiG modems	New feature
20	SMS/GPRS command <u>"setigndigout"</u> added	New feature
21	Jamming feature support added for FMC1XY/FMC2XY devices with MeiG modems	New feature
22	Support of new electric vehicle <u>OEM parameters</u> for FMX00X devices	New feature
23	CAN service and LPG I/O elements added	New feature
24	New I/O elements for each CAN adapter state flag added	New feature
25	New I/O Digital Input 2 for FMX920, FMB910 and FMB900 devices.	New feature

TELTONIKA TELEMATICS UAB Saltoniskiu st. 9B-1, LT-08105 Vilnius, Lithuania











www.teltonika-gps.com info@teltonika.lt

26	Reworked recalibration logic	Rework
27	<u>Default parameter values</u>	Rework
28	SMS Event logic reworked	Rework
29	LLS address count expanded to 16	Rework
30	Black list functionality reworked	Rework
31	SMS/GPRS command <u>"cpureset"</u> protection functionality	Rework
32	<u>Pulse Counter</u> reworked	Rework
33	1-Wire Temperature sensor stability improvements	Stability
34	Operator search procedure functionality improvements	Stability
35	Record saving and sending improvements	Stability
36	DOUT state saving improvements	Stability
37	GPRS Session and PDP Context Activation logic improvements	Stability
38	Trip state saving improvements	Stability
39	CAN data reading improvements	Stability
40	BLE data reading stability improvements	Stability
41	TimeSync, SMS handling and connection stability improvements for FMC1XY/FMC2XY devices with MeiG modems	Stability
42	AutoAPN multiple block file improvement for larger database capacity	Stability
43	Manufacture testing improvements	Stability
44	Improved system stability and fixed general bugs	Stability

Information on older firmware version changes can be found in:

- For FMT100 devices: https://wiki.teltonika-gps.com/view/FMT100_firmware_errata
- For FMB900 devices: https://wiki.teltonika-gps.com/view/FMB900 firmware errata
- For FMB910 devices: https://wiki.teltonika-gps.com/view/FMB910 firmware errata
- For FMB920 devices: https://wiki.teltonika-gps.com/view/FMB920 firmware_errata
- For FMC920 devices: https://wiki.teltonika-gps.com/view/FMC920_firmware_errata
- For FMM920 devices: https://wiki.teltonika-gps.com/view/FMM920_firmware_errata
- For FMB110 devices: https://wiki.teltonika-gps.com/view/FMB110 firmware errata
- For FMB120 devices: https://wiki.teltonika-gps.com/view/FMB120 firmware errata
- For FMB122 devices: https://wiki.teltonika-gps.com/view/FMB122_firmware_errata
- For FMB130 devices: https://wiki.teltonika-gps.com/view/FMB130_firmware_errata
- For FMC130 devices: https://wiki.teltonika-gps.com/view/FMC130 firmware errata
- For FMC13A devices: https://wiki.teltonika-gps.com/view/FMC13A firmware errata
- For FMM130 devices: https://wiki.teltonika-gps.com/view/FMM130_firmware_errata

TELTONIKA TELEMATICS UAB Saltoniskiu st. 9B-1, LT-08105 Vilnius, Lithuania

















- For FMM13A devices: https://wiki.teltonika-gps.com/view/FMM13A firmware errata
- For FMB202 devices: https://wiki.teltonika-gps.com/view/FMB202 firmware errata
- For FMB204 devices: https://wiki.teltonika-gps.com/view/FMB204_firmware_errata
- For FMB206 devices: https://wiki.teltonika-gps.com/view/FMB206 firmware errata
- For FMB230 devices: https://wiki.teltonika-gps.com/view/FMB230_firmware_errata
- For FMC230 devices: https://wiki.teltonika-gps.com/view/FMBC230_firmware_errata
- For FMM230 devices: https://wiki.teltonika-gps.com/view/FMM230 firmware errata
- For FMB140 devices: https://wiki.teltonika-gps.com/view/FMB140_firmware_errata
- For FMB240 devices: https://wiki.teltonika-gps.com/view/FMB240 firmware errata
- For FMB125 devices: https://wiki.teltonika-gps.com/view/FMB125 firmware errata
- For FMC125 devices: https://wiki.teltonika-gps.com/view/FMC125 firmware errata
- For FMM125 devices: https://wiki.teltonika-gps.com/view/FMM125 firmware errata
- For FMB225 devices: https://wiki.teltonika-gps.com/view/FMB125_firmware_errata
- For FMC225 devices: https://wiki.teltonika-gps.com/view/FMC125_firmware_errata

For any additional questions on firmware updates and changes, please make sure to contact your Teltonika sales representative or create a consultation ticket for Teltonika support via Helpdesk system.

TELTONIKA TELEMATICS UAB Saltoniskiu st. 9B-1, LT-08105 Vilnius, Lithuania







