Lab C

Test	Х	у	sel	Carry	Overflow	Sum	Carry	Overflow	Sum	Pass
ID				Out	Expected	Expected	Out	Observed	observed	or
				Expected			Observed			Fail
1	6'b00_0001	6'b00_0100	0	1'b0	1'b0	6'b00_0101	1'b0	1'b0	6'b00_0101	Pass
2	6'b00_0000	6'b00_0000	0	1'b0	1'b0	6'b00_0000	1'b0	1'b0	6'b00_0000	Pass
3	6'b00_0001	6'b00_0100	1	1'b0	1'b0	6'b11_1101	1'b0	1'b0	6'b11_1101	Pass
4	6'b00_0000	6'b00_0000	1	1'b1	1'b0	6'b00_0000	1'b1	1'b0	6'b00_0000	Pass
5	6'b11_1111	6'b00_0001	0	1'b1	1'b0	6'b00_0000	1'b1	1'b0	6'b00_0000	Pass
6	6'b11_1111	6'b00_0001	1	1'b1	1'b0	6'b11_1110	1'b1	1'b0	6'b11_1110	Pass
7	6'b01_0000	6'b01_0000	0	1'b0	1'b1	6'b10_0000	1'b0	1'b1	6'b10_0000	Pass
8	6'b11_1000	6'b10_0111	0	1'b1	1'b1	6'b01_1111	1'b1	1'b1	6'b01_1111	Pass