Light Curtain Override









STEP	ACTION
1	Turn the override key all the way to the right for a second then release. It should spring back to its rest position. Key is located on HMI .
2	Reset the safety zones at the relevant Gate Post.
3	Start All from the Gate Post or START ALL on HMI control screen

This process is done when the light curtain has been tripped.