Claim assessment

ESTIMATE FOR REVIEW - not a settlement or proof of insurer approval

SYNTHETIC TEST FIXTURE - simulated assessment; not real damage evidence.

Claim	DEMO-001
Vehicle	Maruti Suzuki Swift / ****0000
Policy	**********0001 | 2026-01-01 to 2026-12-31
Accident date	2026-10-23
Review	Audit: pass | Decision: approved

Incident

Hit a pole while parking; front bumper and right headlamp were damaged.

Estimated payout

Part / action	Parts price	Labour range	Depreciation	Payable range
front_bumper / replace Section I(vi)	INR 2,250.00	INR 600.00 to INR 1,000.00	50% INR 1,125.00	INR 1,725.00 to INR 2,125.00
headlamp / replace Section I(vi)	INR 2,999.00	INR 250.00 to INR 450.00	50% INR 1,499.50	INR 1,749.50 to INR 1,949.50

Gross: INR 6,099.00 - INR 6,699.00
Depreciation: INR 2,624.50 | Deductible: INR 1,000.00
Estimated payable: INR 2,474.50 - INR 3,074.50
Labour rates are assumptions. Catalogue fitment, policy endorsements and final admissibility require verification. Line payable amounts are before the claim-level deductible.

Coverage & evidence references

1. front_bumper | Section I(vi)

Evidence: photo-1 | Coverage: covered
Policy excerpt: by accidental external means;
Synthetic scenario assumes admissible accidental external damage.
Labour is an assumption; painting excluded from this fixture. Swift 2017-2024; confirm variant and VIN
Parts source: https://www.marutisuzuki.com/genuine-parts/front-bumper/71711m55r00-5pk

2. headlamp | Section I(vi)

Evidence: photo-1 | Coverage: covered
Policy excerpt: by accidental external means;
Synthetic scenario assumes admissible accidental external damage.
Labour is an assumption; painting excluded from this fixture. Right halogen assembly; selected Swift 2017-2022 variants; confirm VIN
Parts source: https://www.marutisuzuki.com/genuine-parts/head-lamp-assembly-right/35100m55r10

Auditor findings

A1 / PASS: Capture date matches the accident date and policy period.
A2 / PASS: No matching image in the prior-claim fixture index.
A3 / PASS: Fixture plate matches the supplied vehicle record.
A4 / PASS: Incident location agrees with the fixture damage labels.
A5 / PASS: Each estimate line has evidence and a coverage decision.
A6 / PASS: Fixture confidence is above 0.6; no structural damage is specified.

Policy source

Royal Sundaram Stand-Alone Motor Own Damage Policy - Private Car, Rev 2023. Section I: accidental external means, replacement-part depreciation and exclusions.
https://www.royalsundaram.in/assets/standalone-motor-own-damage-policy-private-car-rev2023.pdf