Claim assessment

ESTIMATE FOR REVIEW - not a settlement or proof of insurer approval

SYNTHETIC TEST FIXTURE - simulated assessment; not real damage evidence.

Claim	DEMO-002
Vehicle	Maruti Suzuki Baleno / ****0000
Policy	**********0001 | 2026-01-01 to 2026-12-31
Accident date	2026-10-23
Review	Audit: pass | Decision: approved

Incident

A low-speed rear impact damaged my bumper and left tail lamp. I also reported engine noise.

Estimated payout

Part / action	Parts price	Labour range	Depreciation	Payable range
rear_bumper / replace Section I(vi)	INR 4,100.00	INR 600.00 to INR 1,000.00	50% INR 2,050.00	INR 2,650.00 to INR 3,050.00
tail_lamp / replace Section I(vi)	INR 4,699.00	INR 250.00 to INR 450.00	50% INR 2,349.50	INR 2,599.50 to INR 2,799.50

Gross: INR 9,649.00 - INR 10,249.00
Depreciation: INR 4,399.50 | Deductible: INR 1,000.00
Estimated payable: INR 4,249.50 - INR 4,849.50
Labour rates are assumptions. Catalogue fitment, policy endorsements and final admissibility require verification. Line payable amounts are before the claim-level deductible.

Coverage & evidence references

1. rear_bumper | Section I(vi)

Evidence: photo-1 | Coverage: covered
Policy excerpt: by accidental external means;
Synthetic scenario assumes admissible accidental external damage.
Labour is an assumption; painting excluded from this fixture. Demo fitment assumption Baleno 2022 onwards; product page omits fitment so confirm VIN; alternate short URL shows 4056
Parts source: https://www.marutisuzuki.com/genuine-parts/bumper-rear-black/71811m55t00-5pk

2. tail_lamp | Section I(vi)

Evidence: photo-1 | Coverage: covered
Policy excerpt: by accidental external means;
Synthetic scenario assumes admissible accidental external damage.
Labour is an assumption; painting excluded from this fixture. Left lamp; Baleno 2022 onwards; confirm VIN
Parts source: https://www.marutisuzuki.com/genuine-parts/tail-lamp-left/35750m55t12

engine_noise: not_covered / Section I - exclusion (a)

Fixture assumption: inspection attributes engine noise to pre-existing mechanical breakdown, not the impact. Real causation requires a surveyor.

Auditor findings

A1 / PASS: Capture date matches the accident date and policy period.
A2 / PASS: No matching image in the prior-claim fixture index.
A3 / PASS: Fixture plate matches the supplied vehicle record.
A4 / PASS: Incident location agrees with the fixture damage labels.
A5 / PASS: Each estimate line has evidence and a coverage decision.
A6 / PASS: Fixture confidence is above 0.6; no structural damage is specified.

Policy source

Royal Sundaram Stand-Alone Motor Own Damage Policy - Private Car, Rev 2023. Section I: accidental external means, replacement-part depreciation and exclusions.
https://www.royalsundaram.in/assets/standalone-motor-own-damage-policy-private-car-rev2023.pdf