

```

#define LDR A0
#define IR 4
#define LED 5

int ldrValue;
int irValue;

void setup()
{
  pinMode(IR, INPUT);
  pinMode(LED, OUTPUT);

  Serial.begin(9600);
}

void loop()
{
  ldrValue = analogRead(LDR);    // Read light intensity
  irValue = digitalRead(IR);     // Read IR sensor

  Serial.print("LDR Value: ");
  Serial.println(ldrValue);

  if(irValue == LOW)    // Object detected (most IR sensors give LOW)
  {
    if(ldrValue < 500)    // Dark condition
    {
      analogWrite(LED,255); // LED Bright
    }
    else
    {
      analogWrite(LED,80); // LED Dim
    }
  }
  else
  {
    analogWrite(LED,0); // LED OFF
  }

  delay(200);
}

```