TABLE OF CONTENTS

LOG OF REVISIONS
TABLE OF CONTENTS 2
AIRWORTHINESS LIMITATIONS SECTION 3
Section 01 – Introduction 4
Scope 5
Service Difficulties 5
Applicability 5
Language 5
Units of Measure 5
Torque Values 5
Abbreviations and Definitions 5
Revision to ICA 5
Change Bars 6
Section 02 – System Description 6
Parts List 6
Section 03 – Inspection Requirements 6
Description 7
Inspection Program 7
Daily Inspection Program 7
Annual Inspection Program 7
Conditional Inspection Checks 7
Special Inspection Requirements 7
Section 04 - Weight and Balance 7
Weight and Balance information 8
Section 05 - Placards and Markings 8
Placards 8
Markings 8
Section 06 – Servicing 8
Maintenance Support Equipment 8
Consumable Material 8
Routine Cleaning 8
Application of Protective Treatment 8
Recommended Overhaul Period 8
Servicing Information 9
Section 07 – System Maintenance 9
Control and Operation 9
Installation Instructions 9
Removal Instructions 9
Repairs 9

Section 01 – Introduction

Scope

This manual contains the necessary information for carrying out ongoing maintenance and inspections on the Aft Fuselage Inspection Panels installed in Cessna 180, 182, 185, and 188 airplane in accordance with Supplemental Type Certificate (STC) SA00858DE. Physical modifications associated to this STC include the installation of two inspection panels and two doublers installed in the aft fuselage.

Service Difficulties

Report service difficulties with the Cessna 180, 182, 185, and 188 Aft Fuselage Inspection Panel modification to:

Aeropod Inc.
18961 East Kent Circle
Aurora, Colorado 80013
aeropodinc@gmail.com
720-220-8969 303-888-2728

Applicability

This document applies to Cessna 180, 182, 185, and 188 airplanes with STC SA00858DE installed.

Language

This manual is written to the Simplified English (SE) specification. This International Aerospace Maintenance Language Specification is important to maintenance personnel whose first language is not English.

Units of Measure

Unless otherwise noted, measurements throughout this manual are shown in American Standard unit.
Example: 12.55 in

Torque Values

No unique torque values apply to this modification.

Abbreviations and Definitions

ACO	Aircraft Certification Office
FAA	Federal Aviation Administration
CFR	Code of Federal Regulation
ICA	Instructions for Continued Airworthiness
STC	Supplemental Type Certificate

Section 03 – Inspection Requirements

Description

This Section contains the inspection requirements for the Aft Fuselage Inspection Panels modification on Cessna 180, 182, 185, or 188 airplanes in accordance with STC SA00858DE. The inspections must be accomplished by qualified personnel to ascertain the airworthiness of the airplane, and any discrepancy must be eliminated prior to further flight. No component overhaul is required for this STC.

Inspection Program

The inspection program consists of an annual inspection for condition of the panels, doublers, hardware, and structure surrounding the installed panels.

Daily Inspection Program

No daily inspections required.

Annual Inspection Program

During annual inspection, or at an annual interval, perform the following inspections.

1. Inspect the panels for dents, nicks, deformation, cracks, and overall fit on the airframe
2. Inspect the doubler for dents, nicks, deformation, cracks, fit, and security in the airframe.
3. Inspect all hardware for condition.

Conditional Inspection Checks

A conditional inspection/check does not occur at a specified time. It is caused by known or suspected unusual events, malfunctions, or defects.

Inspect the installation in accordance with the Annual Inspection Program in above in the event of a hard landing.

Special Inspection Requirements

There are no special inspection requirements.

Servicing Information

There are no servicing requirements or procedures associated with the components of this document. In the event of failure, contact Aeropod Inc.

Section 07 – System Maintenance

Control and Operation

Not applicable, the placard has no control or operation aspects.

Installation Instructions

Installation of the *Aft Fuselage Inspection Panels* modification is provided by the Aeropod Drawing AP0712057-KIT.

Removal Instructions

Removal of the will *Aft Fuselage Inspection Panels* will require replacement of the upper skin between station 172-209 (Cessna 180/182/185 models) or station 175-212 (Cessna 188 model). Alternatively a patch could be fabricated however the installer may need to seek further FAA approval.

Repairs

Please report any failures or needs for repairs to Aeropod Inc. No special procedures for repairs are required for this modification beyond those listed in the Cessna service manual applicable to the aircraft and AC 43.13-1B.

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. Description of Work Accomplished
(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

N9248C	10/12/2024
Nationality and Registration Mark	Date

Installed Aeropod, Inc left and right aft inspection panels per Supplemental Type Certificate SA00858DE. Installation was accomplished in accordance with Aeropod, Inc master drawing list, document number AP-0005-MDL, revision IR, dated January 20, 2017.

All riveting was accomplished using standard practices, as outlined in AC 43.13-1 B, Chapter 4—section 4, Chapter 7, and Chapter 17 of the Cessna service manual.

Instructions for Continued airworthiness to be accomplished in accordance with the manufacturer's instructions for Continued Airworthiness as presented in document AP0712057-ICA

Weight and Balance change negligible.

----------END----------

☐ Additional Sheets Are Attached