## Aircraft Discrepancy and Deferral Record - Hera Flight

**DISCREPANCY:** Complete this section when an aircraft discrepancy is noted.

| | |
|---|---|
| N # 976JS | Description of discrepancy Aircraft did not properly pressurize. On climbout from KDEN, got "CABIN ALTITUDE" Amber annunciator at approx 10,000'. At approx 14,000' got "CABIN ALTITUDE" Red annunciator in addition. Levelled at FL 190 to troubleshoot. Large and small arrows paired at 10,000' cabin alt, approx 3 PSI. After checklist procedures, climbed to FL 230 with same result. Returned KDEN. Red annunciator extinguished approx 14,000'; Amber extinguished approx 10,000'. |
| Date discovered 12/18/24 | |
| Flight hours 6286.3 | Name of person reporting discrepancy TERRENCE PEACOCK |

**CIRCLE ONE:** ***MEL*** **OR** ***NEF***

**DEFERRAL:** Complete this section only if the discrepancy is to be deferred under the provisions of an MEL. A decal or other document containing the same information may be attached to this form.

| | |
|---|---|
| MEL item # | Maintenance action taken, if applicable: |
| MEL category | Name and certificate # of technician or pilot deferring item |
| Deferral expires | Signature, date, and certificate |

**CORRECTIVE ACTION:** Complete this section only if the discrepancy is to be repaired. A decal or other document containing the same information may be attached to this form.

Maintenance action taken: Troubleshot aircraft not pressurizing correctly in Auto mode issue in reference to Cessna 750 AM chapter 21-30-00. No faults found.

The undersigned certifies that the aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired in accordance with current Regulations (including those of CFR 135 under which this aircraft operates) of the Federal Aviation Administration and is approved for return to service. All items required to be inspected were inspected by an authorized person who determined that the work is satisfactorily completed.

| | |
|---|---|
| Date of repair 12/18/24 | Name and certificate # of technician performing work Nate Acuna CRS K55R339N |
| Flight hours 6286.3 | Signature, date, and repair station # CRS K55R339N |

| | | |
|---|---|---|
| **Rev: 2** | **Form M-103** | **Date: 11/06/2024** |