Log Book Entry

ELEVATE MRO
AN ELEVATE AVIATION GROUP COMPANY

237 N 2370 W
Salt Lake City, UT 84116
United States

Telephone: +1 (385) 509-3780 Fax:

28 September, 2024

Registration #: N962JX
Manufacturer: Embraer
Part/Model number: EMB-145LR
Work Order No: SLC-MX695

Total AC Time: 42,913.15 **Total AC Cycles:** 33,388
Aircraft Serial Number: 145618
Date: 28-Sep-2024

Squawk

2.1 Performed Line Service Check in reference to JSX line service checklist CUS-0004.

2.2 Performed external walk-around in reference to JSX line service checklist CUS-004.

2.3 Inspected NLG wheels and tires in reference to Embraer 145 AMM 32-49-05-200-801-A, and AMM 32-49-04-200-802-A.

2.4 Performed right MLG brake wear indicators inspection in reference to Embraer 145 AMM 32-49-03-200-801-A.

2.5 Performed right MLG wheels and tires inspection in reference to Embraer 145 AMM 32-49-02-200-801 b, and 32-49-01-200-802-A i. Both RH tires are below 1/32" in areas but above flush, per JSX CUS-0004 line service check it can be defered for 10 cycles or replaced at next RON whichever comes first. Deferal iii filled out by Luis at JSX MX Control.

2.6 Checked RH engine oil in reference to AE 3007A EMM 12-10-79-600-801. No oil needed.

2.7 Checked APU engine oil as needed in reference to JSX Line Service Check CUS-0004. No oil needed.

2.8 Checked LH engine oil in reference to AE 3007A EMM 12-10-79-600-801. No oil needed.

2.9 Performed left MLG brake wear indicators inspection in reference to Embraer 145 AMM 32-49-03-200-801-A 8. a.

2.10 Performed Left MLG wheels and tires inspection in reference to Embraer 145 AMM 32-49-02-200-801 b, and 32-49-01-200-802-A i.

2.11 Performed Hydraulic Quantity inspection in reference to JSX Line Service Check CUS-0004. Level shows full at present time.

2.12 Inspected crew oxygen pressure (1750psi) in reference to Embraer AMM 12-14-00-600-801.

2.13 Inspected RH, and LH MLG tire inflation pressure (177psi) in reference to Embraer AMM 32-49-01-610-001-A00.

2.14 Inspected NLG tire inflation pressure (107psi) in reference to Embraer AMM 32-49-04-610-001-A00.

I certify the airframe, engine and/or compentnt identified herin was repaired in accordance with the current Elevate MRO Repair Station Manual System and the Federal Aviation Regulations under which the operator is certified and was determined to be in an airworthy Condition at this date and time with regards to the inspections(s) aleterations and/or maintenance performed, and is approved for return to service as per those requirements. Pertinent details of the repari(s) are on file at this facility.

Samuel I. Perez Baptista
FAA CRS K5SR339N _____ 28/09/2024.

These items identified above were repaired and/or inspected in accordance with current Federal Aviation Regulations and the repairs are approved for return to service. Pertinent details of these repairs are on file at the repair station under Work Order Number SLC-MX695.

*** End of Document ***

JSX

5616 Haven St. Suite A, ATTN: JSX PARTS
Las Vegas, NV, US, 89119
AMO: Attn. Parts

N962JX
EMB-145LR
SN 145618

Work Order / Plan No. SLC-MX695
Service Center Elevate MRO

CUS-0004 **A/F (145618)**

Line Service Check

5 - Inspection (AVG MAN HRS: 2)

Task: - Req: JSX
1. RE 2 Days

Requirement	Due
2 Days	27-Sep-2024
Hrs	
Ldg	

Accepted Technical Publications Status: No technical publications attached
Zone: , Access:

Compliance A/F (145618)	Days	Hrs	Ldg	Other
	28 09 2024	42913.15	33,388	

Task Findings:

- [x] Satisfactory
- [ ] Unsatisfactory
- [ ] Damage
- [ ] Corrosion Lvl. 1
- [ ] No fault Found
- [ ] Fault Found
- [ ] Leak
- [ ] Corrosion Lvl. 2
- [ ] Within Limits
- [ ] Outside Limits
- [ ] Requires Rewor
- [ ] Corrosion Lvl. 3
- [ ] Other:

TSI
Days
Hrs
Ldg

Compliance Notes:

Cost

Man Hrs.

Associated Tasks

Task Number / Description ATA Major Assembly	PN	SN	Requirement	**Due** Association Type
CUS-0004 Line Service Check + TPC checks combined 5 A/F			1. RE A/R	Compliance Share Double

Technician Name: Samuel King
License K5SR339N Signature Samuel King

Inspector Name: Samuel I. Perez Baptista
License FAACRSK5SRB39N Signature

JSX

5616 Haven St. Suite A, ATTN: JSX PARTS
Las Vegas, NV, US, 89119
AMO: Attn. Parts

N962JX
EMB-145LR
SN 145618

Work Order / Plan No. SLC-MX695
Service Center Elevate MRO

CUS-0004 - Line Service Check + TPC checks combined (Continued)

Checklist

CUS-0004 **1. RE A/R**
Line Service Check + TPC checks combined

Step info		Complete
11	**Crew Oxygen** a. Visually check crew oxygen pressure is above 1600 PSI. i. System above 1600 (Check) Yes 1750 No_____ ii. If system is below 1600 PSI, service crew oxygen pressure to 1850 psi per AMM Task 12-14- 00-600-801. If servicing is required, make an Aircraft Discrepancy Log entry.	SK ☑
12	**Left and Right MLG Tire Inflation Pressure** MRB Task 32-49-01-610-001-A00 LANDING GEAR - Check MLG Tire Inflation Pressure - [SVC] If tires are serviced, make an entry in Traxxall documenting original tire pressure and adjusted tire pressure.	SK ☑
13	**NLG Tire Inlation Pressure** MRB Task 32-49-04-610-001-A00 LANDING GEAR - Check NLG Tire Inflation Pressure - [SVC] If tires are serviced, make an entry in Traxxall documenting original tire pressure and adjusted tire pressure.	SK ☑
14	**FINAL** a. Audit Work Card to ensure header information is complete and all line items are initialed. The technician completing the Line service check shall enter his/her signature, printed name, cert type and number, initials and date below. If more than one technician has completed the line service check please enter their information in the additional lines. b. Document accomplishment of Service Check in the Aircraft Discrepancy Log Block 2 "Line Service Check" section. Enter Signature, Cert type & number, Date & time, and airframe time.	SK ☑

Accepted Technical Publications Status: No technical publications attached
Zone: , Access:

Compliance A/F (145618)	Mos	28 09 2024	Hrs	42,913.15	Ldg	33,388	Other	

Compliance Notes:

Cost

Man Hrs.

Technician Name: Samuel King
License K5SR 339N Signature Samuel King

Inspector Name: Samuel I. Perez Bautista
License PAA K5S R339N Signature