Log Book Entry

ELEVATE MRO
- AN ELEVATE AVIATION GROUP COMPANY -

'7 N 2370 W
alt Lake City, UT 84116
United States

Telephone: +1 (385) 509-3780 Fax:

03 September, 2024

Registration #: N120GF **Total AC Time:** 450.3 **Total AC Cycles:** 312
Manufacturer: Honda Aircraft Company, LLC (V)
Part/Model number: HA-420 **Aircraft Serial Number:** 42000232
Work Order No: SLC-MX641 **Date:** 03-Sep-2024

Squawk

2.1 24CA2430013 No. 1 Main Ship Battery (Lead Acid) Capacity Check: Removed battery PN RG-145-1 SN 41188186. Installed new battery PN RG-145-1 SN 41344701 in reference to the HA-420 AMM 24-31-11-000/400-802.

2.2 24CA2430013 No. 2 Main Ship Battery (Lead Acid) Capacity Check: Removed battery PN RG-390ES SN 41229409. Installed new battery PN RG-390ES SN 41229410 in reference to the HA-420 AMM 24-31-11-000/400-802.

2.3 25HA2563062 Emergency Locator Transmitter Self-Test (ELT): Complied with in reference to the HA-420 AMM 25-60-01-700-801.

2.4 27CA2751040 Left Wing Inboard Flap Pushrod - Inspect and Apply Corrosion Inhibiting Compound to the Internal Diameter of Flap Pushrod: Complied with in reference to the HA-420 AMM 20-13-19-910-801.

2.5 27CA2751041 Right Wing Inboard Flap Pushrod - Inspect and Apply Corrosion Inhibiting Compound to the Internal Diameter of Flap Pushrod: Complied with in reference to the HA-420 AMM 20-13-19-910-801.

2.6 27CA2751042 Left Wing Outboard Flap Pushrod - Inspect and Apply Corrosion Inhibiting Compound to the Internal Diameter of Flap Pushrod: Complied with in reference to the HA-420 AMM 20-13-19-910-801.

2.7 27CA2751043 Right Wing Outboard Flap Pushrod - Inspect and Apply Corrosion Inhibiting Compound to the Internal Diameter of Flap Pushrod: Complied with in reference to the HA-420 AMM 20-13-19-910-801.

I certify the airframe, engine and/or component identified herein was repaired and inspected in accordance with the current Elevate MRO Repair Manual System and the Federal Aviation Regulations under which the operator is certified, and was determined to be in an Airworthy Condition at this date and time with regards to the inspection(s) alterations and/or maintenance performed, and is approved for return to service as per those requirements. Pertinent details of the repair(s) are on file at this facility.

Anders Struve
CRS No. K5SR339N

Signature

These items identified above were repaired and/or inspected in accordance with current Federal Aviation Regulations and the repairs are approved for return to service. Pertinent details of these repairs are on file at the repair station under Work Order Number SLC-MX641.